
REVISION HISTORY

4. Change R1 to 4.7K. Soil sensor is not I2C so reroute to D10 and D11. Add 10K pull—up to Soil.SDA. Improve labels on library for Feature M0 assembly to make the pre—defined pins easier to understand. Make a new library shape for Catena 4410, since that's what this is. Change P3 and P5 to match as—built



www.mcci.com Prototype Soil + Pond Sensor MCCI Corporation Sheet: / File: greenhouse.sch Title: greenhouse.sch Date: 2016-10-11 Rev: 4

Size: B Date: 2016-10 KiCad E.D.A. kicad 4.0.2-stable ld: 1/1