


Case 1 control
Rectangle, uniform mesh
(control)
1784 triangles, total work 1784




Case 2 main
L-plate, one heat source
(main)
1670 triangles, total work 1670




Case 3 hard
L-plate, two heat sources
(hard)
1802 triangles, total work 1802




Case 4 structural
Plate with a hole under
tension (structural)
2166 triangles, total work 2166




Case 5 L uniform
L-plate, uniform mesh
(easiest)
1724 triangles, total work 1724




Case 6 three sources
+ three heat sources (1.0 /
0.7 / 0.4)
1996 triangles, total work 1996




Case 7 materials
+ heavy-material zone (3x work
per triangle)
1996 triangles, total work 2782



Case 8 coupling
+ strong-coupling zone
(borders cost 3x)
1996 triangles, total work 2782



Case 9 priority
+ priority zone (prefers the
fast device)
1996 triangles, total work 2782



mesh triangle edges
removed corner / hole
heat source (strength)
heavy material: 3x work
strong coupling: borders cost 3x
priority zone
uniform pull (case 4)