
CORRIE F rev 3 Step 1: pockets (FP hip-reach, IMP-4, IMP-8, IMP-2 sleeve, F-02 + B-16 flo

Paper: LETTER 215.9 x 279.4 mm, 7 rows x 5 cols = 35 tiles (+ this map = 36 pages).

Print at 100% / ACTUAL SIZE (no 'fit to page'). Verify the 100 mm and 4 in squares.


Assemble: rows A.. top to bottom, columns 1.. left to right; overlap 12 mm.


Lines: solid = CUT, grey dashed = SEW, red = notches, blue arrow = grain, circle+cross = drill hole.



100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

Measure: must be exactly 100 mm / 4 in


ID: F-02
PIECE: fly base pocket
MATERIAL: cordura_330d_nylon66
CUT 1
FACE UP
KNIFE: CW from the grain-arrow head; cut windows and slits first
NOTE: see NOTES page (F-02)
PACK: 5200 CORRIE F rev 3
FACE: PU coat DOWN (inside)
A2 >
100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)
A2 >
Measure: must be exactly 100 mm / 4 in
v B1
v B1


< A1
A3 >
lits first
ID: B-16
PIECE: under-strap floor c
MATERIAL: cordura_500c
CUT 2
FACE UP
KNIFE: CW from the grain
NOTE: see NOTES page
PACK: 5200 CORRIE F re
FACE: PU coat DOWN (in
100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)
< A1
A3 >
Measure: must be exactly 100 mm / 4 in
v B2
v B2

PRINT AT 100% ACTUAL SIZE — check test square

< A2

A4 >

ap floor channel (US1 / US2)
ura_500d_nylon66

the grain-arrow head; cut windows and slits first
ES page (B-16)
RRIE F rev 3
OWN (inside)

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

< A2

A4 >

Measure: must be exactly 100 mm / 4 in

v B3

v B3

Trim neighbour page on its border; align to dashed line; match diamonds.

< A3

A5 >

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

< A3

A5 >

Measure: must be exactly 100 mm / 4 in

v B4

v B4

< A4


100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

< A4

Measure: must be exactly 100 mm / 4 in

v B5

v B5


^ A1
^ A1
B2 >
B2 >
100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)
Measure: must be exactly 100 mm / 4 in
v C1
v C1

^ A2

^ A2

< B1

B3 >

ID: B-09c
PIECE: hydration sleeve (folded tube, one side seam)
MATERIAL: robic_100d_ripstop
CUT 1
FACE UP
KNIFE: CW from the grain-arrow head; cut windows and slits first
PACK: 5200 CORRIE F rev 3
FACE: coated side DOWN (inside)

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

< B1

B3 >

Measure: must be exactly 100 mm / 4 in

v C2

v C2

Trim neighbour page on its border; align to dashed line; match diamonds.

^ A3

^ A3

< B2

B4 >

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

< B2

B4 >

Measure: must be exactly 100 mm / 4 in

v C3

v C3

Trim neighbour page on its border; align to dashed line; match diamonds.

^ A4

^ A4

< B3

B5 >

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

< B3

B5 >

Measure: must be exactly 100 mm / 4 in

v C4

v C4

^ A5

^ A5

< B4


100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)


< B4

Measure: must be exactly 100 mm / 4 in

v C5

v C5





Trim neighbour page on its border; align to dashed line; match diamonds.

^ B2

^ B2

< C1

C3 >

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

< C1

C3 >

v D2

Measure: must be exactly 100 mm / 4 in

v D2

^ B3

^ B3

< C2

C4 >

ID:
PIE
MA
CU
FA
KN
PA
FA

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

< C2

C4 >

Measure: must be exactly 100 mm / 4 in

v D3

v D3

^ B4

^ B4

< C3

C5 >

ID: B-09p
PIECE: hose port binding (TPU-coated 840D, laser-cut, slot 12 x 40)
MATERIAL: tpu_coated_nylon_840d
CUT 2
FACE UP
KNIFE: CW from the grain-arrow head; cut windows and slits first
PACK: 5200 CORRIE F rev 3
FACE: TPU DOWN (inside)

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

< C3

C5 >

Measure: must be exactly 100 mm / 4 in

v D4

v D4

Trim neighbour page on its border; align to dashed line; match diamonds.

^ B5

^ B5

< C4


100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

< C4


Measure: must be exactly 100 mm / 4 in

v D5

v D5



Trim neighbour page on its border; align to dashed line; match diamonds.



Trim neighbour page on its border; align to dashed line; match diamonds.

^ C3

^ C3

< D2

D4 >

ID: IMP4-b
PIECE: door pocket bellows (bottom + 2 sides, one strip)
MATERIAL: robic_100d_ripstop
CUT 1
FACE UP
KNIFE: CW from the grain-arrow head; cut windows and slits first
PACK: 5200 CORRIE F rev 3
FACE: coated side DOWN (inside)

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

< D2


D4 >

Measure: must be exactly 100 mm / 4 in

v E3

v E3

Trim neighbour page on its border; align to dashed line; match diamonds.


^ C4
^ C4
< D3
D5 >
100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)
< D3
D5 >
Measure: must be exactly 100 mm / 4 in
v E4
v E4

^ C5

^ C5

< D4

< D4

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

Measure: must be exactly 100 mm / 4 in

v E5

v E5

^ D1

^ D1

E2 >

ID: IMP4-a
PIECE: door pocket face
MATERIAL: robic_100d_ripstop
CUT 1
FACE UP
KNIFE: CW from the grain-arrow head; cut windows and slits firs
PACK: 5200 CORRIE F rev 3
FACE: coated side DOWN (inside)

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

Measure: must be exactly 100 mm / 4 in

E2 >

v F1

v F1

^ D2

^ D2

< E1

E3 >

I slits first

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

< E1

E3 >

v F2

Measure: must be exactly 100 mm / 4 in

v F2

^ D3

^ D3

< E2

E4 >

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

< E2

E4 >

Measure: must be exactly 100 mm / 4 in

v F3

v F3

Trim neighbour page on its border; align to dashed line; match diamonds.

^ D4

^ D4

< E3

E5 >

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

< E3

E5 >

Measure: must be exactly 100 mm / 4 in

v F4

v F4

^ D5

^ D5

< E4


100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

< E4


Measure: must be exactly 100 mm / 4 in

v F5

v F5



Trim neighbour page on its border; align to dashed line; match diamonds.



wer mesh)
pandex

ead; cut windows and slits first

Trim neighbour page on its border; align to dashed line; match diamonds.

^ E3

^ E3

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

Measure: must be exactly 100 mm / 4 in

< F2

F4 >

< F2

F4 >

v G3

v G3

ID: FP-b

Trim neighbour page on its border; align to dashed line; match diamonds.

^ E4

^ E4

< F3

F5 >

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

< F3

F5 >

v G4

Measure: must be exactly 100 mm / 4 in

v G4

^ E5

^ E5

< F4


100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

< F4


Measure: must be exactly 100 mm / 4 in

v G5

v G5



Trim neighbour page on its border; align to dashed line; match diamonds.


^ F2
^ F2
< G1
G3 >
100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)
< G1
G3 >
Measure: must be exactly 100 mm / 4 in

ID: FP-b
PIECE: hip-reach pocket mouth band (camo)
MATERIAL: polyester_ht_630d_printable
CUT 2
FACE UP
KNIFE: CW from the grain-arrow head; cut windows and slits first
NOTE: see NOTES page (FP-b)
PACK: 5200 CORRIE F rev 3
FACE: print UP

^ F3

^ F3

< G2

G4 >


100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

Measure: must be exactly 100 mm / 4 in

< G2

G4 >

Trim neighbour page on its border; align to dashed line; match diamonds.


^ F4
^ F4
< G3
G5 >
100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)
< G3
G5 >
Measure: must be exactly 100 mm / 4 in

^ F5

^ F5

< G4

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

< G4

Measure: must be exactly 100 mm / 4 in

CORRIE F rev 3 Step 1: pockets (FP hip-reach, IMP-4, IMP-8, IMP-2 sleeve, F: piece NOTES (full text)

FP-a hip-reach pocket body (power mesh)

stretch ACROSS; 2 box pleats; one each gusset (FP-L, FP-R)

FP-b hip-reach pocket mouth band (camo)

shock-cord channel; fold on the line, cord inside

F-02 fly base pocket

under B-05, #5 coil zip on the floor's aft edge (panels.yaml F-02)

B-16 under-strap floor channel (US1 / US2)

ends turned 15 mm and left OPEN (the 25 mm under-strap passes through); topstitch both long edges