Step 6: meat ports + fairlead swell (practise one swell on scrap) - PAGE MAP

Paper: LETTER 215.9 x 279.4 mm, 1 rows x 3 cols = 3 tiles (+ this map = 4 pages).

Print at 100% / ACTUAL SIZE (no 'fit to page'). Verify the 100 mm and 4 in squares.

Assemble: rows A.. top to bottom, columns 1.. left to right; overlap 12 mm.

Lines: solid = CUT, grey dashed = SEW, red = notches, blue arrow = grain, circle+cross = drill hole.



100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

Measure: must be exactly 100 mm / 4 in

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

Measure: must be exactly 100 mm / 4 in

A2 >



ID: B-15b
PIECE: IM3 swell cap, upper (32 mm)
MATERIAL: challenge_ultra_200
CUT 2
FACE UP
KNIFE: CW from the grain-arrow head; cut inside windows/slots first
PACK: 5200 v3.1

A2 >



ID: B-13
PIECE: swell cap half, IM
MATERIAL: challenge_u
CUT 8
FACE UP
KNIFE: CW from the gra
PACK: 5200 v3.1



ID: B-12
PIECE: meat-strap port frame
MATERIAL: hypalon_coated_nylon
CUT 6
FACE UP
KNIFE: CW from the grain-arrow head; cut inside windows/slots first
PACK: 5200 v3.1

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

Measure: must be exactly 100 mm / 4 in

< A1

A3 >

< A1

A3 >

ıp half, IM1/IM2 (45 mm)
allenge_ultra_200

n the grain-arrow head; cut inside windows/slots first
.1



ID: B-14a
PIECE: hinge swell cap, lower (22 mm)
MATERIAL: challenge_ultra_200
CUT 2
FACE UP
KNIFE: CW from the grain-arrow head; cut inside windows/slots first
PACK: 5200 v3.1



100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

< A2

Measure: must be exactly 100 mm / 4 in

< A2

ID: B-14b
PIECE: hinge swell cap, upper (68 mm)
MATERIAL: challenge_ultra_200
CUT 2
FACE UP
KNIFE: CW from the grain-arrow head; cut inside windows/slots first
PACK: 5200 v3.1

ID: B-15a
PIECE: IM3 swell cap, lower (58 mm
MATERIAL: challenge_ultra_200
CUT 2
FACE UP
KNIFE: CW from the grain-arrow hea
PACK: 5200 v3.1