# Step 8: hipbelt size M - PAGE MAP

Paper: LETTER  215.9 x 279.4 mm, 4 rows x 3 cols = 12 tiles (+ this map = 13 pages).

Print at 100% / ACTUAL SIZE (no 'fit to page'). Verify the 100 mm and 4 in squares.

Assemble: rows A.. top to bottom, columns 1.. left to right; overlap 12 mm.

Lines: solid = CUT, grey dashed = SEW, red = notches, blue arrow = grain, circle+cross = drill hole.




100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

Measure: must be exactly 100 mm / 4 in

PRINT AT 100% / ACTUAL SIZE - check test square

**ID: H-10**
PIECE: lumbar wedge sleeve
MATERIAL: robic_210d_ripstop
CUT 1
FACE UP
KNIFE: CW from the grain-arrow head; cut inside windows/slots first
PACK: 5200 v3.1

A2 >

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

A2 >

**ID: H-07**
PIECE: lumbar pad face (grippy)
MATERIAL: spacer_mesh_3d
CUT 1
FACE UP
KNIFE: CW from the grain-arrow head; cut inside windows/slots first
PACK: 5200 v3.1

Measure: must be exactly 100 mm / 4 in

v B1

v B1

**ID: SH-05**
PIECE: hipbelt wing-tip shard
MATERIAL: polyester_ht_630d_printable
CUT 2 (1 PAIR L+R)
FACE UP
KNIFE: CW from the grain-arrow head; cut inside windows/slots first
NOTE: same all sizes; tip edges caught in the binding, inner edge turned 8 mm
PACK: 5200 v3.1

**ID: R-03**
PIECE: rifle-boot mount tab
MATERIAL: hypalon_coated_nylon
CUT 4
FACE UP
KNIFE: CW from the grain-arrow head; cut ir
PACK: 5200 v3.1

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

Measure: must be exactly 100 mm / 4 in

**ID: H-08**
PIECE: lumbar pad foam, stage 1
MATERIAL: eva_foam_45c
CUT 1
FACE UP

< A1 A3 > v B2

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

**< A2**

Measure: must be exactly 100 mm / 4 in

**< A2**



**v B3**

**v B3**

PRINT AT 100% / ACTUAL SIZE - check test square

PACK: 5200 v3.1

^ A1

^ A1

B2 >

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

**ID: H-05**
PIECE: hipbelt wing stiffener
SIZE: M
MATERIAL: hdpe_sheet
CUT 2 (1 PAIR L+R)
FACE UP
KNIFE: CW from the grain-arrow head; cut inside windows/slots first

B2 >

Measure: must be exactly 100 mm / 4 in

v C1

v C1

MATERIAL: eva_foam_45c
CUT 1
FACE UP
KNIFE: CW from the grain-arrow he , cut inside windows/slots first
PACK: 5200 v3.1

^ A2

^ A2

< B1

B3 >

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

**ID: H-06**
PIECE: lumbar pad shell
MATERIAL: cordura_330d_nylon66
CUT 1
FACE UP
KNIFE: CW from the grain-arrow head; cut insid
PACK: 5200 v3.1

< B1

B3 >

ts first

Measure: must be exactly 100 mm / 4 in

v C2

v C2

PRINT AT 100% / ACTUAL SIZE - check test square

^ A3

^ A3

**ID: H-09**
PIECE: lumbar stage-2 wedge insert (removable)
MATERIAL: eva_foam_45c
CUT 1
FACE UP
KNIFE: CW from the grain-arrow head; cut inside windows/slots first
PACK: 5200 v3.1

< B2

cut inside windows/slots first

< B2

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

Measure: must be exactly 100 mm / 4 in

v C3

v C3

PRINT AT 100% / ACTUAL SIZE - check test square

^ B1

^ B1

C2 >

**ID: H-03**
PIECE: hipbelt wing load foam
SIZE: M
MATERIAL: eva_foam_45c
CUT 2 (1 PAIR L+R)
FACE UP
KNIFE: CW from the grain-arrow head; cut inside windows/slots first

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

C2 >

Measure: must be exactly 100 mm / 4 in

v D1

v D1


^ B2
^ B2
< C1
C3 >
ID: H-04
PIECE: hipbelt wing comfort foa
SIZE: M
MATERIAL: eva_foam_30c
CUT 2 (1 PAIR L+R)
FACE UP
KNIFE: CW from the grain-arro
slots first
100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)
< C1
C3 >
Measure: must be exactly 100 mm / 4 in
v D2
v D2

^ B3

^ B3

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

Measure: must be exactly 100 mm / 4 in

< C2

mfort foam

_30c

rain-arrow head; cut inside windows/slots first

< C2

v D3

v D3

PRINT AT 100% / ACTUAL SIZE - check test square




^ C2
^ C2
ide windows/slots first
< D1
D3 >
100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)
< D1
D3 >
Measure: must be exactly 100 mm / 4 in

PRINT AT 100% / ACTUAL SIZE - check test square

**ID: H-02**
PIECE: hipbelt wing body face
SIZE: M
MATERIAL: spacer_mesh_3d
CUT 2 (1 PAIR L+R)
FACE UP
KNIFE: CW from the grain-arrow head; cut inside windows/slots first

^ C3

^ C3

< D2

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

Measure: must be exactly 100 mm / 4 in

< D2