Step 8: hipbelt size S - PAGE MAP

Paper: LETTER 215.9 x 279.4 mm, 4 rows x 3 cols = 12 tiles (+ this map = 13 pages).

Print at 100% / ACTUAL SIZE (no 'fit to page'). Verify the 100 mm and 4 in squares.

Assemble: rows A.. top to bottom, columns 1.. left to right; overlap 12 mm.

Lines: solid = CUT, grey dashed = SEW, red = notches, blue arrow = grain, circle+cross = drill hole.



100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

Measure: must be exactly 100 mm / 4 in

PRINT AT 100% / ACTUAL SIZE - check test square

ID: H-10
PIECE: lumbar wedge sleeve
MATERIAL: robic_210d_ripstop
CUT 1
FACE UP
KNIFE: CW from the grain-arrow head; cut inside windows/slots first
PACK: 5200 v3.1

A2 >

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

A2 >

ID: H-07
PIECE: lumbar pad face (grippy)
MATERIAL: spacer_mesh_3d
CUT 1
FACE UP
KNIFE: CW from the grain-arrow head; cut inside windows/slots first
PACK: 5200 v3.1

Measure: must be exactly 100 mm / 4 in

v B1

v B1

ID: SH-05
PIECE: hipbelt wing-tip shard
MATERIAL: polyester_ht_630d_printable
CUT 2 (1 PAIR L+R)
FACE UP
KNIFE: CW from the grain-arrow head; cut inside windows/slots first
NOTE: same all sizes; tip edges caught in the binding, inner edge turned 8 mm
PACK: 5200 v3.1

ID: R-03
PIECE: rifle-boot mount tab
MATERIAL: hypalon_coated_nylon
CUT 4
FACE UP
KNIFE: CW from the grain-arrow head; cut ir
PACK: 5200 v3.1

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

Measure: must be exactly 100 mm / 4 in

ID: H-08
PIECE: lumbar pad foam, stage 1
MATERIAL: eva_foam_45c
CUT 1
FACE UP

< A1
A3 >
v B2

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

Measure: must be exactly 100 mm / 4 in

< A2

< A2



v B3

v B3


PACK: 5200 v3.1
^ A1
^ A1
B2 >
100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)
ID: H-05
PIECE: hipbelt wing stiffener
SIZE: S
MATERIAL: hdpe_sheet
CUT 2 (1 PAIR L+R)
FACE UP
KNIFE: CW from the grain-arrow head; cut inside windows/slots first
B2 >
Measure: must be exactly 100 mm / 4 in
v C1
v C1

MATERIAL: eva_foam_45c
CUT 1
FACE UP
KNIFE: CW from the grain-arrow he[illegible], cut inside windows/slots first
PACK: 5200 v3.1

^ A2

^ A2

< B1

B3 >

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

ID: H-06
PIECE: lumbar pad shell
MATERIAL: cordura_330d_nylon66
CUT 1
FACE UP
KNIFE: CW from the grain-arrow head; cut inside windows/slots first
PACK: 5200 v3.1

< B1

B3 >

Measure: must be exactly 100 mm / 4 in

v C2

v C2

^ A3

^ A3

ID: H-09
PIECE: lumbar stage-2 wedge insert (removable)
MATERIAL: eva_foam_45c
CUT 1
FACE UP
KNIFE: CW from the grain-arrow head; cut inside windows/slots first
PACK: 5200 v3.1

< B2

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

< B2

Measure: must be exactly 100 mm / 4 in

v C3

v C3

PRINT AT 100% / ACTUAL SIZE - check test square



ID: H-03
PIECE: hipbelt wing load foam
SIZE: S
MATERIAL: eva_foam_45c
CUT 2 (1 PAIR L+R)
FACE UP
KNIFE: CW from the grain-arrow head; cut inside windows/slots first

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

Measure: must be exactly 100 mm / 4 in

Trim neighbour page on its border; align to dashed line; match diamonds.

^ B2

^ B2

< C1

C3 >

ID: H-04
PIECE: hipbelt wing comfort foam
SIZE: S
MATERIAL: eva_foam_30c
CUT 2 (1 PAIR L+R)
FACE UP
KNIFE: CW from the grain-arrow head; cut inside windows/slots first

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

< C1

C3 >

Measure: must be exactly 100 mm / 4 in

v D2

v D2

PRINT AT 100% / ACTUAL SIZE - check test square

^ B3

^ B3

< C2

100 mm TEST SQUARE (solid)
4 in TEST SQUARE (dashed)

< C2



v D3

Measure: must be exactly 100 mm / 4 in

v D3

PRINT AT 100% / ACTUAL SIZE - check test square



Trim neighbour page on its border; align to dashed line; match diamonds.

PRINT AT 100% / ACTUAL SIZE - check test square





PRINT AT 100% / ACTUAL SIZE - check test square