
Four-phase intensity modulation (raw)
Pair (0,1)
Pair (1,2)
Pair (2,3)
Pair (0,0)
Mean intensity
Phase φ (rad)
ch=50
ch=100
ch=200
ch=300