

Oxford Flying Club Flight Operations Incident Report (FOIR)		
To: OFC Safety Officer	From:	Date:
10. Of 6 Galety Childer	(1433	(V US)
	•	34X) 12-27-2020
Note: Refer to Club website	Note: Name is optional but helpful.	
1. Type of Event - check all appro	~ {	
☐ Altitude Deviation	☐ Runway/taxiway excursion	☐ Foreign Object Damage
☐ Navigational Deviation	☐ Runway Incursion	☐ Severe Wake Turbulence
☐ Communication Error	☐ Severe Turbulence	☐ Collision Hazard
☐ Severe Icing	☐ Aborted Takeoff	▼ Other
2. Weather Conditions - check all appropriate responses		
	☐ Thunderstorm	☐ Icing
X VMC	☐ Turbulence	☐ Crosswind
☐ Precipitation	□ Windshear	☐ Other
3. Time/Date - check or fill out all		G 0400 0750 l14:
Month 12 Day 27	Year 2020 0900 Hes	□ 0400-0759 local time
☐ 1200-1559 local time	☐ 1600-1959 local time	☐ 2000-2359 local time
4. Mode of Flight	M Cl' 1	TO Descrit
☐ Ramp	X Climb	Descent
☐ Taxi	☐ Cruise	☐ Approach
☐ Takeoff	☐ Holding	□ Landing
5. Action Taken - check all appro		U. Flight Engine Chutdown
☐ Performed Emergency Proc.	☐ Declared Emergency	☐ In-Flight Engine Shutdown
▼ Followed Checklist	☐ Requested Crash/Rescue	M Divert From Dest. Airport
Requested Medical Assist. Other		
6. Safety Officer, or his/her designee, Initial Assessment Probability: 1 Severity: 2		
Probability. Note: Pick Assessment Code of 5 requires		
Resulting Risk Code: 2 Note: Risk Assessment Code of 5 requires immediate notification of Club President.		
7. Comments or Suggestions (Use additional sheets as necessary)		
	DROPPED TO ZERO DURING CL	IMB. CYCLED LIGHTS, PITOT
	MOVEMENT WITH NO RESPON	
ALTERNATOR PROBLEM AND R	LETURNED TO LAND AT OXC V	VITHOUT DECLARING EMBRGENCY.
NO OTHER ISSUES NOTED, I	NO WARNING LIGHTS. LATER	L LEARNED THIS GAUGE WAS
KNOWN BY MANY TO BE UNE	LELIABLE. I DID NOT SEE AI	by notice of same noted any where
8. Safety Officer, or his/her design	gnee, Investigation summary:	
Safety Officer, or his/her designee,		Date 02/11/2021
Tracking " (accigned 2) carety circuit		
Summary: We're looking at ways to test voltage drop via the POH. At this		
time, we have not found an error in the system and only note		
this ammeter issue as a squawk and are looking to see if it		
9. Notes replacement.		
a) If a NASA form was filed (Strongly Recommended if practical), please attach a copy to this report.		
b) For confidentiality, this form may be delivered to any Safety Committee representative.		
Thank you for your interest in your Safety Program.		

DCR-2019-001 OFC1002 Revision: Initial Date: March 14, 2019