OXFORD FLYING CLUB

MEETING MINUTES

Regular Meeting, 17 October 2006

Attendees: Crabtree, Heidrich, Hill, Nalband, Proulx, Richardson, Schmecker, Willenbring, Wilson, Palmatier, Noffke, Sabot, Aulet, Dasilva, Smith

- 13 Regular Members (Quorum)
- 2 Associate Members

General: Scott called the meeting to order at 7:10 PM.

Last Minutes: Minutes from the last meeting were accepted as drafted.

Maintenance Report: Brian Proulx Presented the latest MX report. (See last page for open issues. Also see Web Site for latest status.)

Also...

N33659

Loose ignition issue.

N4384F

• Discussion regarding the timing of annual.

N8261H

• Will require annual in May.

Brian P. presented engine replacement/overhaul/rebuild options for 61H, After much discussion, a motion was made "to rebuild 61H's "First Run Engine" and use new cylinders in accordance with Brian P's research. Further, that the club authorize a projected start date of 1 December 2006, and that SAS perform the work." The motion was carried unanimously.

Though not voted, it was generally agreed that when 61H gets it's new / rebuilt engine that it must be preheated in the hanger overnight during cold weather. (Shall we define a specific outdoor temp?)

Ken Cohen offered to donate 10 leather hides (estimated at \$650) if we want to redo the interior of 61H. This would entail the four seats and side panels. Brian will bring additional information to the next meeting, e.g. color, STCs...

Membership Report: Max Aulet reported:

- Club currently has 22 regular, 2 student, and 7 associate members.
- There are currently nine prospective members.

Treasurers Report: Brian W. reported that dues will stay at \$205 per month until March. We needed \$35k of internal financing; only got \$20k. See September minutes for further details. These actions will result in paying off the 61H loan.

Treasurer's report accepted unanimously.

Motion to accept all reports was seconded and accepted unanimously.

Old Business:

- 659 is no longer available as of 1 November.
- Discussion to keep third tie down. No resolution.
- Raj's Arrow agreement:
 - o \$110 per hours
 - O Put on the scheduler. Scott to follow up with Raj.
 - Leave a set of keys in the cabinet.
 - Club cautioned...
 - That club insurance does not cover members who fly the Arrow.
 - That the club's two-hours each month don't cover the cost of renting the Arrow.
- Holiday Party: See last month's minutes. Party is scheduled for Friday, 15 December, 6:30PM at the Olive Tree in Southbury.

New Business:

- At next meeting consider modifying bank-time and/or booking policy.
- Safety:
 - o Kevin Kett appears to be in violation. Ron Schmecker to call Kevin.
 - o Jay Sabot requested nominations for candidates for this year's Safety Award. Consider the decision process that demonstrates an awareness of safety.
- Pinch Hitter Program was reintroduced:
 - Club sponsors course—approx 8 hours.
 - o By dissemination of minutes, Bruce P would poll membership for interest.
 - o Will be an item for the November Agenda.
- Ron Schmecker provided a description of the 60-day, AFR, BFR requirements.
- Scott suggested a "Family Plan." Brian W. recommended forming a committee to study. Scott, Max, and Ron volunteered to man the committee.
- Plane wash 3 November. Come on out and make 'em beauteous!
- A post-meeting discussion of an LSA was undertaken...

Adjournment: 9:00 PM

Next Meeting: 21 November, 7:00 PM, Main Terminal, OXC.

Respectfully submitted,

/s/

Bruce Palmatier

OFC Maintenance Report Active Issues - October 2006

	Open Date	ID#	Issue	Resolution	Scheduled for	Status Assigned
<u>N8261H</u>						
	10/9/2006	247	Tail light lens broken, but lamp is operational	Will need to order a new assembly, can not repair the current one.		Pending
	7/30/2006	224	Engine hesitation at low RPM	Accelerator pump problem inside carb. Not a major issue but sure is an expensive solution. Decided to hold until engine overhaul. Accelerator pump issue is an inconvienence not a problem.		Open SAS
N4384F						
	10/17/2006	252	500hr Superior warranty check deferred to annual in May	Appears that the Millennium Engine program is shutting down.		Pending
	10/17/2006	251	While changing the oil, Pete noticed that the landing light connector was broken.	New one on order	10/18/2006	Open Classic Air
	8/11/2006	232	Static wick loose/missing on Rt wing	Pending		
N33659						
	10/17/2006	253	50hr Oil Change due		10/18/2006	Open OFT
	10/16/2006	250	Key fell out while in the L mag position	This problem has been there for a while		Pending
	8/14/2006	237	Prop filed but not painted, exposed metal.	was not addressed at annual		Open OFT

As of Tuesday, October 17, 2006