Membership Report: Provided by Don H.



Membership Report Oxford Flying Club

Don Heidrich, August 2013

Membership Changes since Last Meeting:

Resigned:

- <none>

Status Change:

Mike Fazio to Regular (from Mentored Student)

Joined:

- Joe Bell (Joined at July Meeting)
- Ed Hill (Joined at July Meeting)
- Ed Kuhsel (Joined at July Meeting)
- Richard Esposito (joined this week)

Current Totals

Regular 39 Student 5 Mentored Student 0

Associate 11 (Includes Dom Dasilva)

Med Associate 0

Total 55

Other Notes:

Prospects – all are still interested:

- Scott Price Flies with Kyle, getting back into flying, attended Safety Day
- Norm Forrester Student, paused for a while, attended Safety Day
- Jeff DiStasio Flew with Barry Lerman, works for Cisco
- John Herman was member of HFD club, hasn't flown in 4 years
- Greg Delp ATP / Pro / A&P Wants to teach his daughter, will wait until spring.
- Rich Esposito App submitted, 64, wants to get Medical first
- Tom Krasowski owns a Cherokee, working on IFR with Ron, interested after that

<u>Treasurer's Report:</u> Kristi D. summarized and provided reports via email (see attached)

MX Report: Brian P. summarized and provided reports via email (see attached). See BOD meeting minutes 30Jul2013 for LRP and maintenance discussions.

Safety:

No issues reported or discussed.

The club adjourned at 2:54 PM.

No after the meeting presentation.

Submitted by, Karl Noffke

Document History

Version	Date	Change Reference
1.0	03-Aug-2013	Original release
2.0	07-Aug-2013	Added Richard Esposito as present to attendance.
3.0	19-Aug-2013	Added treasurer and MX reports

Oxford Flying Club

Current Financial Status

Balance Sheet

08/17/13

F	13	35	e	t.	5	
$\overline{}$						

Accounts Receivables			\$17.105
	N8261H	\$82,000	
	N4384F	\$51,000	
	N98819	\$45,000	
	N7362Y	\$97,000	
Planes - (values based on AOPA Vref figures as of 1/2	1/2013)		\$275,000

Total Assets: \$386,271

Liabilities

Accounts Payable	-\$329
Bank Time	\$16,002
Loans	\$59,135
Engine & Prop Reserve* includes P&E on 7362Y to date	\$111,503

Total Liabilities: \$186,311

> \$199,960 Total Equity:

Profit & Loss Statement

	July-13	YTD
Total Income	\$22,938	\$119,238
Expenses		
	Monthly	YTD

		ivionitiny	110
N4384F Annu	ual in 05/13 @ \$5,211	\$475	\$14,247
N8261H Annu	ual in 03/13 @ 6169, ELT@1552	\$3,093	\$20,323
N98819 Annu	ual in 12/12 @ \$?	\$1,492	\$13,055
N7362Y Annu	ual in 12/12 @ \$9498	\$3,308	\$9,824
Officers Flying Time		\$760	\$5,130
Fuel & Oil Expense		\$8,773	\$38,680
Other Expenses		\$1,569	\$8,946

Total Expenses:	\$19,470	\$110,204
Net Income (before extraordinary costs):	\$3,468	\$9,034

Net Income:

OFC Maintenance Report Active Issues - August 2013

Open Date	ID#	Issue	Resolution	Scheduled for	Status	Assigne
N4384F						
6/17/2013	887	Electric trim INOP	Clutch is slipping, may need to rebuild clutch.		Open	Image
<u>N98819</u>						
4/15/2013	869	Finish touching up the paint and corrosion on 819	Received a quote for \$500 from Russ. Will need to work through the details.		Open	Club

Friday, August 16, 2013 Page 1 of 1

OFC Maintenance Report Closed Issues - August 2013

Open Date	ID#	Issue	Resolution	Status	Assigned	Clos e Date
N4384F						
8/4/2013	907	Fuel cap left side missing	Located a part. Replaced.	Closed	Club	8/6/2013
8/1/2013	905	25hr oil change	No metal in filter	Closed	Club	8/1/2013
7/24/2013	904	Bad plug, Cyl #2	Replaced plug with servicable unit	Closed	Image	7/24/2013
N7362Y						
8/15/2013	914	New static wick		Closed	Image	8/15/2013
8/15/2013	913	Finally found the problem with the nose wheel shimmey	New nose tire installed	Closed	Image	8/15/2013
8/6/2013	3 909	Slight fuel residue on left side fuel sump and surrounding area	Further investigation led to a potential fuel overvill scenario that was observed by Ed C.	Closed		8/8/2013
8/4/2013	3 908	Cigarette plug INOP	Found the culprit fuse near the gear handle under the panel. Replaced with identical 9A fuse. DO NOT EXCEED 9A of power.	Closed	Image	8/8/2013
8/1/2013	906	50hr oil change	no oil in filter	Closed	Club	8/1/2013
<u>N8261H</u>						
8/8/2013	911	50hr oil change	No metal found in filter	Closed	Club	8/8/2013

Open Date	ID#	Issue	Resolution	Status	Assigned	Clos e Date
7/18/2013	902	Having problems AGAIN with the ALT transmission on the GTX330 Txpndr	Club voted to replace the blind encoder at VIP. New encoder installed, appears to be the issue.	Closed	VIP	7/18/2013
7/5/2013	899	50hr oil change		Closed	Club	7/5/2013
7/3/2013	898	GPS antenna loosing signal very	This is possibly due to an antenna fault. Antenna is about \$1000 new. If it occurs again I will have the antenna replaced. IFR pilotsbrush up on your NAV radio skills.	Closed	VIP	8/4/2013
7/13/2013	897	Having problems with the ALT transmission on the GTX330 Txpndr	According to Ron, they can see the FLxxx readings which indicates that the blind encoder is working. 3-Wing in BDR tested the entire system up to 10000ft with no anomolies. Will need to	Closed	3-Wing	7/9/2013
7/3/2013	896	DG is precessing. Had to adjust several times during each of two ~1 hour trips today	Note that the compass is off by about 10-15deg on specific headings. This has been a known issue for a long time. Due to GNS530 electrical field. May be able to degauss the airframe.	Closed	VIP	7/18/2013
<u>N98819</u>						
8/14/2013	912	Repaired broken plastic		Closed	Club	8/14/2013
7/20/2013	903	Bendix sw AD compliance (100hr)		Closed	Russ	7/20/2013
7/3/2013	895	Missing seat belt clip on mainharrness to click the shoulder harness	Classic replaced the missing part.	Closed		7/7/2013

Open Date	ID#	Issue	Resolution	Status	Assigned	Clos e Date
7/1/2013	894	ATC has had a hard time receiving altitude from our transponder	Going to VIP on Monday 7/15 for further investigation. Could possibly the switch on the Txpndr. Replaced the switch and all is OK.	Closed	VIP	7/15/2013
7/1/2013	893	The cable to the parking brake has snapped from wear	New cable installed	Closed	Image	7/11/2013

Maintenance Overview								
1981 Piper Archer II - N8261H (28-8190025)								
August 8, 2013 Eng. TT 3900.0								
				TTAF	3900.0			
Annual Insp & hours to date	3755.24 144.76			SMOH	1847.1			
Tachometer Reading	3900.0	50hr Oil Due	50.0	TBO	152.9	prop	152.9	
Engine Overhaul (11/30)	2052.9	oil samples	8/8/2013	Hobbs (calc)	4590.3			

Estimated Engine replacement Feb-2014

Maintenance Overview										
1977 Piper Archer II - N4384F (28-7790026)										
		August 9, 2013	Eng. TT	5378.3						
				TTAF	6753.3					
Annual Insp & hours to date	2464.8 61.3			SMOH	794.0					
Tachometer Reading	2526.1	50hr Oil Due	21.9	TBO	-169.0	prop	693.1			
Tach at Replacement	4042.0	oil samples	8/1/2013	Hobbs (calc)	8076.3					

Estimated Engine replacement Feb-2013

Expect to go 250 beyond TBO with new lycoming cylinders installed 8/2010 Nov-2013

Maintenance Overview										
1985 Cessna 172P - N98819 (17276362)										
August 8, 2013										
				TTAF	6884.0					
Annual Insp & hours to date	6730.9 153.1			SMOH	1567.0					
Tachometer Reading	6884.0	50hr Oil Due	50.0	TBO	433.0	prop	1183.3			
Engine Overhaul	5317.0	Oil Sample	7/22/2013	Hobbs (calc)	0.0					

Estimated Engine replacement Oct-2015

Maintenance Overview 1977 Cessna R182 - N7362Y (R18200127) July 10, 2013									
				TTAF	4666.2	4397.0	OFC in service		
Annual Insp & hours to date	4477.00 189.2			SMOH	241.7	3237.5	overhauled engine hrs		
Tachometer Reading	4666.2	50hr Oil Due	25.8	TBO	1010.9	3479.2	time on engine		
Engine Overhaul (11/30)	3677.1	oil samples	6/9/2013	Hobbs (calc)	5492.1				
				Prop TBO	1288.8	or 8/2017			

Estimated Engine replacement Dec-2016