OXFORD FLYING CLUB

BOARD MEETING MINUTES (16 Sep 2014)

Location: 121 Restaurant Oxford, CT

Attendance: Regular: 12 Reg. /Students: 1 Associates: 2 Quorum: Yes No X

| | Туре | Member | Present | Туре | Member | present | Туре | Member | Present |
|----|---------------------|---------------------|---------|-------|--------------------|---------|-------|-------------------|---------|
| 1 | Assoc | Aulet, Maximillian | | Reg | Hill, Ed | | Reg | Proulx, Brian | х |
| 2 | Reg | Baker, Matt | х | Assoc | Hill, Jeremy | | Reg | Pugliese, Jay | |
| 3 | Reg | Bell, Joe | | Reg | Kit, Volodymyr | | Reg | Mahesh, Reddy | |
| 4 | Assoc | Berwick, Ken | | Reg | Krasowski, Tom | | Reg | Richardson, Bruce | |
| 5 | Reg | Burmann, Bruce | | Reg | Kuhsel, Bob | | Stu | Riolo, Jonah | |
| 6 | Assoc | Camejo, Christopher | | Reg | Laine, George | | Reg | Robinson, Andy | |
| 7 | Reg | Carr, Tim | | Reg | Lafosse, Larry | | Reg | Rosen, Stewart | х |
| 8 | Reg | Chromczak, Ed | х | Assoc | Lyons, Hal | | Assoc | Rosendahl, Eric | |
| 9 | Reg | Cooper, Pat | х | Assoc | Moir, Floyd | | Assoc | Sabot, Jay | |
| 10 | Reg | Delp, Greg | Х | Reg | Monahan, Jay | | Assoc | Schindler, Len | х |
| 11 | ASSOC (Honorary) | Dasilva, Dom | | Reg | Morici, John | | Reg | Schmecker, Ron | х |
| 12 | Reg | Distasio, Jeff | | Assoc | Morrone, Matt | | Reg | Shaker, Ed | |
| 13 | Assoc | Dobbs, Glen | | Assoc | Morrow, Bill | | Reg | Stevens, Burt | |
| 14 | Assoc | Dobbs, Kristi | | Reg | Mowerman, Illya | | Reg | St. Pierre, Peter | х |
| 15 | Reg | Earl, Gavin | | Stu | Murphy, Mick | | Reg | Suarez, Federico | |
| 16 | Reg | Ebbert, Davis | | Assoc | Nalband, Gary | Х | Reg | Timpson, Larry | |
| 17 | Reg | Fazio, Mike | х | Reg | Nelson, Nick | | Reg | Treanor, Jim | |
| 18 | Reg | Feeney, Richard | | Reg | Noffke, Karl | х | Reg | Tremallo, Wayne | х |
| 19 | Assoc | Feinman, Jason | | Reg | Oloff, Scott | | Reg | Tyrrel, Chris | х |
| 20 | Assoc | Feinman, Phil | | Reg | Palmatier, Bruce | | Stu | Vitagliano, Erik | х |
| 21 | Reg | Green, Geoffrey | | Reg | Palombo, Rich | | Reg | Weiner, Jay | |
| 22 | Reg | Greenwood, Roland | | Reg | Poole, Christopher | | Reg | Wilson, Richard | |
| 23 | Reg | Ham, Robert | | Assoc | Poole, Raymond | | Assoc | Zipkin, David | |
| 24 | Reg | Heidrich, Don | | Assoc | Pozniak, Jerry | | | | |

¹ Per By-Laws, quorum = one-third of regular plus non-mentored student members. In the event a quorum is not achieved, or is subsequently lost, the President will determine if a majority of the board is present. If so, then the meeting will become a Board Meeting.

Ed C. called the board meeting to order at 7:06 PM.

Membership Report: Presented by Ed C.



Membership Report Oxford Flying Club

Don Heidrich, September 2014

Membership Changes since Last Meeting:

Resigned:

- George Laine

Status Change:

- Eric Rosendahl - Regular to Associate

Joined:

- Matthew Morrone - as Associate

Current Totals

Regular 47 Student 3 Mentored Student 0

Associate 19 (Includes Dom Dasilva)

Med Associate 1

Total 70

Other Notes:

New Prospects:

Prior Prospects:

- Richard Aniuk previous member
- Brian Huster from Louisiana, ATP
- Tom Waterhouse from Ron's barbershop
- Peter Hill

- Scott Price Flies with Kyle, getting back into flying, attended Safety Day
- Norm Forrester Student, paused for a while, attended Safety Day
- John Herman was member of HFD club, hasn't flown in 4 years

<u>Treasurer's Report:</u> Presented by Mike Fazio (see attached).

MX Report: Presented by Brian P. (see attached)

- 819 engine break-in complete
- Engine replacement for 61H and 34X are within 3 months of each other

Long Range Planning Committee - September 2014 Provided by Ed. C.

62Y: [1] (annual due October 2014); several avionics upgrades needed, see item 5.

34X: [2] (during annual, December 2014)

Install red rotating tail beacon (either tail or underbelly) \$700 Upgrade ELT to 406 Mhz; \$1500 Fuselage corrosion proofing; \$700 Upgrade the transponder Garmin GTX 330 mode S to Extended Squitter \$2000 Total 2014: \$4900

819: [3] (schedule undetermined, annual due January 2015)

Upgrade of Garmin GNS 430 GPS to WAAS, may be done prior to annual. Engine OH per oil analysis, compression tests & other factors.

Install either the Garmin GDL 88 or FreeFlight RANGR for ADS-B in & out, depending when we want to consider upgrading 62Y; 2014-2015-2016.

Total 2015 or 2017 avionics \$4500 - \$6000

61H: [4] (during annual, March 2015)

Upgrade the transponder Garmin GTX 330 mode S to Extended Squitter; \$2000 Install the dash mounted Garmin 496 GPS now stored in our hangar for WX. \$300 Total 2015: \$2300

62Y: [5] (schedule the following during annual October 2016) Install either the Garmin GDL 88 or FreeFlight RANGR or equivalent to support ADS-B out & in and interconnecting the ADS-B in to the existing MX-20 MFD for the display and removal of inop Zaon traffic display.

> Total 2016: \$5000

Doing the LRP items in the order listed above allows for planned funding. Ed Chromczak 908-400-9370

Safety: No update

Unfinished Business:

• Spot Landing Event – Saturday, July 19th – Bruce R. & Ron S.

No update

• IMC program – John M.

No update

• OFC Grass Strip Landing and Picnic at Mt. Tobe – Bruce R. & Ron S.

Attached is the flyer with the details of the upcoming Grass Strip Landings and Picnic at Mt. Tobe (Waterbury Airport, N41) on Saturday September 20. (Rain date September 27). We will get started at 9:00 AM and launch on 45 minute intervals with a 1 hour break for lunch.

All (4) planes will be available. Brian P. and Ed C. on record against using 7362Y.

• Sporty's 5% Rebate program – Mike F.

Sporty uses your email address on record to send rebate check.

• N55387 – Seneca I – Ad Hoc Committee – Presented by Brian P. (see attached)

Proposal is to lease Seneca1 to club members for approx. \$275/Hr. Waiting for insurance quote.

The Board will decide if discussions on this should be by board meeting or membership meeting.

New Business:

• Associate Emeritus Membership – Mike Fazio

Discussed replacing Honorary Associate Member to Associate Emeritus Member

Reimbursement of non-insurance claims caused by members' actions

No update

• Other items as presented by membership

No update

The club adjourned at 8:10 PM.

Submitted by, Karl Noffke

Document History

| Version | Date | Change Reference |
|---------|-------------|------------------|
| 1.0 | 16-Sep-2013 | Original release |



Oxford Flying Club

Current Financial Status **Balance Sheet**

9/16/2014

| Assets | | | | | | | |
|----------------|-------------------|------------------------|-------------------|----------------------|----------------|--------------------|-----------|
| Cash | | | | | | \$95,183 | |
| Accounts Red | | | | | | \$30,688 | |
| Resources | | | | N8261H | \$85,000 | | |
| | | | | N4334X | \$85,000 | | |
| | | | | | \$44,000 | | |
| | | | | N7362Y | \$94,000 | | |
| Planes - (valu | es based on AOP | A Vref figures as of 5 | /1/2014) | | | \$308,000 | |
| | | | | | | Total Assets: | \$433,871 |
| Liabilities | | | | | | | |
| Accounts Pay | | | | | | -\$136 | |
| Bank Time (t | | | | | | \$19,379 | |
| Loans (purch | ase of 62Y and | d 34X) | | | | \$93,113 | |
| Prop and Eng | gine Reserve (| all planes - cumul | | | | \$61,083 | |
| | | | | | | Total Liabilities: | \$173,439 |
| Aircraft Dat | :a | | | | | | |
| Curr | rent Mo Hrs Flown | Curr Mo Flight Income | Prop/Eng. reserve | Curr Mo Fuel (apprx) | Tiedown/Hangar | Curr Mo Maint. Exp | |
| N4334X | 30.10 | \$4,010 | \$541.80 | \$1,396 | \$90 | \$62 | |
| N8261H | 25.76 | \$3,063 | \$463.68 | \$1,395 | \$90 | \$552 | |
| N98819 | 48.40 | \$4 604 | \$871.20 | \$2 473 | \$90 | \$148 | |

| | | | -17 0 | (-)- | , , , | |
|--------|--------|----------|------------|---------|-------|-------|
| N4334X | 30.10 | \$4,010 | \$541.80 | \$1,396 | \$90 | \$62 |
| N8261H | 25.76 | \$3,063 | \$463.68 | \$1,395 | \$90 | \$552 |
| N98819 | 48.40 | \$4,604 | \$871.20 | \$2,473 | \$90 | \$148 |
| N7362Y | 34.60 | \$5,915 | \$622.80 | \$2,576 | \$600 | \$175 |
| totals | 138.86 | \$17,591 | \$2,499.48 | \$7,840 | \$870 | \$937 |
| | | | | | | |

| Monthly Inflows/Outflows | vs/Outflows Current Month Year-to-date | | | | | |
|---|--|-----------|-------|--|--|--|
| Membership Payments and Flight Time | \$25,139 | \$158,434 | | | | |
| Officers Flying Time | \$792 | \$5,986 | | | | |
| Fuel & Oil Expense | \$7,840 | \$54,575 | | | | |
| Other Misc. Expenses (postage, seminar, safety day, etc.) | \$18 | \$86,050 | | | | |
| Total Aircraft Expense (excluding officer's, BT and misc. flight time) | \$4,306 | \$34,452 | (est) | | | |
| Monthly Inflow (outflow) total: | \$12,183 | \$11,823 | (est) | | | |

OFC Annual Inspections N7362Y items - Annual 2014

| Open Date | ID# | Issue | Resolution | Status | Assigne |
|--------------|------|---|--|--------|--------------|
| 9/16/2014 | 1078 | Seat rail AD inspection | | Annual | Reliant Air |
| 9/16/2014 | 1077 | Clean the plugs | | Annual | Reliant Air |
| 9/16/2014 | 1076 | ~15 hrs to go for SB SEB01-2r1 MLG 500 actuator inspection | | Annual | Reliant Air |
| 8/23/2014 | 1060 | Per Ed, small engine oil leak top front crankcase. Most likely the crank seal. | | Annual | Reliant Air |
| 7/15/2014 | 1051 | Crack in wingtip needs to be stop drilled | | Annual | Reliant Air |
| 6/15/2014 | 1040 | Red line missing on nose gear. | Temporarilly painted a new "Yellow" line. All paint has come off the nose gear and only aluminum remains. Will discuss with J&M Avaition | Annual | Reliant Air |
| 10/30/2013 | 949 | Cessna Aging Aircraft Inspection - Needs to be budgeted and part of our MX plan going forward | | Annual | |
| 9/14/2012 | 797 | Turn Coordinator 1/4 ball out to right when level. | Please level plane and adjust T/C accordingly | Annual | VIP Avionics |

OFC Maintenance Report Active Issues - September 2014

| Open Date | ID# | Issue | Resolution | Scheduled for | Status | Assigne |
|--------------|------|--|---|---------------|---------|-------------|
| N7362Y | | | | | | |
| 7/8/2014 | 1049 | Ordered a new DG to replace the existing DG | Just to repair the instrument is \$2100 and can not be overhauled. New instrument is \$2500 and can be overhauled at VIP. Now have an overhauled instrument installed. May purchase overhauled unit in plane now. | | Open | VIP |
| 6/16/2014 | 1042 | All wheels severly damaged due to gouging from a screw driver, damage is pre-OFC ownership | One is to the point of requiring replacement, others not far behind. Pricing this now. | | Pending | Reliant Air |
| N8261H | | | | | | |
| 9/16/2014 | 1074 | Baggage door lock spins | | | Open | Club |
| 9/16/2014 | 1073 | AI in need of repair | | 9/18/2014 | Open | VIP |
| N98819 | | | | | | |
| 9/16/2014 | 1075 | Turn coordinator bank angle INOP | Placarded INOP | | Pending | VIP |

OFC Maintenance Report Closed Issues - September 2014

| Open Date | ID# | Issue | Resolution | Status | Assigned | Close Date |
|--------------|------|--|--|--------|-------------|---------------|
| N4334X | | | | | | |
| 9/9/2014 | 1071 | 50hr oil change | | Closed | Club | 9/9/2014 |
| 8/27/2014 | 1067 | Need to purchase 4 additional life jackets | Will put 2 jackets in each plane, will need to borrow if more is needed | Closed | Club | 8/27/2014 |
| 8/27/2014 | 1066 | Stall warning tab possibly bent | Damage may have occurred. Need to verify. Test flew plane, goes off ~ 50kts | Closed | Club | 8/28/2014 |
| 8/20/2014 | 1056 | Fuel sump pilot side leaking | Gummed up, all set | Closed | Club | 8/20/2014 |
| N7362Y | | | | | | |
| 9/2/2014 | 1068 | Dynamic prop balance scheduled in S. Carolina | Oloff will have this work done while his is on vacation with the plane. ~\$300 which is average for this work. | Closed | Club | 9/4/2014 |
| 8/23/2014 | 1064 | New brake pads | | Closed | Reliant Air | 8/23/2014 |
| 8/23/2014 | 1063 | 50hr oil change | | Closed | Club | 8/25/2014 |
| 8/23/2014 | 1062 | Tug needs new fuel cap. Avgas did a number on the rubber seal. | Must run the tug with the cap loose or engine will | Closed | Club | 9/16/2014 |
| 8/23/2014 | 1061 | Per Ed, Found metal in filter | Inspected the metal, not too bad. Need to wait for oil analysis. | Closed | Reliant Air | 8/23/2014 |

| Open Date | ID# | Issue | Resolution | Status | Assigned | Close Date |
|--------------|------|---|---|--------|-------------|---------------|
| 8/23/2014 | 1059 | Loose landing light wire/clamp | repaired | Closed | Reliant Air | 8/29/2014 |
| 8/23/2014 | 1058 | Carb heat inlet hose cracked | Repaired | Closed | Reliant Air | 8/29/2014 |
| 8/23/2014 | 1057 | Report of smoke exiting left cowl | Found a valve cover screw missing, some screws loose. Oloff tightened and replaced missing screw. Inspected ny Reliant. Will have prop dynamically balanced | Closed | Club | 8/23/2014 |
| N8261H | | | | | | |
| 9/2/2014 | 1069 | Autopilot issue with activation? | Reported by LaFosse. Will check it out on 9/3. This was not an issue. Appears to be pilot error. | Closed | Club | 9/3/2014 |
| 8/25/2014 | 1065 | 50hr oil change | | Closed | Club | 8/25/2014 |
| 6/6/2014 | 1036 | COM1 transmissions garbled | Issue has to do with COM2 KX155 radio. Currently trying to repair it but may have to result in switching antennas. Swapped antennas and reinstalled our radio. Ops check OK | Closed | VIP | 8/4/2014 |
| N98819 | | | | | | |
| 9/13/2014 | 1072 | 15hr oil change - back to normal oil | | Closed | Club | 9/13/2014 |
| 9/4/2014 | 1070 | 10hr oil change - still @ mineral oil | Breaking in Cyl #2 | Closed | Club | 9/4/2014 |

| Open Date | ID# | Issue | Resolution | Status | Assigned | Close Date |
|--------------|------|--|--|--------|-------------|---------------|
| 8/8/2014 | 1054 | 50hr oil change. Metal found in filter and low comp in 1 cyl | Compression check reveals 52 in Cyl #2. This is the cylinder that Pete L redid when the valve was stuck. Not bad for an overhauled cyl. New Cyl ordered per direction given at special meeting on 8/19. Tach at repair was | Closed | Reliant Air | 8/26/2014 |

| Maintenance Overview | | | | | | | | |
|-----------------------------|--|---------------------------|---------------|-----------------|----------|------|--------|--|
| | 1981 Piper Archer II - N8261H (28-8190025) | | | | | | | |
| | | September 15, 2014 | | Eng. TT | 7731.0 | | | |
| | | | | TTAF | 4229.1 | | | |
| Annual Insp & hours to date | 4062.45 166.67 | | | SMOH | 166.0 | | | |
| Tachometer Reading | 4229.1 | 50hr Oil Due | 35.9 | TBO | 1834.0 | prop | 1834.0 | |
| Engine Overhaul (11/30) | 2052.9 | oil samples | 7/8/2014 | Hobbs (calc) | 4977.7 | | | |
| | | | Estimated Eng | ine replacement | Nov-2020 | | | |

| | Maintenance Overview 1985 Cessna 172P - N98819 (17276362) September 15, 2014 | | | | | | | | | |
|-----------------------------|--|--------------|----------|--------------|--------|------|-------|--|--|--|
| | | | | TTAF | 7274.0 | | | | | |
| Annual Insp & hours to date | 6995.8 278.2 | | | SMOH | 1957.0 | | | | | |
| Tachometer Reading | 7274.0 | 50hr Oil Due | 46.0 | TBO | 43.0 | prop | 793.3 | | | |
| Engine Overhaul | 5317.0 | Oil Sample | 8/8/2014 | Hobbs (calc) | 8561.5 | | | | | |

Estimated Engine replacement Nov-2014 Continue to +250 TBO Jul-2015

| Maintenance Overview | | | | | | | | | |
|---------------------------------------|--------------------|--------------|-----------|--------------|--------|-----------|-----------------------|--|--|
| 1977 Cessna R182 - N7362Y (R18200127) | | | | | | | | | |
| | September 15, 2014 | | | Eng. TT | 4524.0 | | | | |
| | | | | TTAF | 4963.5 | | | | |
| Annual Insp & hours to date | 4757.90 205.6 | | | SMOH | 1286.5 | 3237.5 | overhauled engine hrs | | |
| Tachometer Reading | 4963.5 | 50hr Oil Due | 28.5 | TBO | 713.6 | | | | |
| Engine Overhaul (11/30) | 3677.1 | oil samples | 8/23/2014 | Hobbs (calc) | 5842.0 | | | | |
| | | | | Prop TBO | 991.5 | or 8/2017 | | | |

Estimated Engine replacement Feb-2017

| Maintenance Overview | | | | | | | | |
|--|--------------------|--------------|-----------|--------------|--------|---------|---------------|--|
| 1984 Piper Archer II - N4334X (28-8490040) | | | | | | | | |
| | September 15, 2014 | | | Eng. TT | 211.0 | 3rd ru | ın case | |
| | | | | TTAF | 3533.4 | 15 | 40 in service | |
| Annual Insp & hours to date | 1540 | 144 | | SMOH | 211.0 | | | |
| Tachometer Reading | 1683 | 50hr Oil Due | 42.0 | TBO | 1789.0 | prop 19 | 33 | |
| Engine Overhaul (11/30) | 2053 | oil samples | 9/10/2014 | Hobbs (calc) | 172.7 | | | |

Estimated Engine replacement Mar-2021

ofe Grass Strip Landings and Picnic at Mt. Tobe



This is a great opportunity for OFC members to become proficient in landing on turf fields.

The Club instructors will be available to sit right seat to teach you the proper techniques and sign off your logbook.

Tach time will be charged to participants (PIC).

Highlights !!!!!!

- Become proficient in landing OFC aircraft on turf fields.
- Quality time with your friends and family.
- Meet the Waterbury Airport "regulars".

Oxford Flying Club 288 Christian Street, Box 3, Oxford, CT 06478

Mt. Tobe Airport a.k.a. Waterbury Airport (N41) is located on Mt. Tobe Rd. in Plymouth, CT. From Waterbury, take Rt. 8 north to exit 37. Go right at end of exit, then right at stop sign, cross RR tracks, then right onto Waterbury Rd. Take first left onto Spruce Brook Rd. (Rt. 262) follow for 2.2 miles to Mt Tobe Airport on right.

Questions?: Bruce Richardson 203.592.5962 or bdrichardson@snet.net

Time: 9:00 AM to whenever

Date: September 20, 2014 (Rain date Sept. 27)



Seneca lease Sub-Committee Report

Members in Attendance:

Scott O, Ron S, Mahesh R, Wayne T, Brian P, Chris T, Tom K, Burt S (via phone)

On September 14th, 2014 at 7 p.m. the subcommittee chaired by Scott Oloff met to discuss the following items:

Hi Everyone,

We had an introductory meeting on Sunday, September 14, 2014 at 7PM in the KeyAir conference room. We brainstormed on topics such as:

- Responsibilities of the club for the leased aircraft

Upon discussion of the various scenarios, it was suggested that the Oxford Flying Club (OFC) would be responsible for:

- 1. fuel
- oil
- 3. Insurance (1st year upto \$3,000, then \$5,000 per year), and
- 4. a total of \$4000 per year for miscellaneous maintenance, to include tires, and small items.
- 5. Cost for any damage, not covered by insurance would be covered by the member responsible.

- Responsibilities of the aircraft owner

The Aircraft Owner (AO) would be responsible for:

- 1. Annual,
- 2. 100 hour,
- 3. Hangar/tie-down
- 4. 1st year Insurance upto \$2,000

- Fees collected from members who fly the leased aircraft

The hourly rate was discussed and a tentative rate of \$275.00 per tach hour was set based on the following:

| Description | An. Hrs | Rate | Qty | Per Hour |
|-------------|---------|----------|-----|-----------|
| Fuel | | \$ 7.00 | 22 | \$ 154.00 |
| Insurance | 150 | 5,000.00 | | \$ 34.00 |
| Misc. Maint | 150 | 4,000.00 | | \$ 27.00 |
| Oil | 150 | 1,500.00 | | \$ 10.00 |
| Owner | | | | \$ 50.00 |
| | | | | \$ 275.00 |

In effect the dry rate for the Seneca would be \$121.00 per tach hour.

- Maintenance requirements

OFC would be responsible for oil changes and miscellaneous maintenance to be scheduled out, such as tires, minor damage (Oil caps lost, etc)

- Insurance requirements

Insurance will be under OFC's policy and the Seneca would be an add-on. The Insurance would be fully picked up by the Seneca flying members at no additional cost to the rest of the membership.

- Any other topic raised

It was discussed on how to handle the financial accounting for the owner when he flies the Seneca. It was decided it would be the same as all members, \$275.00 per tach hour.

The assumptions were as follows:

At least10 members interested in flying the Seneca

150 tach hours per year

OFC would attract more members with the twin engine Seneca

Chris Tyrrel raised a question as to who would bear the financial burden if the Seneca was flown only 70 tach hours in the first year. If that were to happen OFC would bear the financial cost for the additional 80 hours *UNLESS*, and to be discussed, the members that sign on for flying it guarantee to absorb the cost before the end of the fiscal year.

It should also be noted that some of the responsibilities, having an impact on the per hour rate, may change as the sub-committee continues its deliberations in the coming weeks.

Mahesh Reddy

September 16, 2014