Open issue: J3 rear end overruns the shell rear wall by ~1.6 mm with S55B (see RESEARCH_TODO item 7b).
MECHANICAL PLACEMENT DRAFT — NOT FOR FAB. Parts right of the board are unplaced (staging).



