

Raymond Test

Daily Construction Site Report

| PROJECT | REPORT DATE | REPORT ID | STATUS |
|---------------------------|-------------------|-----------------|-------------------|
| Footscray Hospital | 10/14/2025 | b2d66d96 | PROCESSING |

Works Summary

Kerb pour - service lane

Poured concrete kerb from the start of the service lane through to the mid-point, including curved and straight sections. Alignment and levels verified against set-out marks. General trimming and preparation of adjacent formation completed.

Key Activities:

- Survey set-out and verification of kerb alignment and levels
- Form, place and finish 320 kg kerb mix concrete from service lane start to mid-point
- Compaction/trim of adjacent formation and clean-up
- Traffic/pedestrian separation maintained with fencing and barriers

Workforce

4

Total Workers

8

Total Hours

32

Man Hours

Works Performed

kerb poured from the start of the service lane to the middle of the service lane

Materials Used

| MATERIAL | QUANTITY | UNIT |
|--------------------------|----------|------|
| 320 kg kerb mix concrete | 12 | m3 |
| Sand | 1 | t |
| Cement (GP) | 3 | bags |

Plant & Equipment

- Site truck

Safety & Incidents

Incidents Reported:

- [object Object]



Safety Observations:

Exclusion zones, temporary fencing and water-filled barriers in place. Housekeeping maintained around work fronts.

Next Day Plan

- Continue kerb pour from mid-point to end of service lane to complete run
- Install required contraction/expansion joints and check line/levels to VicRoads Section 703 tolerances
- Backfill and tidy behind kerb after initial set and commence curing regime
- Prepare for pavement works: final trim and subbase placement adjacent to completed kerb, subject to weather

Site Photos



Report generated by TradeaseAI on 11/13/2025 at 7:14:47 AM

Raymond Test | raymond.cordeiro@gmail.com