

VAR
VAR11
V_in=1


VAR
VAR5
RLoad=2.5 kOhm

VAR
VAR1
CP=350 pF

VAR
VAR2
LP=15 uH

VAR
VAR3
LS=15 uH

VAR
VAR4
F_in=3.4 MHz



Mutual
Mutual1
K=K_M
M=
Inductor1="L1"
Inductor2="L2"

VAR
VAR6
K_M=0.2

VAR
VAR7
C0=350e-12

VAR
VAR8
C1=1.75e-10

VAR
VAR9
C2=1.3125e-10

VAR
VAR10
C3=1.0937e-10

