


Mode-I Stage 6: Integration-Point Stress Variance and Formulation Mechanics

(a) Stress Spread vs Recovery Error along Crack Plane



(b) Error Distribution by Element Formulation

