

Authentic Precritical Indicator Support & $3\ell_0$ Buffers
Full Domain Evaluation: Primary Ligament and Secondary Flank
Precritical Damage ($d \geq 0.05$)
Left FPZ Support ($3\ell_0$ buffer)
Right Flank Support ($3\ell_0$ buffer)
Notch ($a_0 = 0.5$ mm)
Hole ($R = 0.10$ mm)
y [mm]
x [mm]
Authentic Precritical Damage d [-]
0.80
0.75
0.70
0.65
0.60
0.55
0.50
0.45
0.4
0.5
0.6
0.7
0.8
0.40
0.35
0.30
0.25
0.20
0.15
0.10