
Element Resolution & Spatial Selectivity Audit
Model C
Element Size Histogram by Zone
Far Field (N = 9793)
Process Zone (N = 1509)
ℓ0 = 0.0075 mm
ℓ0/2 = 0.0037 mm
Element Count
Element Characteristic Size h_area = √Area [mm]
Cumulative Size Distribution
Process Zone CDF
Far Field CDF
ℓ0
ℓ0/2
Cumulative Fraction
Element Size h_area [mm]