

F1736 Standalone Benchmark Reassessment: Case 2: Plate with an Off-Axis Hole
(Physical Geometry: [0.0, 1.0] × [0.0, 1.0] mm, $\ell_0 = 0.0075$ mm)


(a) Original Coarse Mesh
2906 elements (97.5% Q) | 3010 nodes




(b) Authoritative Adapted Mesh
23965 elements (97.2% Q) | 23957 nodes



(c) Spatial Resolution h_e/ℓ_0 (Capped at 3.0)
$h \le \ell_0$: 79.6% count (24.9% area) | $h_{\min} = 0.66\,\mu$m





(d) Authentic Coupled Phase-Field Damage ($u = 0.00768$ mm)
Job 1423271 (Exit 1 at min dt) | 343 Broken Elements into Hole

