


Component: vacuum crystallization drying spectroscopy/GIWAXS lid. All dimensions in cm. Recommended material: Al.





O-ring groove on both sides of this part for a 3mm o-ring: 3.5mm width, 2.25 mm depth

o-ring needed: 3mm width, 25.7 cm long, I.D. = 8 cm




*for use with 1 cm length M6x1 bolts upon assembly with GIWAXS window holder plates