



Component: vacuum crystallization drying spectroscopy/GIWAXS sample stage. All dimensions in cm. Recommended material: Al.









Part contains 4 M6x1 tapped holes through the depth