


KING AIR/1900 LED WINGTIP LIGHTS



350 Model



90, B200/250, 300 & 1900 Model

ADVANTAGES:

- STC Approved
- Uses TSO-Approved Lights
- Plug and Play Install
- Fit, Form and Function
- Lower Current Draw
- Brighter Than Bulbs
- Long Life LEDs
- No Maintenance
- 5 Year Warranty
- STC Documentation Included

LED LIGHTING EXTERIOR UPGRADE

Finally, you can add LED wingtips to your King Air. STC-approved and a direct fit, form and function replacement.

Not a box of parts, they are delivered fully assembled, tested and ready to install. The wingtip is complete with the new metal bracket and the LEDs (wiring harness included on 350 only).

These wingtips are not only super bright, but they produce far less heat, saving your wingtip lens from warping, crazing and discoloration. And the savings continue by reducing the electrical load on the motor-driven generators. These LED wingtip lights feature a much lower current draw.


Get enhanced visibility on the ground and in the sky. These wingtip lights are brighter than bulbs. And you can get rid of those high voltage strobe power supplies.

Your King Air deserves the premier LED wingtip lights. Consider the growing family of all PWI LED products.

CERTIFICATIONS:
STC: SA03902NY

PRODUCT PAGE
CLICK **HERE**





King Air B300/350

PWI PN: L 6900430 – 002
R 6900431 – 002

Full Assembly	Yes
Plug-and-Play Install	Yes
STC/TSO Approved	Yes
Current Draw (less than bulbs)	70%
Brighter (than bulbs)	500%
Aircraft mods required	None

King Air 90, B200/250, 300; 1900

PWI PN: L 6900445 – 001
R 6900446 – 001

Full Assembly	Yes
Plug-and-Play Install	Yes
STC/TSO Approved	Yes
Current Draw (less than bulbs)	50%
Brighter (than bulbs)	30%
Aircraft mods required	None

Compatibility:

B300/350: All Serial Numbers

C90: LJ-1063 thru LJ-1846

C90GT: LJ-1847 and later

E90: LW-200 and later

F90: All

B200: BB-1133, BB-1141, BB-1145 and later

B200C: BL-37 thru BL-72, BL-124, and later

B200GT: BY-001 and later

300: FA-001 and later

1900: All UA, UB, UC

(not compatible on B200 with winglets)