
Heat release rate from timber combustion
Heat release rate from burner
Heat loss rate to lining
Heat loss rate to specimen
Heat loss rate to windows
Heat loss rate to ventilation
Heat loss rate to internal gas
4000
2000
0
−2000
−4000
Heat rate [MW]
0
20
40
60
80
100
120
Time [min]