


Why do we use rice husk for grain dryer furnaces?

Rice husk is cheap and lowers drying cost, thus making mechanical drying competitive. As a waste of the rice milling process, the cost of acquiring rice husk is practically its transportation cost to the dryer.




What are the types of rice husk furnace?

Two furnace designs are shown below, both with inclined grates. The box-type furnace does not do as good a job of settling ashes as the furnace with cylindrical chamber and center pipe.



Schematic of the box-type inclined grate furnace.



Schematic of the furnace with cylindrical combustion chamber (of the SHG-4 and SHG-8 dryers).

IRRI, in cooperation with Nong Lam Univeristy (NLU), has recently upscaled the Hohenheim-type inverted draft automatic furnace, which enables each rice husk feeding to last to 1 whole hour. The burning is even, keeping the drying temperature constant. The furnace can be matched with the SHG-4 four-ton dryer.

Components of a rice husk furnace

- 1) Hopper to contain rice husk
- 2) Grate to support the rice husk layer in burning
- 3) Primary combustion chamber to burn the charred carbon in the husk
- 4) Secondary combustion chamber to burn the volatile matter ("smoke") released from the husk
- 5) Ash pit to contain ash, for periodic removal

Hohenhein type inverted draft automatic furnance

Firing a rice husk furnace

Put a layer of husk on the grate. Shut the feeding gate

With the dryer fan OFF, use pieces of paper to burn the husk on the grate. When enough husk is ignited with the fire visible, turn the fan ON; open the feeding gate. Periodically (after about 5 min), check to see if the husk flow is not interrupted; remove the ash if the ash pit is full. The furnace should burn without smoke or fly ashes.

Learn More

Visit Rice Based Cropping Systems Knowledge Bank www.rkbodisha.in



