# CORKTOWN AUDIO WORKS

17241 Prairie St, Detroit, MI 48221 | (313) 555-0147 | kofi@corktownaudio.com

## BENCH REPORT

Service and function test

| SKU | UNIT | BENCH DATE | TECHNICIAN |
|---|---|---|---|
| CAW-1068 | Sony TC-K61 cassette deck | 2026-08-04 | Kofi Mensah |

### INCOMING CONDITION

Powers up; meters and lamps light. In play the transport ran slow and unsteady, the take-up reel stalled and fast wind was weak. Both belts stretched and glazed. Heads and tape path coated with oxide.

### WORK PERFORMED

1. Capstan belt and reel belt replaced.
2. Idler cleaned; grips the reel tables without slipping.
3. Heads cleaned and demagnetized. Capstan, pinch roller and tape guides cleaned.
4. Transport lubricated: capstan bearing and lever pivots, light oil, none on the rubber.
5. Tape speed set against the 3 kHz test tape.

### MEASUREMENTS

| Test | Method | Reading | Result |
|---|---|---|---|
| Tape speed | 3 kHz test tape, playback | 3,006 Hz (+0.2%) | Pass |
| Wow and flutter | 3 kHz test tape, weighted RMS | 0.06% WRMS | Pass |
| Playback level | Test tape level tone, left vs right | L/R within 0.5 dB | Pass |
| Record/play | Type I and Type II tape, Dolby NR on and off | Clean, no dropouts | Pass |

### FUNCTIONAL CHECKS

| Check | Result |
|---|---|
| Transport, all modes: play, stop, pause, record, fast forward, rewind, eject | OK |
| Tape counter and counter reset | OK |
| Level meters, both channels | OK |
| Lamps | OK |

### RESULT

**Signed off:** Kofi Mensah, bench tech, 2026-08-04

**PASS. All functions to spec.**

*Cosmetic grade is set from the master photos against Grading Guide v3. Ready for master photos.*