Sesión Laboratorio de Robótica – Scorbot (III)

Durante esta tercera sesión realizamos un proyecto libre en conjunto con otro grupo, poniendo en práctica los conocimientos que hemos adquirido en las sesiones anteriores.

Clasificación de piezas: madera o metal

El ejercicio que nos hemos propuesto realizar es un clasificador de piezas según sean de madera o de metal. Para ello nos servimos principalmente del sensor inductivo, que detecta las piezas de metal, activando su salida cuando la pieza es de metal.

El funcionamiento es el siguiente: las piezas, de madera y metal, están almacenadas a un lado de la mesa (el de nuestro grupo). En la cinta están puestos el sensor inductivo y un sensor óptico para detectar la presencia de las piezas. Nuestro robot va cogiendo piezas y las deja sobre la cinta. Cuando el robot deja la pieza en la cinta y se retira a una posición segura, la cinta se pone en marcha (el eje de la cinta lo controlamos nosotros). La cinta se ejecuta en un subprograma, CINTA, que se ejecuta hasta que se activa nuestra entrada 14. Es la correspondiente al sensor óptico. Lo único que hace el programa CINTA es activarla y moverla. Al activarse IN[14], salta un TRIGGER STOPC, que para la cinta, y si se ha detectado un objeto, activa nuestra salida OUT[6] para avisar al otro robot de que hay un objeto, y si además es de metal, activa nuestra salida OUT[5] para avisarlo también de eso.

Realizado eso, pueden suceder dos cosas:

Que la pieza no sea de metal, en cuyo caso nuestro robot, que está ya en una posición de seguridad, queda esperando a que el otro robot termine, para coger otra pieza y empezar de nuevo el proceso. El otro robot recibe nuestra señal OUT[6] y toma la pieza, y, como no ha recibido nuestra OUT[5], se la lleva a su lado de la mesa y la almacena.

Que la pieza sea de metal. Entonces el otro robot toma la pieza y se dirige a la posición de encuentro de los robots. Nuestro robot espera a que el otro esté en posición, y se aproxima (en dos pasos) para recoger la pieza en el aire. La tomamos, y enviamos una señal OUT[10] para avisar de que la hemos cogido. Entonces quedamos a la espera de la señal IN[2] del otro robot, que nos avisa de que ya ha soltado la pieza. Concluido esto, él se aleja y nosotros nos llevamos la pieza a nuestro lado de la mesa, para su almacenamiento.

Este proceso se puede repetir indefinidamente.

Código

```
$v 1 AUX 0

$v 2 PINZA 1

$v 3 TIMEA 808

$v 4 TIEM 0

$v 5 VAR 808

$p 1 1 0 0 0 0 0 0 0

$p 2 1 POS1 -4771 10675 -10138 -1054 1033 0

$p 3 1 POS2 -4772 13444 -10855 -1057 1032 0

$p 4 1 POS3 -1812 11259 -9388 -1914 185 0
```

```
$р
   5
      1 POS4 -1814 14012 -9880 -1917 184 0
      1 ZERO -2366 8038 -7342 -1914 185 0
$p
   6
$р
   7
      1 POS6 -3021 12703 -13756 -4077 -1974 0
      1 POS5 -3018 9466 -12527 -4075 -1972 0
$р
   8
      1 POS8 2937 13141 -11726 -2364 -197 0
$р
   9
$p
       1 POS7 2937 10281 -10860 -2360 -193 0
   10
$p
   11
       1 POS10
               5234 13284 -11420 -2815 -642 0
$р
   12
       1 POS9 5233 10460 -10629 -2812 -640 0
   13
               4273 11940 -12219 -4272 -2481 0
$p
       1 POS12
   14
       1 POS11
               3952
                     9395 -10255 -4445 -2338 0
$р
       1 AUX1 32767 0 0 0 0 0
$р
   15
$р
   16
       1 AUX2 4272 8960 -10784 -4270 -2480 0
$р
   17
       1 AUX 4273 11940 -12219 -4272 -2481 0
       1 REST -3357 4910 -3611 -1914 185 0
$p
   18
   19
       1 INT -12116 11018 -5829 -4741 -2688 0
$р
       1 INT2 -11989 8738 -4796 -4739 -2687 0
$p
   20
$р
   21
       1 AUX3 -2366 8038 -7342 -1914
                                     185 0
   22
       1 POS20 -3052 14204 -9395 -1914
$р
                                        185 0
   23
       1 POS21 -3051 11449 -8979 -1911
$p
                                        187 0
$p
   24
       1 POS22
               1534 15317 -7999 -1914
                                        185 0
               1533 12274 -8094 -1911 187 0
$р
   25
       1 POS23
$р
   26
       1 A -4037 16705 -10504 -8363 -1846 0
   27
       1 B -14558 6894 -5642 -3913 -1966 0
$р
   28
       1 CINTA -14559 8587 -7977 -3916 -1968 0
$р
$р
   29 1 APRA -3200 10654 -10214 -2919 1185 0
   1 2 00 0 0 0 0 0 0
$р
$p
   2
      2 AM -12679 0 -1 -1 -1 0
    1 P3
$pr
$pr
    2 P4
    3 P5
$pr
$pr
    4 CERCA
$pr
    5 LEJOS
$pr
    6 COGER
    7 SOLTA
$pr
$pr
    8 P21
    9 P22
$pr
    10 P23
$pr
    11 STOP
$pr
    12 RECU
$pr
$pr
    13 P232
$pr
    14 P24
$pr
    15 BOTON
    16 P242
$pr
    17 P25
$pr
$par
     1 -400 120 333 0 0 50 12 30
$par
     9 0 44 0 0 0 0 0 0
     17 0 0 0 0
                 200
                      200 200 250
$par
    25 250
              180 700 700 700
                                 700
$par
                                      700 0
     33 12770 -10216
                      10216 5022 5022 0 0 0
$par
        250
             250 250 300 300 500
$par
     41
                                      500
$par 49 500 500 500 0
                          13653 -2867
                                      1773 0
$par
     57 0 0 0 0 1000 2500 2500 1200
```

```
$par 65 1200 1500 1200 1200 1200 1200 1
   73 5400 0 3500 5 0 1 2 0
$par
$par 81 0 0 0 0 0 0 0
$par 89 0 0 0 0 160 3490 2210 2210
$par 97 1450 0 0 0 24330 17160 21000 16000
$par 105 16000 32767 32767 32767 32767 32767 32767 0
$par 113 0 0 0 0 0 0 0
$par 121 -18830 -400 -32000 -16000 -16000 -32768 -32768 -32768
$par 129 -32768 -32768 -32768 0 0 0 0 0
$par 137 0 0 0 0 3000 3000 3000 3000
       3000 3000 16000 16000 16000 16000 0
$par 145
$par 153 0 0 0 0 0 0 0
$par 169 4500 4500 4500 0 0 0 0
$par 177 0 0 0 0 5 5 3 5
       5 25 10 10 10 10 10 0
$par 185
$par 193 0 0 0 0 0 0 0
$par 209 3000 3000 3000 0 0 0 0
$par 217 0 0 0 0 4500 6000 6000 3000
       3000 6000
                3000 3000 3000
$par 225
                              3000 3000 0
$par 233 0 0 0 0 0 0 0
$par 241 24 24 30 24 24 12 5 5
$par 249 5 5 5 0 0 0 0
$par 257 0 0 0 0 20 20 20 20
$par 265 20 10 10 10 10 10
                         10 1
$par 273 0 0 0 0 0 0 0
$par 289 4000 4000 4000 0 0 8000 50 40
$par 297 50 30 660 15 0 0 0 0
$par 305 0 0 0 0 0 0
```

PROGRAM CERCA ***********

SPEED 70
SETP AUX2=AUX
SHIFTC AUX2 BY Z 1000
SETP AUX3=AUX2
MOVED AUX2
END

SPEED 70
SETP AUX3=ZERO
MOVED ZERO
END

 SPEED 25

OPEN

SET PINZA = 1 SETP AUX3=AUX

MOVELD AUX

CLOSE

SET PINZA = 0 SETP AUX3=AUX2

MOVELD AUX2

END

PROGRAM SOLTA

SPEED 25

SETP AUX3=AUX

MOVELD AUX

OPEN

SET PINZA = 1 SETP AUX3=AUX2

MOVELD AUX2

END

PROGRAM P21

MOVED ZERO SETP AUX=POS2 GOSUB CERCA COGER GOSUB GOSUB LEJOS AUX=POS8 SETP GOSUB CERCA GOSUB SOLTA GOSUB LEJOS SETP AUX=POS4 CERCA GOSUB GOSUB COGER GOSUB LEJOS AUX=POS10 SETP GOSUB CERCA SOLTA GOSUB GOSUB LEJOS AUX=POS6 SETP GOSUB CERCA GOSUB COGER GOSUB LEJOS SETP AUX=POS12 CERCA GOSUB

SOLTA

LEJOS

GOSUB

GOSUB

ZERO MOVED END

PROGRAM P22

SET OUT[1] = 1WAIT IN[1] = 1SET OUT[1] = 0

GOSUB P21

END

PROGRAM P23

SET OUT[1] = 1WAIT IN[1] = 1OUT[1] = 0SET STOP BY IN 1 0 TRIGGER

GOSUB P21

END

PROGRAM STOP

STOP P23

CLRBUF

25 SPEED REST MOVED

END

PROGRAM RECU

PINZA = 0IF SUSPEND P232 25 SPEED MOVED INT2 INT MOVELD OPEN MOVELD INT2 SPEED 70 MOVED REST IN[1] = 1WAIT MOVED INT2 SPEED 25 MOVELD INT CLOSE

MOVELD INT2 70 SPEED

MOVED AUX3

ENDIF

```
PINZA = 1
 SUSPEND P232
        25
 SPEED
         REST
 MOVED
 WAIT
         IN[1] = 1
         AUX3
 MOVED
ENDIF
CONTINUE P232
END
             PROGRAM P232
             ******
SET
       OUT[1] = 1
       IN[1] = 1
WAIT
       OUT[1] = 0
SET
TRIGGER RECU BY IN 1 0
GOSUB
       P21
END
             PROGRAM P24
             ******
PEND
       TIEM = 0
       VAR FROM TIEM
PRINTLN
        VAR
       VAR > 300
 MOVED
         ZERO
         70
 SPEED
       POS1
 MOVED
 OPEN
       25
<del>-</del>
 SPEED
 MOVED
         POS2
 CLOSE
       POS4 TIMEA
 MOVED
 MOVED
         POS2 TIMEA
 OPEN
         25
 SPEED
         POS1
 MOVED
          70
 SPEED
 MOVED
         ZERO
ELSE
 PRINTLN
          "Tiempo insuficiente"
         70
 SPEED
 MOVED
         ZERO
ENDIF
END
             PROGRAM BOTON
```

IN[4] = 1WAIT

```
TIMEA = TIME
SET
WAIT
         IN[1] = 0
SET
         TIMEA=TIME - TIMEA
END
               PROGRAM P242
               ******
         P24
RUN
WAIT
        IN[1] = 1
         TIMEA = TIME
SET
WAIT
         IN[1] = 0
         TIMEA=TIME - TIMEA
SET
         TIMEA TO TIEM
POST
END
               PROGRAM P25
               *****
         ZERO
MOVED
         70
SPEED
MOVED
         APRA
         25
SPEED
OPEN
MOVED
         Α
CLOSE
MOVED
         APRA
SPEED
         70
MOVED
        В
        25
SPEED
        CINTA
MOVELD
OPEN
MOVELD
         В
         OUT[7] = 1
SET
         ANOUT[7] = 800
SET
        100
DELAY
         ANOUT[7] = 2000
SET
DELAY
         300
         ANOUT[7] = 800
SET
DELAY
         100
         ANOUT [7] = -1000
SET
DELAY
         200
         ANOUT [7] = -2000
SET
DELAY
         400
SET
         ANOUT[7] = -1000
DELAY
         200
         OUT[7] = 0
SET
SPEED
         25
MOVELD
         CINTA
CLOSE
MOVELD
         В
```

70

SPEED

```
MOVED
         APRA
          25
SPEED
MOVED
          Α
OPEN
MOVED
        APRA
         70
SPEED
MOVED
          ZERO
END
(END)
```

Código del otro grupo:

```
$v 1 POSR2 0
  1 1 0 0 0 0 0 0 0
$р
$p 2
     1 POUT 2021 11719 -9133 -659 655 0
$p 3 1 POS1 -13335 9863 -5942 1114 2278 0
$p 4 1 POSR -11690 6545 363 -2943 -6072 0
$p 5 1 POSH 1967 5490 -5785 -713 41 0
$p 6 1 POUT1 32767 0 0 0 0
$p 7 1 POS2 2025 13635 -9464 -668 650 0
$p 8 1 POSR2 -11690 6545 363 -2415 -6960 0
$p 9 1 POUT2 -13330 8977 -4476 1105 2269 0
$p 10 1 POFF -13330 8977 -4476 1105
                                   2269 0
  1 2 00 0 0 0 0 0 0
$pr 1 CARGA
$pr 2 DESCA
$pr 3 METAL
   4 PROG
$pr
   5 CMET
$pr
$par 1 -400 120 333 0 0 50 12 30
$par 9 0 44 0 0 0 0 0
$par 17 0 0 0 0 200 200 200 250
$par 25 250 180 700 700 700 700 700 0
$par 33 12770 -10216 10216 5022 5022 0 0 0
$par 41 250 250 250 300 300 500 500 500
$par 49 500 500 500 0 13653 -2867
                                   1773 0
$par 57 0 0 0 0 1000 2500 2500 1200
$par 65 1200 1500 1200 1200 1200 1200 1
$par 73 5400 0 3500 5 0 1 2 0
$par 81 0 0 0 0 0 0 0
$par 89 0 0 0 0 160 3490 2210 2210
$par 97 1450 0 0 0 24330 17160 21000 16000
$par 105 16000 32767 32767 32767 32767 32767 32767 0
$par 113 0 0 0 0 0 0 0
$par 121 -18830 -400 -32000 -16000 -16000 -32768 -32768 -32768
$par 129 -32768 -32768 -32768 0 0 0 0 0
$par 137 0 0 0 0 3000 3000 3000 3000
              3000 16000 16000 16000 16000 0
$par 145
        3000
$par 153 0 0 0 0 0 0 0
         4500
              4500 4500 4500 4500 4900 4500 4500
$par 161
$par 169 4500
              4500 4500 0 0 0 0
$par 177 0 0 0 0 5 5 3 5
```

\$par 185 5 25 10 10 10 10 10 0 \$par 193 0 0 0 0 0 0 0 0 \$par 209 3000 3000 3000 0 0 0 0 \$par 217 0 0 0 0 4500 6000 6000 3000 3000 3000 3000 \$par 225 3000 6000 3000 3000 0 \$par 233 0 0 0 0 0 0 0 \$par 241 24 24 30 24 24 12 5 5 \$par 249 5 5 5 0 0 0 0 0 \$par 257 0 0 0 0 20 20 20 20 \$par 265 20 10 10 10 10 10 10 1 \$par 273 0 0 0 0 0 0 0 \$par 289 4000 4000 4000 0 0 8000 50 40 \$par 297 50 30 660 15 0 0 0 0 \$par 305 0 0 0 0 0 0

OPEN SHIFTC POUT BY Z 700 SPEED 50 POUT MOVED 20 SPEED POUT BY Z -700 SHIFTC MOVED POUT CLOSE SHIFTC POUT BY Z 700 MOVED POUT

END

OUT[7] = 0SET POUT BY Z 700 SHIFTC 40 SPEED MOVED POUT 20 SPEED POUT BY Z -700 SHIFTC POUT MOVED OPEN SET OUT[11] = 1POUT BY Z 700 SHIFTC MOVED POUT END

STOP PROG

		_
Laboratorio		
Tanorarono	UB KUDULIC	1 — SCORNOI

Pablo Carmona Benito

	_			
4º	\sim		2 N 7	
4=	ודא	ICE	₹IVI	

```
OPEN
WAIT
        IN[2] = 1
SETP
        POUT=POS1
GOSUB
        CARGA
        40
SPEED
MOVED
        POSR
SET
        OUT[5] = 1
WAIT
        IN[4] = 1
OPEN
MOVED
       POSR2
        OUT[6] = 1
SET
MOVED
         POSH
SET
         OUT[5] = 0
         OUT[6] = 0
SET
GOSUB
         PROG
END
              PROGRAM PROG_
              ******
LABEL
        1
         OUT[5] = 0
SET
SET
         OUT[6] = 0
        OUT[11] = 0
SET
        POSH
MOVED
TRIGGER METAL BY IN 1 1
        IN[2] = 1
WAIT
SETP
        POUT=POS1
GOSUB
        CARGA
SETP
        POUT=POS2
GOSUB
        DESCA
GOTO
END
```

OPEN
SPEED 60
MOVED POUT2
SPEED 30
MOVED POUT
CLOSE
MOVED POUT2
END
(END)