## **Solution for Exercise 3**

You can just **copy paste the solution** from the text below

```
//Program
//-----Version 1.1
//----Author: Rajvir
/*
Write a PLC program that monitors various sensors in
a facility.
If any sensor detects an abnormal condition, such as
a high level
or low level an alarm should be triggered.
*/
//read inputs
xSensor1 := _IO_EM_DI_00;
xSensor2 := _IO_EM_DI_01;
xSensor3 := _IO_EM_DI_02;
xReset := _IO_EM_DI_03;
if (xSensor1 OR xSensor2 OR xSensor3) THEN
    iTemp := 99;
END_IF;
```

```
if (iTemp = 99 AND xReset) THEN
    iTemp := 0;
END_IF;

xAlarm := iTemp = 99;

//Write outputs
_IO_EM_DO_00 := xAlarm; //Alarm
```