STEPS TO CREATE CONTROL CHART (C CHART) ON MINITAB (ACTIVITY SOLUTION)



DISCLAIMER: SOME STEPS MAY SLIGHTLY DIFFER BASED ON YOUR MINITAB VERSION

- 1. Open the Excel Sheet "Control Chart Data_No. of Errors".
- 2. Copy data from the excel sheet to the Minitab worksheet.
- 3. Choose Stat > Control Charts > Attributes Charts > C.
- 4. In Variables, enter No. of Employees late to work then click OK.

Graph window output

