
STEPS TO MEAN, MEDIAN, MODE & STANDARD DEVIATION ON MINITAB




DISCLAIMER: SOME STEPS MAY SLIGHTLY DIFFER BASED ON YOUR MINITAB VERSION

STEP 01: PASTE DATA IN COLUMN C1 OF THE WORKSHEET



STEP 02: CLICK <u>STAT</u> -> <u>BASIC STATISTICS</u> -> <u>DISPLAY DESCRIPTIVE</u> <u>STATISTICS</u>




STEP 03: IN DISPLAY DESCRIPTIVE STATISTICS WINDOW, OBSERVE IF THE CURSOR IS BLINKING INSIDE THE "VARIABLES" BOX


IF THE CURSOR IS BLINKING INSIDE THE BOX. GO TO STEP 04

 IF THE CURSOR IS NOT BLINKING INSIDE THE BOX, CLICK INSIDE THE BOX SO THAT THE CURSOR STARTS BLINKING THERE, THEN GO TO


STEP 04




STEP 04: DOUBLE-CLICK ON "C1 AHT DATA". AS YOU DO THIS STEP, YOU WILL OBSERVE THAT THE VARIABLES BOX IS UPDATED WITH "AHT DATA" AS SHOWN IN THE SCREENSHOT BELOW:




STEP 04: CLICK ON THE "STATISTICS" BUTTON, A NEW WINDOW WILL POP-UP CALLED "DISPLAY DESCRIPTIVE STATISTICS – STATISTICS"



STEP 05: IN THE "DISPLAY DESCRIPTIVE STATISTICS – STATISTICS WINDOW", ENSURE THAT ONLY MEAN, STANDARD DEVIATION, MEDIAN & MODE ARE CHECKED. UNCHECK EVERYTHING ELSE. THEN CLICK OK.



STEP 06: IN THE "DISPLAY DESCRIPTIVE STATISTICS" WINDOW, CLICK OK



Copyright © Smart Growth Hacks

STEP 07: YOU WILL RECEIVE THE FOLLOWING OUTPUT IN THE SESSION WINDOW:

- MEAN = 200.22
- STANDARD DEVIATION = 19.27
- MEDIAN = 200..70
- MODE = * (I.E. THERE IS NO MODE IN THIS DATA)

