## STEPS TO CREATE PIE CHART ON MINITAB



DISCLAIMER: SOME STEPS MAY SLIGHTLY DIFFER BASED ON YOUR MINITAB VERSION

- 1. Open the Excel Sheet "Data Line Chart.xlsx".
- 2. Copy & paste data from Excel to Minitab.
- 3. Choose **Graph > Pie Chart**.
- 4. Choose Chart values from a table.
- 5. In **Categorical variable**, enter *Team*. In **Summary variables**, enter *Average Handle Time*.
- 6. Click **Pie Chart Options**. Under **Order slices by**, choose **Decreasing volume**. Click **OK**.
- 7. Click **Labels**. Click the **Slice Labels** tab.
- 8. Under Label pie slices with, check Category Name and Percent.
- 9. Click **OK** in each dialog box.

## Graph window output

