Little advice

Great! That you have completed Structures and UDT. Now I would suggest you the following:

Optimize your old PLC Programs with:

- 1. Database (DBIn_Out): Read the PLC tags in the DB
- 2. Define UDT with structures
- 3. Organize the DB with UDT and Structures
- 4. Update the tagging and run your program

I am sure you will get a good feeling about it :)

Cheers!