


LECTURE


SEVEN
INDICATORS
OF AN OUTOF-CONTROL
PROCESS


SIX SIGMA WHITE BELT















Eight Consecutive Points On One Side Of The Average



Fourteen Consecutive Points In An Up
And Down Pattern







Copyright © Smart Growth Hacks | All Rights Reserved

SMART GROWTH HACKS

DEDICATED TO YOUR CAREER SUCCESS