

LECTURE

STEPS TO CREATE THE CHECK SHEETS?

SIX SIGMA WHITE BELT












DOCUMENT THE OPERATIONAL DEFINITION OF THE METRIC











Copyright © Smart Growth Hacks | All Rights Reserved









Defect Types	Day							Takal
	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	Sunday	Total
Defect 1								
Defect 2								
Defect 3								
Defect 4								
Defect 5								
Defect 6								
Defect 7								
Defect 8								
Defect 9								
Defect 10								

SMART GROWTH HACKS

DEDICATED TO YOUR CAREER SUCCESS