

Ford F-150 2023 Owner's Manual

Model Year: 2023 | Make: Ford | Model: F-150

Table of Contents

1. Engine Maintenance
2. Transmission
3. ADAS Safety Systems
4. Fault Codes Reference

Engine Maintenance

The 3.5L EcoBoost V6 engine requires synthetic 5W-30 oil. Oil change intervals are every 7,500 miles under normal driving conditions. The engine temperature should remain between 195degF and 220degF (90degC-104degC) during normal operation. If the temperature gauge exceeds the midpoint, pull over safely immediately.

Diagnostic Code P0300 indicates a random or multiple cylinder misfire. Common causes include worn spark plugs, faulty ignition coils, or low fuel pressure. The F-150 uses COP (Coil-On-Plug) ignition. Replace spark plugs every 60,000 miles with Motorcraft SP-515 plugs.

Transmission

The 10-speed SelectShift automatic transmission fluid should be checked at 150,000 miles under normal conditions. Use only Motorcraft MERCON ULV fluid. Code P0700 indicates a Transmission Control System malfunction - schedule service immediately as continued driving may cause irreversible damage.

Towing capacity: 13,200 lbs with Max Trailer Tow Package. Ensure trailer brakes are functional when towing over 5,000 lbs.

ADAS Safety Systems

The Ford Co-Pilot360 system includes Pre-Collision Assist with Automatic Emergency Braking (AEB), Lane-Keeping System, Auto High-Beam Headlamps, and Reverse Sensing System.

If the FORWARD_COLLISION_WARNING alert triggers repeatedly, check for obstruction on the front radar sensor (located behind the Ford logo). Clean the sensor with a soft damp cloth. Recalibration may be required after windshield replacement - visit a certified Ford service center.

Fault Codes Reference

P0300 - Random/Multiple Cylinder Misfire: Check spark plugs, ignition coils, fuel injectors.

P0420 - Catalyst Efficiency Below Threshold: Catalytic converter may require replacement.

P0171 - System Too Lean Bank 1: Check for vacuum leaks, faulty MAF sensor, or low fuel pressure.

P0455 - EVAP System Large Leak: Inspect gas cap seal, EVAP canister, and purge valve.

U0100 - Lost Communication with ECM: Check battery voltage and CAN bus connections.