

GENERAL NOTES:

- 1 ALL COMPONENT & EQUIPMENT NUMBERS ARE PRECEDED BY "7B" TO REPRESENT THE BULK DRUG SUBSTANCE (BDS) BUILDING.
- 2 ALL AUTOMATIC VALVES FAIL CLOSED (F.C.) UNLESS NOTED FAIL OPEN (F.O.).
- 3 ALL PLC/COMPUTER CONNECTIONS ARE WITHIN THE PCS UNLESS OTHERWISE NOTED.
- 4 LAST LINE NUMBER:
- 5 LINE NUMBER NOT USED:
- 6 LAST AUTO VALVE NUMBER: XV-640107 7 AUTO VALVE NUMBERS NOT USED:
- XV-640101 8 LAST MANUAL VALVE NUMBER: HV-640163
- SV-640107 9 MANUAL VALVE NUMBERS NOT USED: HV-640105, 13, 41 SV-640101, 02

## SHEET NOTES

- 1 ADJUST VALVE OPENING STOP TO MATCH FLOW RATE LISTED IN POINT-OF-USE DESCRIPTION BOX. 2 LOCATE VALVES AND REGULATORS AT OPERATOR
- LEVEL FOR ERGONOMIC ACCESS (TYPICALLY 1220 MM TO 1525 MM ABOVE FINISHED FLOOR). 3 HOLD PENDING SAMPLING ACCESSIBILITY ASSESSMENT PRIOR TO CONSTRUCTION ISSUE.

INTERLOCKS

INTERLOCK LOOP VALVES WITH WFI GENERATION SKID STATUS. IF HWFI IS OUT OF SPEC (TOC, CONDUCTIVITY, GENERAL ALARM) LOCK VALVES.



Project Services Engineering Design/Build

Compliance Consulting

Suite 100 BLUE BELL, PA 19422 PHONE: (610) 828-4090 FAX: (610) 828-3656 www.ipsdb.com IPS Professional Engineers and Architects, LLC.

721 Arbor Way

SION	DATE	DESCRIPTION	BY
4	01JUL2020	50% BD ISSUE	DLS
3	28AUG2020	90% BD ISSUE	JJR
	27NOV2020	DESIGN ISSUE	JJR
)	12FEB2021	30% DD ISSUE	RLD
Ξ	12AUG2021	90% DD ISSUE	RLD
= [	16SEP2021	90% DD ISSUE	RLD
)	08OCT2021	CONSTRUCTION ISSUE	RLD



R. Dr. Cesário Mota Júnior, 424 - Vila Buarque, São Paulo - SP, 01221-020

REVISION HISTORY

1 REV. 0 - NONE.

CONFIDENTIAL THE INFORMATION CONTAINED HEREIN MAY NOT BE USED OR REPRODUCED IN ANY MANNER WITHOUT WRITTEN PERMISSION OF INTEGRATED PROJECT SERVICES.



**BURITI EPCMV** 

**P&I DIAGRAM DRUG SUBSTANCE HOT WFI** 

DISTRIBUTION

XREF FILE(S) DRAWING NUMBER

7B-Z-0-2-61

ISSUED FOR CONSTRUCTION

Robert L. De Somei Tr.

THIS IS NOT A SEALED DOCUMENT