







DOC NR.:	SHEET.
569-DB7A-AIC-310-002	
DOC NR.:	REV.:
DDD AIC LIC 044	_

		INSTRUMENT INDEX - EMS /A	PRD-AIC-LIS-	011	0
1- THIS LIST WAS PREPARED IN ACCORDA	NCE WITH THE "DRUG PRODUCT EMS ARCHITECTURE",	, DRAWING NUMBER 7A-I-0-7-03			
	REVISION 0 - NOTES				
	1. ADDED PDIT-A2041-02 & PDIT-A2025-03				
	1. ADDED PDIT-A2041-02 & PDIT-A2025-03				

				TITLE:			DOC NR.:		SHEET.:			
TESSIER - C						569-DB7A-AIC-310-002						
□ = □	TESSLER Engenharia ips (Takeda) Hemobrás						CLIENT NR.:					
C prosecular to de None contracte e batterio e contracte e batterio e contracte e contract				INSTRUMENT	T INDE	EX - EMS 7A	PRD-AIC-LIS-011					
				P&ID	LOC.		ELEMENTARY DRAWING					
ID	REV	TAG Nr.	SERVICE	LINE OR EQUIP	(*)	SPECIFICATION SHEETS	WIRING DIAGRAM	ROUTES DRAWING	NOTES			
			TEMPERATURE TRANSMITTER PRINTER	LINE ON EQUIP	()							
1	0	TIT-A1002-01	TEMPERATURE TRANSMITTER - PRINTED	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11	7A-I-1-3-11	1			
			MATERIALS ROOM A1002				7A-I-0-3-07					
2	0	IMII-Δ1002-01	HUMIDITY TRANSMITTER - PRINTED	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11	7A-I-1-3-11	1			
			MATERIALS ROOM A1002 TEMPERATURE TRANSMITTER - INBOUND				7A-I-0-3-07 7A-I-0-3-11					
3	0	TIT-A1004-01	STAGING ROOM A1004	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-1-3-15	1			
-			HUMIDITY TRANSMITTER - INBOUND STAGING				7A-I-0-3-07 7A-I-0-3-11					
4	0	IMIT_A1001_01	ROOM A1004	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-1-3-15	1			
			TEMPERATURE TRANSMITTER - STAGING				7A-I-0-3-07 7A-I-0-3-11					
5	0	TIT-A1006-01	INSPECTED - ROOM A1006	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-1-3-15	1			
			HUMIDITY TRANSMITTER - STAGING				7A-I-0-3-07 7A-I-0-3-11					
6	0	MIT-A1006-01	INSPECTED - ROOM A1006	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-1-3-15	1			
			TEMPERATURE TRANSMITTER -			+	7A-I-0-3-07 7A-I-0-3-11					
7	0	TIT-A1007-01	CONDITIONING STAGING - ROOM A1007	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-1-3-15	1			
			HUMIDITY TRANSMITTER - CONDITIONING		С		7A-I-0-3-07 7A-I-0-3-11					
8	0	IMI I - Δ 1 007-01	STAGING - ROOM A1007	7A-I-1-3-11		PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-1-3-15	1			
			TEMPERATURE TRANSMITTER - VISUAL		F		7A-I-0-3-07 7A-I-0-3-11					
9	9 0	TIT-A1019-01	INSPECTION ROOM A1019	7A-I-1-3-11		F	PRD-AIC-DSH-001	7A-I-0-3-07	7A-I-1-3-15	1		
		MIT-A1019-01	HUMIDITY TRANSMITTER - VISUAL		С		7A-I-0-3-11	7A-I-1-3-15				
10	0		INSPECTION ROOM A1019	7A-I-1-3-11		PRD-AIC-DSH-001	7A-I-0-3-07		1			
	<u> </u>	TIT-A1029-01	TEMPERATURE TRANSMITTER - PACKAGING		 _		7A-I-0-3-11					
11	0		ROOM A1029	7A-I-1-3-11 F	/A-I-1-3-11	/A-I-1-3-11	/A-I-1-3-11 F	F	l F	PRD-AIC-DSH-001	7A-I-0-3-07	7A-I-1-3-15
			HUMIDITY TRANSMITTER - PACKAGING		+ _		7A-I-0-3-11					
12	0	IMIT_A1N2Q_N1	ROOM A1029	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-07	7A-I-1-3-15	1			
		TIT-A1035-01	TEMPERATURE TRANSMITTER - 2-8°C	70.14.0.44	3-11 F	DDD AIO DOLL 004	7A-I-0-3-11	74 1 4 0 45				
13	0		STORAGE	7A-I-1-3-11			PRD-AIC-DSH-001	7A-I-0-3-07	7A-I-1-3-15	1		
		TIT 44007 04	TEMPERATURE TRANSMITTER - STAGING	70.14.0.44		DDD AIC DOLL 004	7A-I-0-3-11	70 14 0 45				
14	0	TIT-A1037-01	ROOM A1037	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-07	7A-I-1-3-15	1			
4.5		MIT-A1037-01	HUMIDITY TRANSMITTER - STAGING ROOM	70.14.0.44	 		_	DDD AIC DOLL 004	7A-I-0-3-11	74 14 0 45		
15	U	WIII-A1037-01	A1037	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-07	7A-I-1-3-15	1			
16	0	TIT-A1040-01	TEMPERATURE TRANSMITTER - AMBIENT	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11	7A-I-1-3-15	1			
10	U	111-A1040-01	STORAGE ROOM A1040	1 M-1-1-9-11		- LVD-410-D9U-001	7A-I-0-3-07	1 A-1-1-3-10	<u>'</u>			
17	Λ	MIT-A1040-01	HUMIDITY TRANSMITTER - AMBIENT STORAGE	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11	7A-I-1-3-15	1			
- ' '	L		ROOM A1040	1 1-0-11	'	1 1/0-1/10-0011-001	7A-I-0-3-07	1 A-1-1-0-10	'			
18	Λ	IPI)II-A7001-01	PRESSURE DIFERENTIAL TRANSMITTER -	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11	7A-I-2-3-25	1			
		1 DII A2001-01	CAPPING/TRAY OFF - ROOM A2001	77(11011		1 NO AIO DOI 1-001	7A-I-0-3-07	77.12.0-20	'			
19	0	TIT-A2001-01	TEMPERATURE TRANSMITTER -	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11	7A-I-2-3-25	1			
	ĻĽ	,	CAPPING/TRAY OFF - ROOM A2001			. 1.5 / 1.5 5511 661	7A-I-0-3-07	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
20	0	MIT-A2001-01	HUMIDITY TRANSMITTER - CAPPING/TRAY OFF	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11	7A-I-2-3-25	1			
	Ļ		- ROOM A2001				7A-I-0-3-07		•			
21	0	PDIT-A2002-01	PRESSURE DIFERENTIAL TRANSMITTER -	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11	7A-I-2-3-25	1			
	Ļ		ASSEPTIC STAGING - ROOM A2002		-		7A-I-0-3-07					
22	0	TIT-A2002-01	TEMPERATURE TRANSMITTER - ASSEPTIC	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11	7A-I-2-3-25	1			
	-		STAGING - ROOM A2002				7A-I-0-3-07					
23	0	MIT-A2002-01	HUMIDITY TRANSMITTER - ASSEPTIC STAGING	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11	7A-I-2-3-25	1			
			ROOM A2002				7A-I-0-3-07					

			Ī	TITLE:			DOC NR.:		SHEET.:
	ES	SLER PA	Takeda Hemobrás				569-DB7A-AIC-310-002		4/6
□ □ ∈	TESSLER Engenharia Takeda Il Hemobrás Erpresa brazile to de homo de				T INDE	Y - FMS 7A	CLIENT NR.:		
 				2012			PRD-AIC-LIS-011		
ID	REV	TAG Nr.	SERVICE -	P&ID	LOC.	SPECIFICATION SHEETS	ELEMENTARY DRAWING	ROUTES DRAWING	NOTES
			9=	LINE OR EQUIP	(*)		WIRING DIAGRAM		
24	0	101111-82023-01	PRESSURE DIFERENTIAL TRANSMITTER - QC STORAGE - ROOM A2023	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
25	0	TIT-A2023-01	TEMPERATURE TRANSMITTER - QC STORAGE ROOM A2023	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
26	0	IMI1-Δ2023-01	HUMIDITY TRANSMITTER - QC STORAGE ROOM A2023	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
27	0	101111-82025-01	PRESSURE DIFERENTIAL TRANSMITTER- FILLING ROOM A2025	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
28	0	TIT-A2025-01	TEMPERATURE TRANSMITTER- FILLING ROOM A2025	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
29	0	MIT-A2025-01	HUMIDITY TRANSMITTER- FILLING ROOM A2025	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
30	0	1D1111-82036-01	PRESSURE DIFERENTIAL TRANSMITTER - FORMULATION ROOM - ROOM A2036	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-l-0-3-11 7A-l-0-3-07	7A-I-2-3-25	1
31	0	TIT-A2036-01	TEMPERATURE TRANSMITTER - FORMULATION ROOM - ROOM 2036	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
32	0	IMIT-02036-01	HUMIDITY TRANSMITTER - FORMULATION ROOM - ROOM A2036	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-l-0-3-11 7A-l-0-3-07	7A-I-2-3-25	1
33	0	121111-8203/-01	PRESSURE DIFERENTIAL TRANSMITTER - BUFFER PREP - ROOM A2037	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
34	0	IMI1-Δ2037-01	HUMIDITY TRANSMITTER - BUFFER PREP ROOM A2037	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
35	0	TIT-A2037-01	TEMPERATURE TRANSMITTER - BUFFER PREP ROOM A2037	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-l-0-3-11 7A-l-0-3-07	7A-I-2-3-25	1
36	0	TIT-A2006-01	TEMPERATURE TRANSMITTER - MATERIAL STAGING ROOM A2006	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
37	0	IMIT-42006-01	HUMIDITY TRANSMITTER - MATERIAL STAGING ROOM A2006	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-l-0-3-11 7A-l-0-3-07	7A-I-2-3-25	1
38	0	1P1111_A2012_01	PRESSURE DIFERENTIAL TRANSMITTER- MATERIAL STAGING - ROOM A2012	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-l-0-3-11 7A-l-0-3-07	7A-I-2-3-25	1
39	0	TIT-A2012-01	TEMPERATURE TRANSMITTER - MATERIAL STAGING ROOM A2012	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
40	0	IMII-67017-01	HUMIDITY TRANSMITTER - MATERIAL STAGING ROOM A2012	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
41	0	TIT-A2014-01	TEMPERATURE TRANSMITTER - STAGING ROOM A2014	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
42	0	IMII-Δ201 <i>1</i> -01	HUMIDITY TRANSMITTER - STAGING ROOM A2014	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
43	0	TIT-A2008-01	TEMPERATURE TRANSMITTER - STORAGE ROOM A2008	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
44	0	1P1)11_A2003_01	PRESSURE DIFERENTIAL TRANSMITTER - CLEAN EQUIPAMENTE - ROOM A2003	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
45	0	1P1)11-A7004-01	PRESSURE DIFERENTIAL TRANSMITTER - PRE WASH - ROOM A2004	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
46	0	1P1)11-A2005-01	PRESSURE DIFERENTIAL TRANSMITTER - MAL OUT - ROOM A2005	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1

				TITLE:			DOC NR.:		SHEET.:
		SIEP .	100 Hamakuta	··· 			569-DB7A-AIC-310-002		5/6
e l	n q e	SLER ips	Takeda Hemobrás				CLIENT NR.:		REV.:
	_			INSTRUMEN [*]	T INDE	EX - EMS 7A	PRD-AIC-LIS-011		0
			- 		P&ID LOC			ELEMENTARY DRAWING	
ID	REV	TAG Nr.	SERVICE	LINE OR EQUIP	(*)	SPECIFICATION SHEETS	WIRING DIAGRAM	ROUTES DRAWING	NOTES
47	0	101111-77006-07	PRESSURE DIFERENTIAL TRANSMITTER - MAL OUT - ROOM A2005	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-l-0-3-11 7A-l-0-3-07	7A-I-2-3-25	1
48	0	DDIT-A2000-01	PRESSURE DIFERENTIAL TRANSMITTER- CIP/SIP - ROOM A2009	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
49	0	IPI) -Δ2017-01	PRESSURE DIFERENTIAL TRANSMITTER - GOWN DEGOWN - ROOM A2017	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
50	0	1P1111_A2017_02	PRESSURE DIFERENTIAL TRANSMITTER - GOWN DEGOWN - ROOM A2017	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
51	0	PDIT-A2026-01	PRESSURE DIFERENTIAL TRANSMITTER - MAL OUT - ROOM A2026	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-l-0-3-11 7A-l-0-3-07	7A-I-2-3-25	1
52	0	PDIT-A2027-01	PRESSURE DIFERENTIAL TRANSMITTER - MAL IN - ROOM A2027	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-l-0-3-11 7A-l-0-3-07	7A-I-2-3-25	1
53	0	PDIT-A2027-02	PRESSURE DIFERENTIAL TRANSMITTER - MAL IN - ROOM A2027	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-l-0-3-11 7A-l-0-3-07	7A-I-2-3-25	1
54	0	PDIT-A2028-01	PRESSURE DIFERENTIAL TRANSMITTER - JC ROOM A2028	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
55	0	PDIT-A2029-01	PRESSURE DIFERENTIAL TRANSMITTER - CLEAN STORAGE - ROOM A2029	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
56	0	PDI1-A2029-02	PRESSURE DIFERENTIAL TRANSMITTER - CLEAN STORAGE - ROOM A2029	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
57	0	PDIT-A2030-01	PRESSURE DIFERENTIAL TRANSMITTER - AIR LOCK - ROOM A2030	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-l-0-3-11 7A-l-0-3-07	7A-I-2-3-25	1
58	0	PDI1-A2030-02	PRESSURE DIFERENTIAL TRANSMITTER - AIR LOCK - ROOM A2030	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-l-0-3-11 7A-l-0-3-07	7A-I-2-3-25	1
59	0	PDIT-A2031-01	PRESSURE DIFERENTIAL TRANSMITTER - PAL OUT - ROOM A2031	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-l-0-3-11 7A-l-0-3-07	7A-I-2-3-25	1
60	0	PDIT-A2031-02	PRESSURE DIFERENTIAL TRANSMITTER - PAL OUT - ROOM A2031	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-l-0-3-11 7A-l-0-3-07	7A-I-2-3-25	1
61	0	PDIT-A2032-01	PRESSURE DIFERENTIAL TRANSM - PAL IN ROOM A2032	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-l-0-3-11 7A-l-0-3-07	7A-I-2-3-25	1
62	0	PDI1-A2032-02	PRESSURE DIFERENTIAL TRANSM - PAL IN ROOM A2032	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-l-0-3-11 7A-l-0-3-07	7A-I-2-3-25	1
63	0	PDIT-A2034-01	PRESSURE DIFERENTIAL TRANSMITTER - PAL OUT - ROOM A2034	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-l-0-3-11 7A-l-0-3-07	7A-I-2-3-25	1
64	0	PDI1-A2034-02	PRESSURE DIFERENTIAL TRANSMITTER - PAL OUT - ROOM A2034	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
65	0	PDIT-A2035-01	PRESSURE DIFERENTIAL TRANSMITTER - MAL OUT - ROOM A2035	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
66	0	PD11-A2035-02	PRESSURE DIFERENTIAL TRANSMITTER - 2 - MAL OUT - ROOM A2035	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
67	0	PDIT-A2038-01	PRESSURE DIFERENTIAL TRANSMITTER - PAL IN - ROOM A2038	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
68	0	1P1)11-47038-07	PRESSURE DIFERENTIAL TRANSMITTER - PAL IN - ROOM A2038	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1
69	0	1P1)11_A703Q_01	PRESSURE DIFERENTIAL TRANSMITTER - MAL IN - ROOM A2039	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1

				TITLE:			DOC NR.:		SHEET.:	
	res	SLER Inc	Takeda Hemobrás				569-DB7A-AIC-310-002		6/6	
TESSLER ips			Takeda Takeda Takeda Takeda Santa Sa	INSTRUMENT INDEX - EMS 7A			CLIENT NR.: PRD-AIC-LIS-011		REV.:	
ē	חבע	EV TAG Nr.	TAG No.	CEDVICE	P&ID	LOC.	LOC.	ELEMENTARY DRAWING	DOUTES DRAWING	NOTES
ID	KEV		TAG Nr. SERVICE	LINE OR EQUIP	(*)	(*) SPECIFICATION SHEETS	WIRING DIAGRAM	ROUTES DRAWING	NOTES	
70	0	PDIT-A2039-02	PRESSURE DIFERENTIAL TRANSMITTER - MAL IN - ROOM A2039	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1	
71	0	PDIT-A2040-01	PRESSURE DIFERENTIAL TRANSMITTER - JC ROOM A2040	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1	
72	0	PDIT-A2041-01	PRESSURE DIFERENTIAL TRANSMITTER - COMPONENT LOAD - ROOM A2041	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1	
73	0	PDIT-A2041-02	PRESSURE DIFERENTIAL TRANSMITTER - COMPONENT LOAD - ROOM A2041	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1	
74	0	PDIT-A2046-01	PRESSURE DIFERENTIAL TRANSMITTER - MAL IN - ROOM A2046	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1	
75	0	PDIT-A2025-03	PRESSURE DIFERENTIAL TRANSMITTER- FILLING ROOM A2025	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1	
76	0	TIT-FS-2001-01	TEMPERATURE TRANSMITTER FREEZER FS-2001 - ROOM A2049	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1	
77	0	TIT-FS-2002-01	TEMPERATURE TRANSMITTER FREEZER FS-2002 - ROOM A2014	7A-I-1-3-11	F	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1	
78	0	TIT-FR-3801-01	TEMPERATURE TRANSMITTER REFRIGERATOR FR-3801 - ROOM A2037	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1	
78	0	TIT-FR-3901-01	TEMPERATURE TRANSMITTER REFRIGERATOR FR-3901 - ROOM A2036	7A-I-1-3-11	С	PRD-AIC-DSH-001	7A-I-0-3-11 7A-I-0-3-07	7A-I-2-3-25	1	