SIEMENS

Correction File

Referenced eArtifact : IA_syngoWorkflowMLR_VB36A-HF09_CHARM_242470_IARecord

SY

Date of Correction : 2015-04-14

Correction File	
Document Type	CF
Date of correction	2015-04-14
ID Comment	1-CF

Referenced eArtifact	
Product	syngoWorkflowMLR
Version	VB36A-HF09
ID of eArtifact	IA_syngoWorkflowMLR_VB36A-HF09_CHARM_242470_IARecord
Type	IA
Title	IA_CHARM_242470_IARecord
Revision	n.a
Date	2015-03-25
Author	IN002\IC014048

Corrections :

Id	Finding	Description of the correction
1	[1] As per CM report the node numbers for the below elements are different. for SASRichEdit.java the node number as per CM report is 17 but IA shows 16. For SpeechControlUtils.java the node number as per Cm report is 4 but IA shows 3.	Please read file node as below: 1. \iwm\sources\iwm_portals\iwm_portals_common\src\main\java\de\siemens\med\pacs\iwm\client\speech\SpeechControlUtils.java@@\main\mlr_int_vb36a\mlr_portal_vb36a_dev\4 2. \iwm\sources\iwm_portals\iwm_portals_common\src\main\java\de\siemens\med\pacs\iwm\client\gui\SASRichEdit.java@@\main\mlr_int_vb36a\mlr_portal_vb36a_dev\19

Correction File

SY

Referenced eArtifact : IA_syngoWorkflowMLR_VB36A-HF09_CHARM_242470_IARecord

Date of Correction : 2015-04-14

Additional signature(s) :

Further remarks :

Responsible signer :

The signer(s) confirm(s) the validity of the taken corrective actions

Role	Name	Department	Date, Signature
DEV	M, MANOHAR	CT DC AA H1-FH PCP SY	