
(a) Proportion of Variance Explained (Scree Plot)
Cumulative PVE
Variance Explained (%)
100
80
60
40
20
0
46.8%
23.0%
PC1
PC2
(b) Factor Loadings Matrix ($\mathbf{W} \in \mathbb{R}^{4 \times 2}$)
Loading Weight
0.8
0.6
0.4
0.2
0.0
−0.2
−0.4
−0.6
PC1 Loading
PC2 Loading
Bearing 1
Bearing 2
Bearing 3
Bearing 4