

ZYXEL

Software Release Note Switch XGS1210-12

Date: Aug. 26, 2022



Zyxel Switch XGS1210-12 V1.00(ABTY.6)C0 Release Note

Date: Aug. 26, 2022

This document describes the features in the XGS1210 desktop product for its V1.00(ABTY.6)C0 release. Firmware upgrades may reset configuration options to factory default. Please backup your current configuration first before performing firmware upgrade.

Supported Platforms

Support Platform	Firmware version
Zyxel XGS1210-12	V1.00(ABTY.6)C0



New Feature and Enhancements

None

Bug fix

- 1. Fixed BN_mod_sqrt() of OpenSSL to cause infinite loop issue by upgrading OpenSSL version.
- 2. [eITS#220301352] Switch port speed will not change even click "Apply" button.



Known Issue

None

Change History

- V1.00(ABTY.6) | 08/26/2022
- V1.00(ABTY.5) | 11/12/2021
- V1.00(ABTY.4) | 06/10/2021
- V1.00(ABTY.3) | 06/03/2020
- V1.00(ABTY.2) | 03/02/2020
- V1.00(ABTY.1) | 02/19/2020
- V1.00(ABTY.0) | 11/26/2019