```
function configs = CellTtoConfig(data, grip)
  configs = zeros(length(data), 13);
  for i = 1:length(data)
      configs(i, :) = TtoConfig(data{i}, grip);
  end
end
```

```
Not enough input arguments.
Error in CellTtoConfig (line 2)
    configs = zeros(length(data), 13);
```

Published with MATLAB® R2021b