
Study Cards
What is the safety glass standard in the Canada ?
1. ASME
2. IEEE
3. CSA
4. ESA


Study Cards
What is the reading of Vernier Caliper in the Figure ?
1. 0.546
2. 0.344
3. 4.673
4. 0.466


Study Cards
When is the tool-box meeting shall be attended and how it should be ?
1. At the end of shift and concise
2. In the middle of the shift in full detail
3. Before start of shift and concise
4. In the brake time and very short
start