Parth John 2K20/B17/33 Jelling Stop Dools & Deguels, *Marketing & Measuring Jooks obsed for taking measurements Made of Stainless steel or Spring Steel 9) Scale of 300 nm is mainly used in practice. Durface Plate Josed Jos marketing outwork & for desting flamess or trueness of work.

Made of Grey cast Gron. Serbez o) Pointed out at once or both ends Ilsed to scratch lines on given swiface Thursal Surface Gauge reight from a plane surface.

machined & placed at the top, bottom & all vides. PartWolmp 2K20/B17/33 ·tuncho o) It is used for making out work & locating centers in a permanent manner. 9) They are made of hardened steel and may be classified in two types such as Porick of Dot punch of Centre Purch. e) The centre punch has an inclined angle of Va Blocks o) St is a block of steel with V-shaped groones Joy marking oy drilling on a Eylindri Leal morkpiece it Serves as a useful support to the morkpiece. Doy-Dquare. It is used to check the truckers of mutually normally surfaces or another Jewords adjacent surjaces.

on the absence of our face plate, Latness of any surface may also be checked by it PARTH JOHRI Callipers The main function of callipers to Fransfer and comparie a dimiensión from an surface lo eter where I the meas whement cannot be in i) Cautside calliper ii) Onside calliper 111) Hermapprodite or oddræg caliper Vernier calèper & Vernier height Gauge o Vernier callipers can measure internal dirension gexternal dimensions heights components. Micrometer, Ensonment for making precise linear measur-ement of dimensions such as cliameters, thickness be lengths of solid bodies.

Holding, & Supporting Lools Parth Johon 20018 17/33 Bence Vice The benchvice is a device commonly used for holding, the work pilces. 9) Stistion beach, with the Thelp of nuts & I bolts & also thoun as fitter's ruce - Pe Vee. 95t consists of a cast snon trame & base of is used for holding the sou hound; section metal like proper between etc. on this case screw is vertical & the moveable faur morks vertically Hand rice This type of race is usually employed for gupping very small jobs.

Parth John Tin-Vice. It is used for holding nound jobse small diameter such as pines & wires Jetc. Oools Maker's Vice. Useful for holding, small size of jobs which. Itseful for holding small size of jobs which. It is made I bequire juling of drilling, letc. It is made mild-steel Ceilling Seling & Scraping Tools For cutting & chiping among pieces of motal Ets cutting edge is guien a slight curve so as to prevent comers from lagging away -> Flatchisel the metal → Gnoss - Cut Chisel Used for cutting groones in large surfaces or keyways in shafts or wheels Nound Mose Chisel Used in cutting o'il grooms an bearings, pullys

Diamond point clusely One end of this chisel is duanus to a small square and this end is ground off at an angle producing "Diamond" Shape. Parth Johon 2K20/B17/33 Mookshop of Bargo School Song toping topic o cathade anions omon becor a major we is anything in order