Report Patroli (2024-11-01 to 2024-11-14)

No	Tanggal	Task	Point	Status	Description	Petugas
1	2024-11-06	LT 15 WING A	PENGECEKAN APAR	-	-	-
2	2024-11-06	LT 15 WING A	PENGECEKAN KORIDOR	-	-	-
3	2024-11-06	LT 15 WING A	PENGECEKAN KORIDOR	-	-	-
4	2024-11-06	LT 15 WING A	PENGECEKAN KORIDOR	-	-	-
5	2024-11-06	LT 15 WING A	PENGECEKAN HYDRANT	-	-	-
6	2024-11-06	LT 15 WING A	PENGECEKAN HYDRANT	-	-	-
7	2024-11-06	LT 15 WING A	PENGECEKAN HYDRANT	-	-	-
8	2024-11-06	LT 15 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
9	2024-11-06	LT 15 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
10	2024-11-06	LT 15 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
11	2024-11-06	LT 15 WING A	PENGECEKAN PINTU KAMAR	-	-	-
12	2024-11-06	LT 15 WING A	PENGECEKAN PINTU KAMAR	-	-	-
13	2024-11-06	LT 15 WING A	PENGECEKAN PINTU KAMAR	-	-	-
14	2024-11-06	LT 12 WING A	PENGECEKAN APAR	-	-	-
15	2024-11-06	LT 12 WING A	PENGECEKAN APAR	-	-	-
16	2024-11-06	LT 12 WING A	PENGECEKAN APAR	-	-	-
17	2024-11-06	LT 12 WING A	PENGECEKAN KORIDOR	-	-	-
18	2024-11-06	LT 12 WING A	PENGECEKAN KORIDOR	-	-	-
19	2024-11-06	LT 12 WING A	PENGECEKAN KORIDOR	-	-	-
20	2024-11-06	LT 12 WING A	PENGECEKAN HYDRANT	-	-	-
21	2024-11-06	LT 12 WING A	PENGECEKAN HYDRANT	-	-	-
22	2024-11-06	LT 12 WING A	PENGECEKAN HYDRANT	-	-	-
23	2024-11-06	LT 12 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
24	2024-11-06	LT 12 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
25	2024-11-06	LT 12 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
26	2024-11-06	LT 12 WING A	PENGECEKAN PINTU KAMAR	-	-	-
27	2024-11-06	LT 12 WING A	PENGECEKAN PINTU KAMAR	-	-	-
28	2024-11-06	LT 12 WING A	PENGECEKAN PINTU KAMAR	-	-	-
29	2024-11-06	LT 12 WING B	PENGECEKAN APAR	-	-	-
30	2024-11-06	LT 12 WING B	PENGECEKAN APAR	-	-	-
31	2024-11-06	LT 12 WING B	PENGECEKAN APAR	-	-	-
32	2024-11-06	LT 12 WING B	PENGECEKAN HYDRANT	-	-	-
33	2024-11-06	LT 12 WING B	PENGECEKAN HYDRANT	-	-	-
34	2024-11-06	LT 12 WING B	PENGECEKAN HYDRANT	-	-	-
35	2024-11-06	LT 12 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
36	2024-11-06	LT 12 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
37	2024-11-06	LT 12 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
38	2024-11-06	LT 12 WING B	PENGECEKAN PINTU KAMAR	-	-	-

10	No	Tanggal	Task	Point	Status	Description	Petugas
1	39	2024-11-06	LT 12 WING B	PENGECEKAN PINTU KAMAR	-	-	-
March Marc	40	2024-11-06	LT 12 WING B	PENGECEKAN PINTU KAMAR	-	-	-
March Marc	41	2024-11-06	LT 12 WING B	PENGECEKAN KORIDOR	-	-	-
1	42	2024-11-06	LT 12 WING B	PENGECEKAN KORIDOR	-	-	-
PRINCECKAM APAR	43	2024-11-06	LT 12 WING B	PENGECEKAN KORIDOR	-	-	-
PENGECEKAN AYAR	44	2024-11-06	LT 11 WING B	PENGECEKAN APAR	-	-	-
47 2024-11-08 LT I YWNO B PENGECERAN HYDRANT . . . 48 2024-11-08 LT I YWNO B PENGECRAN HYDRANT .	45	2024-11-06	LT 11 WING B	PENGECEKAN APAR	-	-	-
AB	46	2024-11-06	LT 11 WING B	PENGECEKAN APAR	-	-	-
PRINCECKAN HYDRANT	47	2024-11-06	LT 11 WING B	PENGECEKAN HYDRANT	-	-	-
PRINCECKAN EMBRGENCY ENT	48	2024-11-06	LT 11 WING B	PENGECEKAN HYDRANT	-	-	-
PENGECKAN EMERGENCY EXIT	49	2024-11-06	LT 11 WING B	PENGECEKAN HYDRANT	-	-	-
52 2024-11-08 LT11 WING B PENGECKAN EMERGENCY EXIT 1 2 1 53 2024-11-08 LT11 WING B PENGECKAN PINTU KAMAR 1 2 2 54 2024-11-08 LT11 WING B PENGECKAN PINTU KAMAR 1 2 2 56 2024-11-08 LT11 WING B PENGECKAN PINTU KAMAR 1 2 2 56 2024-11-08 LT11 WING B PENGECKAN KORIDOR 1 2 2 57 2024-11-08 LT11 WING B PENGECKAN KORIDOR 1 2 2 2 58 2024-11-08 LT11 WING A PENGECKAN APAR 1 2 1 2 60 2024-11-08 LT11 WING A PENGECKAN APAR 1 2 1 2 61 2024-11-08 LT11 WING A PENGECKAN HYDRANT 1 2 1 2 62 2024-11-08 LT11 WING A PENGECKAN HYDRANT 1 2 1 2 63 2024-11-08	50	2024-11-06	LT 11 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
53 2024-11-06 LT 11 WING B PENGECEKAN PINTU KAMAR - - - - 54 2024-11-06 LT 11 WING B PENGECEKAN PINTU KAMAR - - - - - 55 2024-11-06 LT 11 WING B PENGECEKAN KORIDOR -	51	2024-11-06	LT 11 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
544 2024-11-08 LT 11 WING B PENGECEKAN PINTU KAMAR . <td>52</td> <td>2024-11-06</td> <td>LT 11 WING B</td> <td>PENGECEKAN EMERGENCY EXIT</td> <td>-</td> <td>-</td> <td>-</td>	52	2024-11-06	LT 11 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
PENGECEKAN PINTU KAMAR	53	2024-11-06	LT 11 WING B	PENGECEKAN PINTU KAMAR	-	-	-
96 2024-11-06 LT 11 WING B PENGECEKAN KORIDOR - - - 57 2024-11-06 LT 11 WING B PENGECEKAN KORIDOR - - - - 58 2024-11-06 LT 11 WING B PENGECEKAN KORIDOR - - - - 59 2024-11-06 LT 11 WING A PENGECEKAN APAR - - - - 60 2024-11-06 LT 11 WING A PENGECEKAN APAR - - - - 61 2024-11-06 LT 11 WING A PENGECEKAN HYDRANT - - - - 63 2024-11-06 LT 11 WING A PENGECEKAN HYDRANT - - - - 64 2024-11-06 LT 11 WING A PENGECEKAN EMERGENCY EXIT - - - - 65 2024-11-06 LT 11 WING A PENGECEKAN EMERGENCY EXIT - - - - 67 2024-11-06 LT 11 WING A PENGECEKAN EMERGENCY EXIT - -	54	2024-11-06	LT 11 WING B	PENGECEKAN PINTU KAMAR	-	-	-
57 2024-11-06 LT 11 WING B PENGECEKAN KORIDOR - - - - 58 2024-11-06 LT 11 WING B PENGECEKAN KORIDOR - - - - - 59 2024-11-06 LT 11 WING A PENGECEKAN APAR - - - - - 60 2024-11-06 LT 11 WING A PENGECEKAN APAR - - - - - - 61 2024-11-06 LT 11 WING A PENGECEKAN HYDRANT -	55	2024-11-06	LT 11 WING B	PENGECEKAN PINTU KAMAR	-	-	-
68 2024-11-06 LT 11 WING A PENGECEKAN KORIDOR .	56	2024-11-06	LT 11 WING B	PENGECEKAN KORIDOR	-	-	-
59 2024-11-06 LT 11 WING A PENGECEKAN APAR - - - 60 2024-11-06 LT 11 WING A PENGECEKAN APAR - - - - 61 2024-11-06 LT 11 WING A PENGECEKAN APAR - - - - 62 2024-11-06 LT 11 WING A PENGECEKAN HYDRANT - - - - 63 2024-11-06 LT 11 WING A PENGECEKAN HYDRANT - - - - - 64 2024-11-06 LT 11 WING A PENGECEKAN HYDRANT - <td< td=""><td>57</td><td>2024-11-06</td><td>LT 11 WING B</td><td>PENGECEKAN KORIDOR</td><td>-</td><td>-</td><td>-</td></td<>	57	2024-11-06	LT 11 WING B	PENGECEKAN KORIDOR	-	-	-
2024-11-06 LT 11 WING A PENGECEKAN APAR - - - - - - - - -	58	2024-11-06	LT 11 WING B	PENGECEKAN KORIDOR	-	-	-
61 2024-11-06 LT 11 WING A PENGECEKAN APAR .	59	2024-11-06	LT 11 WING A	PENGECEKAN APAR	-	-	-
62 2024-11-06 LT 11 WING A PENGECEKAN HYDRANT - - - - 63 2024-11-06 LT 11 WING A PENGECEKAN HYDRANT - - - - - 64 2024-11-06 LT 11 WING A PENGECEKAN HYDRANT -	60	2024-11-06	LT 11 WING A	PENGECEKAN APAR	-	-	-
63 2024-11-06 LT 11 WING A PENGECEKAN HYDRANT -	61	2024-11-06	LT 11 WING A	PENGECEKAN APAR	-	-	-
64 2024-11-06 LT 11 WING A PENGECEKAN HYDRANT -	62	2024-11-06	LT 11 WING A	PENGECEKAN HYDRANT	-	-	-
65 2024-11-06 LT 11 WING A PENGECEKAN EMERGENCY EXIT -<	63	2024-11-06	LT 11 WING A	PENGECEKAN HYDRANT	-	-	-
66 2024-11-06 LT 11 WING A PENGECEKAN EMERGENCY EXIT -<	64	2024-11-06	LT 11 WING A	PENGECEKAN HYDRANT	-	-	-
67 2024-11-06 LT 11 WING A PENGECEKAN EMERGENCY EXIT -<	65	2024-11-06	LT 11 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
68 2024-11-06 LT 11 WING A PENGECEKAN PINTU KAMAR - - - - 69 2024-11-06 LT 11 WING A PENGECEKAN PINTU KAMAR - - - - 70 2024-11-06 LT 11 WING A PENGECEKAN PINTU KAMAR - - - - 71 2024-11-06 LT 11 WING A PENGECEKAN KORIDOR - - - - 72 2024-11-06 LT 11 WING A PENGECEKAN KORIDOR - - - - 73 2024-11-06 LT 11 WING A PENGECEKAN KORIDOR - - - - 74 2024-11-06 LT 10 WING A PENGECEKAN APAR - - - - 75 2024-11-06 LT 10 WING A PENGECEKAN APAR - - - -	66	2024-11-06	LT 11 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
69 2024-11-06 LT 11 WING A PENGECEKAN PINTU KAMAR - - - - 70 2024-11-06 LT 11 WING A PENGECEKAN PINTU KAMAR - - - - 71 2024-11-06 LT 11 WING A PENGECEKAN KORIDOR - - - - 72 2024-11-06 LT 11 WING A PENGECEKAN KORIDOR - - - - 73 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR - - - - 74 2024-11-06 LT 10 WING A PENGECEKAN APAR - - - - 75 2024-11-06 LT 10 WING A PENGECEKAN APAR - - - -	67	2024-11-06	LT 11 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
70 2024-11-06 LT 11 WING A PENGECEKAN PINTU KAMAR - - - - 71 2024-11-06 LT 11 WING A PENGECEKAN KORIDOR - - - - 72 2024-11-06 LT 11 WING A PENGECEKAN KORIDOR - - - - 73 2024-11-06 LT 11 WING A PENGECEKAN KORIDOR - - - - 74 2024-11-06 LT 10 WING A PENGECEKAN APAR - - - - 75 2024-11-06 LT 10 WING A PENGECEKAN APAR - - - -	68	2024-11-06	LT 11 WING A	PENGECEKAN PINTU KAMAR	-	-	-
71 2024-11-06 LT 11 WING A PENGECEKAN KORIDOR - - - - 72 2024-11-06 LT 11 WING A PENGECEKAN KORIDOR - - - - 73 2024-11-06 LT 11 WING A PENGECEKAN KORIDOR - - - - 74 2024-11-06 LT 10 WING A PENGECEKAN APAR - - - - 75 2024-11-06 LT 10 WING A PENGECEKAN APAR - - - -	69	2024-11-06	LT 11 WING A	PENGECEKAN PINTU KAMAR	-	-	-
72 2024-11-06 LT 11 WING A PENGECEKAN KORIDOR - - - - 73 2024-11-06 LT 11 WING A PENGECEKAN KORIDOR - - - - 74 2024-11-06 LT 10 WING A PENGECEKAN APAR - - - - 75 2024-11-06 LT 10 WING A PENGECEKAN APAR - - - -	70	2024-11-06	LT 11 WING A	PENGECEKAN PINTU KAMAR	-	-	-
73 2024-11-06 LT 11 WING A PENGECEKAN KORIDOR - - - - 74 2024-11-06 LT 10 WING A PENGECEKAN APAR - - - - 75 2024-11-06 LT 10 WING A PENGECEKAN APAR - - - -	71	2024-11-06	LT 11 WING A	PENGECEKAN KORIDOR	-	-	-
74 2024-11-06 LT 10 WING A PENGECEKAN APAR -	72	2024-11-06	LT 11 WING A	PENGECEKAN KORIDOR	-	-	-
75 2024-11-06 LT 10 WING A PENGECEKAN APAR	73	2024-11-06	LT 11 WING A	PENGECEKAN KORIDOR	-	-	-
	74	2024-11-06	LT 10 WING A	PENGECEKAN APAR	-	-	-
	75	2024-11-06	LT 10 WING A	PENGECEKAN APAR	-	-	-
76 2024-11-06 LT 10 WING A PENGECEKAN APAR	76	2024-11-06	LT 10 WING A	PENGECEKAN APAR	-	-	-
77 2024-11-06 LT 10 WING A PENGECEKAN HYDRANT	77	2024-11-06	LT 10 WING A	PENGECEKAN HYDRANT	-	-	-

78 2024-11-06 LT 10 WING A PENGECEKAN HYDRANT 79 2024-11-06 LT 10 WING A PENGECEKAN HYDRANT 80 2024-11-06 LT 10 WING A PENGECEKAN EMERGENG 81 2024-11-06 LT 10 WING A PENGECEKAN EMERGENG 82 2024-11-06 LT 10 WING A PENGECEKAN EMERGENG 83 2024-11-06 LT 10 WING A PENGECEKAN PINTU KAM 84 2024-11-06 LT 10 WING A PENGECEKAN PINTU KAM 85 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 86 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 87 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 89 2024-11-06 LT 10 WING B PENGECEKAN APAR 90 2024-11-06 LT 10 WING B PENGECEKAN APAR 91 2024-11-06 LT 10 WING B PENGECEKAN HYDRANT 93 2024-11-06 LT 10 WING B PENGECEKAN HYDRANT	CY EXIT - CY EXIT - IAR - IAR -		
80 2024-11-06 LT 10 WING A PENGECEKAN EMERGENCE 81 2024-11-06 LT 10 WING A PENGECEKAN EMERGENCE 82 2024-11-06 LT 10 WING A PENGECEKAN EMERGENCE 83 2024-11-06 LT 10 WING A PENGECEKAN PINTU KAM 84 2024-11-06 LT 10 WING A PENGECEKAN PINTU KAM 85 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 87 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 88 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 89 2024-11-06 LT 10 WING B PENGECEKAN APAR 90 2024-11-06 LT 10 WING B PENGECEKAN APAR 91 2024-11-06 LT 10 WING B PENGECEKAN HYDRANT	CY EXIT - CY EXIT - CY EXIT - IAR -		
81 2024-11-06 LT 10 WING A PENGECEKAN EMERGENCE 82 2024-11-06 LT 10 WING A PENGECEKAN EMERGENCE 83 2024-11-06 LT 10 WING A PENGECEKAN PINTU KAM 84 2024-11-06 LT 10 WING A PENGECEKAN PINTU KAM 85 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 87 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 88 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 89 2024-11-06 LT 10 WING B PENGECEKAN APAR 90 2024-11-06 LT 10 WING B PENGECEKAN APAR 91 2024-11-06 LT 10 WING B PENGECEKAN APAR 92 2024-11-06 LT 10 WING B PENGECEKAN HYDRANT	CY EXIT - CY EXIT - IAR - IAR - IAR - I - IAR		
82 2024-11-06 LT 10 WING A PENGECEKAN EMERGENO 83 2024-11-06 LT 10 WING A PENGECEKAN PINTU KAM 84 2024-11-06 LT 10 WING A PENGECEKAN PINTU KAM 85 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 87 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 88 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 89 2024-11-06 LT 10 WING B PENGECEKAN APAR 90 2024-11-06 LT 10 WING B PENGECEKAN APAR 91 2024-11-06 LT 10 WING B PENGECEKAN APAR 92 2024-11-06 LT 10 WING B PENGECEKAN HYDRANT	CY EXIT - JAR - JAR - JAR - - JAR - - - - - - - - - - - - -		
83 2024-11-06 LT 10 WING A PENGECEKAN PINTU KAM 84 2024-11-06 LT 10 WING A PENGECEKAN PINTU KAM 85 2024-11-06 LT 10 WING A PENGECEKAN PINTU KAM 86 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 87 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 88 2024-11-06 LT 10 WING B PENGECEKAN APAR 90 2024-11-06 LT 10 WING B PENGECEKAN APAR 91 2024-11-06 LT 10 WING B PENGECEKAN APAR 92 2024-11-06 LT 10 WING B PENGECEKAN HYDRANT	IAR -		
84 2024-11-06 LT 10 WING A PENGECEKAN PINTU KAM 85 2024-11-06 LT 10 WING A PENGECEKAN PINTU KAM 86 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 87 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 88 2024-11-06 LT 10 WING B PENGECEKAN APAR 90 2024-11-06 LT 10 WING B PENGECEKAN APAR 91 2024-11-06 LT 10 WING B PENGECEKAN APAR 92 2024-11-06 LT 10 WING B PENGECEKAN HYDRANT	IAR - IAR		- - -
85 2024-11-06 LT 10 WING A PENGECEKAN PINTU KAM 86 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 87 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 88 2024-11-06 LT 10 WING B PENGECEKAN KORIDOR 89 2024-11-06 LT 10 WING B PENGECEKAN APAR 90 2024-11-06 LT 10 WING B PENGECEKAN APAR 91 2024-11-06 LT 10 WING B PENGECEKAN APAR 92 2024-11-06 LT 10 WING B PENGECEKAN HYDRANT		- - - -	
86 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 87 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 88 2024-11-06 LT 10 WING B PENGECEKAN KORIDOR 89 2024-11-06 LT 10 WING B PENGECEKAN APAR 90 2024-11-06 LT 10 WING B PENGECEKAN APAR 91 2024-11-06 LT 10 WING B PENGECEKAN APAR 92 2024-11-06 LT 10 WING B PENGECEKAN HYDRANT		- - - -	
87 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 88 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 89 2024-11-06 LT 10 WING B PENGECEKAN APAR 90 2024-11-06 LT 10 WING B PENGECEKAN APAR 91 2024-11-06 LT 10 WING B PENGECEKAN APAR 92 2024-11-06 LT 10 WING B PENGECEKAN HYDRANT	- - - -	- - -	- - -
88 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR 89 2024-11-06 LT 10 WING B PENGECEKAN APAR 90 2024-11-06 LT 10 WING B PENGECEKAN APAR 91 2024-11-06 LT 10 WING B PENGECEKAN APAR 92 2024-11-06 LT 10 WING B PENGECEKAN HYDRANT		- -	-
89 2024-11-06 LT 10 WING B PENGECEKAN APAR 90 2024-11-06 LT 10 WING B PENGECEKAN APAR 91 2024-11-06 LT 10 WING B PENGECEKAN APAR 92 2024-11-06 LT 10 WING B PENGECEKAN HYDRANT	-	-	-
90 2024-11-06 LT 10 WING B PENGECEKAN APAR 91 2024-11-06 LT 10 WING B PENGECEKAN APAR 92 2024-11-06 LT 10 WING B PENGECEKAN HYDRANT	-	-	
91 2024-11-06 LT 10 WING B PENGECEKAN APAR 92 2024-11-06 LT 10 WING B PENGECEKAN HYDRANT			-
92 2024-11-06 LT 10 WING B PENGECEKAN HYDRANT		-	-
		-	
93 2024-11-06 LT 10 WING B PENGECEKAN HYDRANT	-	-	
	-	-	-
94 2024-11-06 LT 10 WING B PENGECEKAN HYDRANT	-	-	-
95 2024-11-06 LT 10 WING B PENGECEKAN EMERGENCE	CY EXIT -	-	-
96 2024-11-06 LT 10 WING B PENGECEKAN EMERGENC	CY EXIT -	-	-
97 2024-11-06 LT 10 WING B PENGECEKAN EMERGENCE	CY EXIT -	-	-
98 2024-11-06 LT 10 WING B PENGECEKAN PINTU KAM	IAR -	-	-
99 2024-11-06 LT 10 WING B PENGECEKAN PINTU KAM	IAR -	-	-
100 2024-11-06 LT 10 WING B PENGECEKAN PINTU KAM	IAR -	-	-
101 2024-11-06 LT 10 WING B PENGECEKAN KORIDOR	-	-	-
102 2024-11-06 LT 10 WING B PENGECEKAN KORIDOR	-	-	-
103 2024-11-06 LT 10 WING B PENGECEKAN KORIDOR	-	-	-
104 2024-11-06 LT 09 WING B PENGECEKAN APAR	-	-	-
105 2024-11-06 LT 09 WING B PENGECEKAN APAR	-	-	
106 2024-11-06 LT 09 WING B PENGECEKAN APAR	-	-	-
107 2024-11-06 LT 09 WING B PENGECEKAN HYDRANT	-	-	
108 2024-11-06 LT 09 WING B PENGECEKAN HYDRANT	-	-	
109 2024-11-06 LT 09 WING B PENGECEKAN HYDRANT	-	-	
110 2024-11-06 LT 09 WING B PENGECEKAN EMERGENC	CY EXIT -	-	
111 2024-11-06 LT 09 WING B PENGECEKAN EMERGENC	CY EXIT -	-	-
112 2024-11-06 LT 09 WING B PENGECEKAN EMERGENC	CY EXIT -	-	-
113 2024-11-06 LT 09 WING B PENGECEKAN PINTU KAM	IAR -	-	-
114 2024-11-06 LT 09 WING B PENGECEKAN PINTU KAM	IAR -	-	
115 2024-11-06 LT 09 WING B PENGECEKAN PINTU KAM	IAR -	-	
116 2024-11-06 LT 09 WING B PENGECEKAN KORIDOR	-	-	-

	Tanggal	Task	Point	Status	Description	Petugas
117	2024-11-06	LT 09 WING B	PENGECEKAN KORIDOR	-	-	-
118	2024-11-06	LT 09 WING B	PENGECEKAN KORIDOR	-	-	-
119	2024-11-06	LT 09 WING A	PENGECEKAN APAR	-	-	-
120	2024-11-06	LT 09 WING A	PENGECEKAN APAR	-	-	-
121	2024-11-06	LT 09 WING A	PENGECEKAN APAR	-	-	-
122	2024-11-06	LT 09 WING A	PENGECEKAN HYDRANT	-	-	-
123	2024-11-06	LT 09 WING A	PENGECEKAN HYDRANT	-	-	-
124	2024-11-06	LT 09 WING A	PENGECEKAN HYDRANT	-	-	-
125	2024-11-06	LT 09 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
126	2024-11-06	LT 09 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
127	2024-11-06	LT 09 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
128	2024-11-06	LT 09 WING A	PENGECEKAN PINTU KAMAR	-	-	-
129	2024-11-06	LT 09 WING A	PENGECEKAN PINTU KAMAR	-	-	-
130	2024-11-06	LT 09 WING A	PENGECEKAN PINTU KAMAR	-	-	-
131	2024-11-06	LT 09 WING A	PENGECEKAN KORIDOR	-	-	-
132	2024-11-06	LT 09 WING A	PENGECEKAN KORIDOR	-	-	-
133	2024-11-06	LT 09 WING A	PENGECEKAN KORIDOR	-	-	-
134	2024-11-06	LT 08 WING A	PENGECEKAN APAR	-	-	-
135	2024-11-06	LT 08 WING A	PENGECEKAN APAR	-	-	-
136	2024-11-06	LT 08 WING A	PENGECEKAN APAR	-	-	-
137	2024-11-06	LT 08 WING A	PENGECEKAN HYDRANT	-	-	-
138	2024-11-06	LT 08 WING A	PENGECEKAN HYDRANT	-	-	-
139	2024-11-06	LT 08 WING A	PENGECEKAN HYDRANT	-	-	-
140	2024-11-06	LT 08 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
141	2024-11-06	LT 08 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
142	2024-11-06	LT 08 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
143	2024-11-06	LT 08 WING A	PENGECEKAN PINTU KAMAR	-	-	-
144	2024-11-06	LT 08 WING A	PENGECEKAN PINTU KAMAR	-	-	-
145	2024-11-06	LT 08 WING A	PENGECEKAN PINTU KAMAR	-	-	-
146	2024-11-06	LT 08 WING A	PENGECEKAN KORIDOR	-	-	-
147	2024-11-06	LT 08 WING A	PENGECEKAN KORIDOR	-	-	-
148	2024-11-06	LT 08 WING A	PENGECEKAN KORIDOR	-	-	-
149	2024-11-06	LT 08 WING B	PENGECEKAN APAR	-	-	-
150	2024-11-06	LT 08 WING B	PENGECEKAN APAR	-	-	-
151	2024-11-06	LT 08 WING B	PENGECEKAN APAR	-	-	-
152	2024-11-06	LT 08 WING B	PENGECEKAN HYDRANT	-	-	-
153	2024-11-06	LT 08 WING B	PENGECEKAN HYDRANT	-	-	-
154	2024-11-06	LT 08 WING B	PENGECEKAN HYDRANT	-	-	-
155	2024-11-06	LT 08 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-

No	Tanggal	Task	Point	Status	Description	Petugas
156	2024-11-06	LT 08 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
157	2024-11-06	LT 08 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
158	2024-11-06	LT 08 WING B	PENGECEKAN PINTU KAMAR	-	-	-
159	2024-11-06	LT 08 WING B	PENGECEKAN PINTU KAMAR	-	-	-
160	2024-11-06	LT 08 WING B	PENGECEKAN PINTU KAMAR	-	-	-
161	2024-11-06	LT 08 WING B	PENGECEKAN KORIDOR	-	-	-
162	2024-11-06	LT 08 WING B	PENGECEKAN KORIDOR	-	-	-
163	2024-11-06	LT 08 WING B	PENGECEKAN KORIDOR	-	-	-
164	2024-11-06	LT 07 WING B	PENGECEKAN APAR	-	-	-
165	2024-11-06	LT 07 WING B	PENGECEKAN APAR	-	-	-
166	2024-11-06	LT 07 WING B	PENGECEKAN APAR	-	-	-
167	2024-11-06	LT 07 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
168	2024-11-06	LT 07 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
169	2024-11-06	LT 07 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
170	2024-11-06	LT 07 WING B	PENGECEKAN HYDRANT	-	-	-
171	2024-11-06	LT 07 WING B	PENGECEKAN HYDRANT	-	-	-
172	2024-11-06	LT 07 WING B	PENGECEKAN HYDRANT	-	-	-
173	2024-11-06	LT 07 WING B	PENGECEKAN PINTU KAMAR	-	-	-
174	2024-11-06	LT 07 WING B	PENGECEKAN PINTU KAMAR	-	-	-
175	2024-11-06	LT 07 WING B	PENGECEKAN PINTU KAMAR	-	-	-
176	2024-11-06	LT 07 WING B	PENGECEKAN KORIDOR	-	-	-
177	2024-11-06	LT 07 WING B	PENGECEKAN KORIDOR	-	-	-
178	2024-11-06	LT 07 WING B	PENGECEKAN KORIDOR	-	-	-
179	2024-11-06	LT 07 WING A	PENGECEKAN APAR	-	-	-
180	2024-11-06	LT 07 WING A	PENGECEKAN APAR	-	-	-
181	2024-11-06	LT 07 WING A	PENGECEKAN APAR	-	-	-
182	2024-11-06	LT 07 WING A	PENGECEKAN HYDRANT	-	-	-
183	2024-11-06	LT 07 WING A	PENGECEKAN HYDRANT	-	-	-
184	2024-11-06	LT 07 WING A	PENGECEKAN HYDRANT	-	-	-
185	2024-11-06	LT 07 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
186	2024-11-06	LT 07 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
187	2024-11-06	LT 07 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
188	2024-11-06	LT 07 WING A	PENGECEKAN PINTU KAMAR	-	-	-
189	2024-11-06	LT 07 WING A	PENGECEKAN PINTU KAMAR	-	-	-
190	2024-11-06	LT 07 WING A	PENGECEKAN PINTU KAMAR	-	-	-
191	2024-11-06	LT 07 WING A	PENGECEKAN KORIDOR	-	-	-
192	2024-11-06	LT 07 WING A	PENGECEKAN KORIDOR	-	-	-
193	2024-11-06	LT 07 WING A	PENGECEKAN KORIDOR	-	-	-
194	2024-11-06	LT 06 WING A	PENGECEKAN APAR	-	-	-
194	2024-11-06	LT 06 WING A	PENGECEKAN APAR	-	-	-

196	on Petugas
197 2024-11-06	-
1996	-
PENGLECKAN HYDRANT	-
2004 2024-11-06	-
2011 2024-11-06	-
202 2024-11-06 LT 06 WING A PENGECEKAN EMERGENCY EXIT - - 203 2024-11-06 LT 06 WING A PENGECEKAN PINTU KAMAR - - 204 2024-11-06 LT 06 WING A PENGECEKAN PINTU KAMAR - - 205 2024-11-06 LT 06 WING A PENGECEKAN PINTU KAMAR - - 206 2024-11-06 LT 06 WING A PENGECEKAN KORIDOR - - 207 2024-11-06 LT 06 WING A PENGECEKAN KORIDOR - - 208 2024-11-06 LT 06 WING B PENGECEKAN APAR - - 210 2024-11-06 LT 06 WING B PENGECEKAN APAR - - 211 2024-11-06 LT 06 WING B PENGECEKAN HYDRANT - - 212 2024-11-06 LT 06 WING B PENGECEKAN HYDRANT - - 213 2024-11-06 LT 06 WING B PENGECEKAN HYDRANT - - 214 2024-11-06 LT 06 WING B PENGECEKAN HERGENCY EXIT <	-
203 2024-11-06	-
2014 2024-11-06	-
205 2024-11-06 LT 06 WING A PENGECEKAN PINTU KAMAR - - 206 2024-11-06 LT 06 WING A PENGECEKAN KORIDOR - - 207 2024-11-06 LT 06 WING A PENGECEKAN KORIDOR - - 208 2024-11-06 LT 06 WING A PENGECEKAN KORIDOR - - 209 2024-11-06 LT 06 WING B PENGECEKAN APAR - - 210 2024-11-06 LT 06 WING B PENGECEKAN APAR - - 211 2024-11-06 LT 06 WING B PENGECEKAN APAR - - 212 2024-11-06 LT 06 WING B PENGECEKAN HYDRANT - - 213 2024-11-06 LT 06 WING B PENGECEKAN HYDRANT - - 214 2024-11-06 LT 06 WING B PENGECEKAN HYDRANT - - 215 2024-11-06 LT 06 WING B PENGECEKAN HERGENCY EXIT - - 216 2024-11-06 LT 06 WING B PENGECEKAN EMERGENCY EXIT -	-
206 2024-11-06	-
207 2024-11-06	-
208 2024-11-06 LT 06 WING A PENGECEKAN KORIDOR - - 209 2024-11-06 LT 06 WING B PENGECEKAN APAR - - 210 2024-11-06 LT 06 WING B PENGECEKAN APAR - - 211 2024-11-06 LT 06 WING B PENGECEKAN HYDRANT - - 212 2024-11-06 LT 06 WING B PENGECEKAN HYDRANT - - 214 2024-11-06 LT 06 WING B PENGECEKAN HYDRANT - - 215 2024-11-06 LT 06 WING B PENGECEKAN EMERGENCY EXIT - - 216 2024-11-06 LT 06 WING B PENGECEKAN EMERGENCY EXIT - - 217 2024-11-06 LT 06 WING B PENGECEKAN EMERGENCY EXIT - - 218 2024-11-06 LT 06 WING B PENGECEKAN EMERGENCY EXIT - - 219 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 220 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR	-
209 2024-11-06	-
2024-11-06	-
211 2024-11-06 LT 06 WING B PENGECEKAN APAR - - 212 2024-11-06 LT 06 WING B PENGECEKAN HYDRANT - - 213 2024-11-06 LT 06 WING B PENGECEKAN HYDRANT - - 214 2024-11-06 LT 06 WING B PENGECEKAN HYDRANT - - 215 2024-11-06 LT 06 WING B PENGECEKAN EMERGENCY EXIT - - 216 2024-11-06 LT 06 WING B PENGECEKAN EMERGENCY EXIT - - 217 2024-11-06 LT 06 WING B PENGECEKAN EMERGENCY EXIT - - 218 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 219 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 220 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 221 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 223 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 224 2024-11-06 LT 06 WING B	-
212 2024-11-06 LT 06 WING B PENGECEKAN HYDRANT - - 213 2024-11-06 LT 06 WING B PENGECEKAN HYDRANT - - 214 2024-11-06 LT 06 WING B PENGECEKAN HYDRANT - - 215 2024-11-06 LT 06 WING B PENGECEKAN EMERGENCY EXIT - - 216 2024-11-06 LT 06 WING B PENGECEKAN EMERGENCY EXIT - - 217 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 218 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 219 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 220 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 221 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 222 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 223 2024-11-06 LT 06 WING B PENGECEKAN APAR - -	-
213 2024-11-06 LT 06 WING B PENGECEKAN HYDRANT - - 214 2024-11-06 LT 06 WING B PENGECEKAN HYDRANT - - 215 2024-11-06 LT 06 WING B PENGECEKAN EMERGENCY EXIT - - 216 2024-11-06 LT 06 WING B PENGECEKAN EMERGENCY EXIT - - 217 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 218 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 219 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 220 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 221 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 222 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 223 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 224 2024-11-06 LT 06 WING B PENGECEKAN APAR - -	-
214 2024-11-06 LT 06 WING B PENGECEKAN HYDRANT - - 215 2024-11-06 LT 06 WING B PENGECEKAN EMERGENCY EXIT - - 216 2024-11-06 LT 06 WING B PENGECEKAN EMERGENCY EXIT - - 217 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 218 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 219 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 220 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 221 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 222 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 223 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 224 2024-11-06 LT 06 WING B PENGECEKAN APAR - -	-
215 2024-11-06 LT 06 WING B PENGECEKAN EMERGENCY EXIT - - 216 2024-11-06 LT 06 WING B PENGECEKAN EMERGENCY EXIT - - 217 2024-11-06 LT 06 WING B PENGECEKAN EMERGENCY EXIT - - 218 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 219 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 220 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 221 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 222 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 223 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 224 2024-11-06 LT 05 WING B PENGECEKAN APAR - -	-
216 2024-11-06 LT 06 WING B PENGECEKAN EMERGENCY EXIT - - 217 2024-11-06 LT 06 WING B PENGECEKAN EMERGENCY EXIT - - 218 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 219 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 220 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 221 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 222 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 223 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 224 2024-11-06 LT 06 WING B PENGECEKAN APAR - -	-
217 2024-11-06 LT 06 WING B PENGECEKAN EMERGENCY EXIT - - 218 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 219 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 220 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 221 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 222 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 223 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 224 2024-11-06 LT 06 WING B PENGECEKAN APAR - -	-
218 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 219 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 220 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 221 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 222 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 223 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 224 2024-11-06 LT 05 WING B PENGECEKAN APAR - -	-
219 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 220 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 221 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 222 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 223 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 224 2024-11-06 LT 05 WING B PENGECEKAN APAR - -	-
220 2024-11-06 LT 06 WING B PENGECEKAN PINTU KAMAR - - 221 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 222 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 223 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 224 2024-11-06 LT 05 WING B PENGECEKAN APAR - -	-
221 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 222 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 223 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - 224 2024-11-06 LT 05 WING B PENGECEKAN APAR - -	-
222 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - - 223 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - - 224 2024-11-06 LT 05 WING B PENGECEKAN APAR - - -	-
223 2024-11-06 LT 06 WING B PENGECEKAN KORIDOR - - - 224 2024-11-06 LT 05 WING B PENGECEKAN APAR - - -	-
224 2024-11-06 LT 05 WING B PENGECEKAN APAR	-
	-
225 2024-11-06 LT 05 WING B PENGECEKAN APAR	-
	-
226 2024-11-06 LT 05 WING B PENGECEKAN APAR - - -	-
227 2024-11-06 LT 05 WING B PENGECEKAN HYDRANT - - -	-
228 2024-11-06 LT 05 WING B PENGECEKAN HYDRANT - - -	-
229 2024-11-06 LT 05 WING B PENGECEKAN HYDRANT - - -	-
230 2024-11-06 LT 05 WING B PENGECEKAN EMERGENCY EXIT	-
231 2024-11-06 LT 05 WING B PENGECEKAN EMERGENCY EXIT	-
232 2024-11-06 LT 05 WING B PENGECEKAN EMERGENCY EXIT	-
233 2024-11-06 LT 05 WING B PENGECEKAN PINTU KAMAR	-

235 2 236 2 237 2	2024-11-06 2024-11-06 2024-11-06 2024-11-06	LT 05 WING B LT 05 WING B LT 05 WING B	PENGECEKAN PINTU KAMAR PENGECEKAN PINTU KAMAR	-	-	-
236 2	2024-11-06 2024-11-06		PENGECEKAN PINTU KAMAR			
237 2	2024-11-06	LT 05 WING B		-	-	-
			PENGECEKAN KORIDOR	-	-	-
238 2		LT 05 WING B	PENGECEKAN KORIDOR	-	-	-
	2024-11-06	LT 05 WING B	PENGECEKAN KORIDOR	-	-	-
239 2	2024-11-06	LT 05 WING A	PENGECEKAN APAR	-	-	-
240 2	2024-11-06	LT 05 WING A	PENGECEKAN APAR	-	-	-
241 2	2024-11-06	LT 05 WING A	PENGECEKAN APAR	-	-	-
242 2	2024-11-06	LT 05 WING A	PENGECEKAN HYDRANT	-	-	-
243 2	2024-11-06	LT 05 WING A	PENGECEKAN HYDRANT	-	-	-
244 2	2024-11-06	LT 05 WING A	PENGECEKAN HYDRANT	-	-	-
245 2	2024-11-06	LT 05 WING A	PENGECEKAN EMERGENCY EXIT	-		-
246 2	2024-11-06	LT 05 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
247 2	2024-11-06	LT 05 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
248 2	2024-11-06	LT 05 WING A	PENGECEKAN PINTU KAMAR	-	-	-
249 2	2024-11-06	LT 05 WING A	PENGECEKAN PINTU KAMAR	-	-	-
250 2	2024-11-06	LT 05 WING A	PENGECEKAN PINTU KAMAR	-	-	-
251 2	2024-11-06	LT 05 WING A	PENGECEKAN KORIDOR	-	-	-
252 2	2024-11-06	LT 05 WING A	PENGECEKAN KORIDOR	-	-	-
253 2	2024-11-06	LT 05 WING A	PENGECEKAN KORIDOR	-	-	-
254 2	2024-11-06	LT 03 WING A	PENGECEKAN APAR	-	-	-
255 2	2024-11-06	LT 03 WING A	PENGECEKAN APAR	-	-	-
256 2	2024-11-06	LT 03 WING A	PENGECEKAN APAR	-	-	-
257 2	2024-11-06	LT 03 WING A	PENGECEKAN HYDRANT	-	-	-
258 2	2024-11-06	LT 03 WING A	PENGECEKAN HYDRANT	-	-	-
259 2	2024-11-06	LT 03 WING A	PENGECEKAN HYDRANT	-	-	-
260 2	2024-11-06	LT 03 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
261 2	2024-11-06	LT 03 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
262 2	2024-11-06	LT 03 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
263 2	2024-11-06	LT 03 WING A	PENGECEKAN PINTU KAMAR	-	-	-
264 2	2024-11-06	LT 03 WING A	PENGECEKAN PINTU KAMAR	-	-	-
265 2	2024-11-06	LT 03 WING A	PENGECEKAN PINTU KAMAR	-	-	
266 2	2024-11-06	LT 03 WING A	PENGECEKAN KORIDOR	-	-	-
267 2	2024-11-06	LT 03 WING A	PENGECEKAN KORIDOR	-	-	-
268 2	2024-11-06	LT 03 WING A	PENGECEKAN KORIDOR	-	-	-
269 2	2024-11-06	LT 03 POOL 1	PENGECEKAN APAR	-	-	-
270 2	2024-11-06	LT 03 POOL 1	PENGECEKAN APAR	-	-	
271 2	2024-11-06	LT 03 POOL 1	PENGECEKAN APAR	-	-	
272 2	2024-11-06	LT 03 POOL 1	PENGECEKAN HYDRANT	-	-	-

No	Tanggal	Task	Point	Status	Description	Petugas
273	2024-11-06	LT 03 POOL 1	PENGECEKAN HYDRANT	-	-	-
274	2024-11-06	LT 03 POOL 1	PENGECEKAN HYDRANT	-	-	-
275	2024-11-06	LT 03 POOL 1	PENGECEKAN PANEL LISTRIK	-	-	-
276	2024-11-06	LT 03 POOL 1	PENGECEKAN PANEL LISTRIK	-	-	-
277	2024-11-06	LT 03 POOL 1	PENGECEKAN PANEL LISTRIK	-	-	-
278	2024-11-06	LT 03 POOL 1	PENGECEKAN EMERGENCY EXIT	-	-	-
279	2024-11-06	LT 03 POOL 1	PENGECEKAN EMERGENCY EXIT	-	-	-
280	2024-11-06	LT 03 POOL 1	PENGECEKAN EMERGENCY EXIT	-	-	-
281	2024-11-06	LT 03 POOL 2	PENGECEKAN APAR	-	-	-
282	2024-11-06	LT 03 POOL 2	PENGECEKAN APAR	-	-	-
283	2024-11-06	LT 03 POOL 2	PENGECEKAN APAR	-	-	-
284	2024-11-06	LT 03 POOL 2	PENGECEKAN HYDRANT	-	-	-
285	2024-11-06	LT 03 POOL 2	PENGECEKAN HYDRANT	-	-	-
286	2024-11-06	LT 03 POOL 2	PENGECEKAN HYDRANT	-	-	-
287	2024-11-06	LT 03 POOL 2	PENGECEKAN PANEL LISTRIK	-	-	-
288	2024-11-06	LT 03 POOL 2	PENGECEKAN PANEL LISTRIK	-	-	-
289	2024-11-06	LT 03 POOL 2	PENGECEKAN PANEL LISTRIK	-	-	-
290	2024-11-06	LT 03 POOL 2	PENGECEKAN EMERGENCY EXIT	-	-	-
291	2024-11-06	LT 03 POOL 2	PENGECEKAN EMERGENCY EXIT	-	-	-
292	2024-11-06	LT 03 POOL 2	PENGECEKAN EMERGENCY EXIT	-	-	-
293	2024-11-06	LT 03 GYM	PENGECEKAN APAR	-	-	-
294	2024-11-06	LT 03 GYM	PENGECEKAN APAR	-	-	-
295	2024-11-06	LT 03 GYM	PENGECEKAN APAR	-	-	-
296	2024-11-06	LT 03 GYM	PENGECEKAN PANEL LISTRIK	-	-	-
297	2024-11-06	LT 03 GYM	PENGECEKAN PANEL LISTRIK	-	-	-
298	2024-11-06	LT 03 GYM	PENGECEKAN PANEL LISTRIK	-	-	-
299	2024-11-06	LT 03 WING B	PENGECEKAN APAR	-	-	-
300	2024-11-06	LT 03 WING B	PENGECEKAN APAR	-	-	-
301	2024-11-06	LT 03 WING B	PENGECEKAN APAR	-	-	-
302	2024-11-06	LT 03 WING B	PENGECEKAN HYDRANT	-	-	-
303	2024-11-06	LT 03 WING B	PENGECEKAN HYDRANT	-	-	-
304	2024-11-06	LT 03 WING B	PENGECEKAN HYDRANT	-	-	-
305	2024-11-06	LT 03 WING B	PENGECEKAN PINTU KAMAR	-	-	-
306	2024-11-06	LT 03 WING B	PENGECEKAN PINTU KAMAR	-	-	-
307	2024-11-06	LT 03 WING B	PENGECEKAN PINTU KAMAR	-	-	-
308	2024-11-06	LT 03 WING B	PENGECEKAN KORIDOR	-	-	-
309	2024-11-06	LT 03 WING B	PENGECEKAN KORIDOR	-	-	-
310	2024-11-06	LT 03 WING B	PENGECEKAN KORIDOR	-	-	-
311	2024-11-06	LT 03 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
-311	2024-11-00	EF-05 WING D	PENOLOLIAN LIVILITATION LAND			

	Tanggal	Task	Point	Status	Description	Petugas
312	2024-11-06	LT 03 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
313	2024-11-06	LT 03 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
314	2024-11-06	LT 03 ROOF TOP	PENGECEKAN APAR	-	-	-
315	2024-11-06	LT 03 ROOF TOP	PENGECEKAN APAR	-	-	-
316	2024-11-06	LT 03 ROOF TOP	PENGECEKAN APAR	-	-	-
317	2024-11-06	LT 03 ROOF TOP	PENGECEKAN PINTU LIFT & MESIN	-	-	-
318	2024-11-06	LT 03 ROOF TOP	PENGECEKAN PINTU LIFT & MESIN	-	-	-
319	2024-11-06	LT 03 ROOF TOP	PENGECEKAN PINTU LIFT & MESIN	-	-	-
320	2024-11-06	LT 03 ROOF TOP	PENGECEKAN HYDRANT	-	-	-
321	2024-11-06	LT 03 ROOF TOP	PENGECEKAN HYDRANT	-	-	-
322	2024-11-06	LT 03 ROOF TOP	PENGECEKAN HYDRANT	-	-	-
323	2024-11-06	LT 03 AHU ROOM	PENGECEKAN APAR	-	-	-
324	2024-11-06	LT 03 AHU ROOM	PENGECEKAN APAR	-	-	-
325	2024-11-06	LT 03 AHU ROOM	PENGECEKAN APAR	-	-	-
326	2024-11-06	LT 03 AHU ROOM	PENGECEKAN HYDRANT	-	-	-
327	2024-11-06	LT 03 AHU ROOM	PENGECEKAN HYDRANT	-	-	-
328	2024-11-06	LT 03 AHU ROOM	PENGECEKAN HYDRANT	-	-	-
329	2024-11-06	LT 03 AHU ROOM	PENGECEKAN PANEL LISTRIK	-	-	-
330	2024-11-06	LT 03 AHU ROOM	PENGECEKAN PANEL LISTRIK	-	-	-
331	2024-11-06	LT 03 AHU ROOM	PENGECEKAN PANEL LISTRIK	-	-	-
332	2024-11-06	LT 02 AV ROOM	PENGECEKAN APAR	-	-	-
333	2024-11-06	LT 02 AV ROOM	PENGECEKAN APAR	-	-	-
334	2024-11-06	LT 02 AV ROOM	PENGECEKAN APAR	-	-	-
335	2024-11-06	LT 02 AV ROOM	PENGECEKAN HYDRANT	-	-	-
336	2024-11-06	LT 02 AV ROOM	PENGECEKAN HYDRANT	-	-	-
337	2024-11-06	LT 02 AV ROOM	PENGECEKAN HYDRANT	-	-	-
338	2024-11-06	LT 02 AV ROOM	PENGECEKAN PANEL LISTRIK	-	-	-
339	2024-11-06	LT 02 AV ROOM	PENGECEKAN PANEL LISTRIK	-	-	-
340	2024-11-06	LT 02 AV ROOM	PENGECEKAN PANEL LISTRIK	-	-	-
341	2024-11-06	LT 02 BACK ANGSANA 3	PENGECEKAN APAR	-	-	-
342	2024-11-06	LT 02 BACK ANGSANA 3	PENGECEKAN APAR	-	-	-
343	2024-11-06	LT 02 BACK ANGSANA 3	PENGECEKAN APAR	-	-	-
344	2024-11-06	LT 02 BACK ANGSANA 3	PENGECEKAN HYDRANT	-	-	
345	2024-11-06	LT 02 BACK ANGSANA 3	PENGECEKAN HYDRANT	-	-	-
346	2024-11-06	LT 02 BACK ANGSANA 3	PENGECEKAN HYDRANT	-	-	
347	2024-11-06	LT 02 BACK ANGSANA 3	PENGECEKAN PANEL LISTRIK	-	-	
348	2024-11-06	LT 02 BACK ANGSANA 3	PENGECEKAN PANEL LISTRIK	-	-	
349	2024-11-06	LT 02 BACK ANGSANA 3	PENGECEKAN PANEL LISTRIK	-	-	
350	2024-11-06	LT 02 STORE BANQUET	PENGECEKAN APAR	-	-	

No	Tanggal	Task	Point	Status	Description	Petugas
351	2024-11-06	LT 02 STORE BANQUET	PENGECEKAN APAR	-	-	-
352	2024-11-06	LT 02 STORE BANQUET	PENGECEKAN APAR	-	-	-
353	2024-11-06	LT 02 STORE BANQUET	PENGECEKAN HYDRANT	-	-	-
354	2024-11-06	LT 02 STORE BANQUET	PENGECEKAN HYDRANT	-	-	-
355	2024-11-06	LT 02 STORE BANQUET	PENGECEKAN HYDRANT	-	-	-
356	2024-11-06	LT 02 STORE BANQUET	PENGECEKAN PANEL LISTRIK	-	-	-
357	2024-11-06	LT 02 STORE BANQUET	PENGECEKAN PANEL LISTRIK	-	-	-
358	2024-11-06	LT 02 STORE BANQUET	PENGECEKAN PANEL LISTRIK	-	-	-
359	2024-11-06	LT 02 SMOKING AREA	PENGECEKAN APAR	-	-	-
360	2024-11-06	LT 02 SMOKING AREA	PENGECEKAN APAR	-	-	-
361	2024-11-06	LT 02 SMOKING AREA	PENGECEKAN APAR	-	-	-
362	2024-11-06	LT 02 SMOKING AREA	PENGECEKAN HYDRANT	-	-	-
363	2024-11-06	LT 02 SMOKING AREA	PENGECEKAN HYDRANT	-	-	-
364	2024-11-06	LT 02 SMOKING AREA	PENGECEKAN HYDRANT	-	-	-
365	2024-11-06	LT 02 CENDANA 1	PENGECEKAN APAR	-	-	-
366	2024-11-06	LT 02 CENDANA 1	PENGECEKAN APAR	-	-	-
367	2024-11-06	LT 02 CENDANA 1	PENGECEKAN APAR	-	-	-
368	2024-11-06	LT 02 CENDANA 1	PENGECEKAN HYDRANT	-	-	-
369	2024-11-06	LT 02 CENDANA 1	PENGECEKAN HYDRANT	-	-	-
370	2024-11-06	LT 02 CENDANA 1	PENGECEKAN HYDRANT	-	-	-
371	2024-11-06	LT 02 PANTRY	PENGECEKAN APAR	-	-	-
372	2024-11-06	LT 02 PANTRY	PENGECEKAN APAR	-	-	-
373	2024-11-06	LT 02 PANTRY	PENGECEKAN APAR	-	-	-
374	2024-11-06	LT 02 PANTRY	PENGECEKAN HYDRANT	-	-	-
375	2024-11-06	LT 02 PANTRY	PENGECEKAN HYDRANT	-	-	-
376	2024-11-06	LT 02 PANTRY	PENGECEKAN HYDRANT	-	-	-
377	2024-11-06	LT 02 PANTRY	PENGECEKAN EMERGENCY EXIT	-	-	-
378	2024-11-06	LT 02 PANTRY	PENGECEKAN EMERGENCY EXIT	-	-	-
379	2024-11-06	LT 02 PANTRY	PENGECEKAN EMERGENCY EXIT	-	-	-
380	2024-11-06	LT 02 KITCHEN BANQUET	PENGECEKAN APAR	-	-	-
381	2024-11-06	LT 02 KITCHEN BANQUET	PENGECEKAN APAR	-	-	-
382	2024-11-06	LT 02 KITCHEN BANQUET	PENGECEKAN APAR	-	-	-
383	2024-11-06	LT 02 KITCHEN BANQUET	PENGECEKAN HYDRANT	-	-	-
384	2024-11-06	LT 02 KITCHEN BANQUET	PENGECEKAN HYDRANT	-	-	-
385	2024-11-06	LT 02 KITCHEN BANQUET	PENGECEKAN HYDRANT	-	-	-
386	2024-11-06	LT 02 KITCHEN BANQUET	PENGECEKAN EMERGENCY EXIT	-	-	-
387	2024-11-06	LT 02 KITCHEN BANQUET	PENGECEKAN EMERGENCY EXIT	-	-	-
388	2024-11-06	LT 02 KITCHEN BANQUET	PENGECEKAN EMERGENCY EXIT	-	-	-
389	2024-11-06	LT 02 STAIRCASE WING B	PENGECEKAN PINTU STAIRCASE	-	-	-

	2024-11-06	LT 00 OTALBOADE MUNIO B				
391		LT 02 STAIRCASE WING B	PENGECEKAN PINTU STAIRCASE	-	-	-
	2024-11-06	LT 02 STAIRCASE WING B	PENGECEKAN PINTU STAIRCASE	-	-	-
392	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN APAR	-	-	-
393	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN APAR	-	-	-
394	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN APAR	-	-	-
395	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN HYDRANT	-	-	-
396	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN HYDRANT	-	-	-
397	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN HYDRANT	-	-	-
398	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN EMERGENCY EXIT	-	-	-
399	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN EMERGENCY EXIT	-	-	-
400	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN EMERGENCY EXIT	-	-	-
401	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN PANEL LISTRIK	-	-	-
402	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN PANEL LISTRIK	-	-	-
403	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN PANEL LISTRIK	-	-	-
404	2024-11-06	LT 01 KITCHEN BOTANY 1	PENGECEKAN APAR	-	-	
405	2024-11-06	LT 01 KITCHEN BOTANY 1	PENGECEKAN APAR	-	-	-
406	2024-11-06	LT 01 KITCHEN BOTANY 1	PENGECEKAN APAR	-	-	-
407	2024-11-06	LT 01 KITCHEN BOTANY 1	PENGECEKAN HYDRANT	-	-	-
408	2024-11-06	LT 01 KITCHEN BOTANY 1	PENGECEKAN HYDRANT	-	-	-
409	2024-11-06	LT 01 KITCHEN BOTANY 1	PENGECEKAN HYDRANT	-	-	-
410	2024-11-06	LT 01 KITCHEN BOTANY 1	PENGECEKAN EMERGENCY EXIT	-	-	-
411	2024-11-06	LT 01 KITCHEN BOTANY 1	PENGECEKAN EMERGENCY EXIT	-	-	-
412	2024-11-06	LT 01 KITCHEN BOTANY 1	PENGECEKAN EMERGENCY EXIT	-	-	-
413	2024-11-06	LT 01 KITCHEN BOTANY 2	PENGECEKAN APAR	-	-	-
414	2024-11-06	LT 01 KITCHEN BOTANY 2	PENGECEKAN APAR	-	-	-
415	2024-11-06	LT 01 KITCHEN BOTANY 2	PENGECEKAN APAR	-	-	-
416	2024-11-06	LT 01 KITCHEN BOTANY 2	PENGECEKAN HYDRANT	-	-	-
417	2024-11-06	LT 01 KITCHEN BOTANY 2	PENGECEKAN HYDRANT	-	-	-
418	2024-11-06	LT 01 KITCHEN BOTANY 2	PENGECEKAN HYDRANT	-	-	-
419	2024-11-06	LT 01 KITCHEN BOTANY 2	PENGECEKAN EMERGENCY EXIT	-	-	-
420	2024-11-06	LT 01 KITCHEN BOTANY 2	PENGECEKAN EMERGENCY EXIT	-	-	-
421	2024-11-06	LT 01 KITCHEN BOTANY 2	PENGECEKAN EMERGENCY EXIT	-	-	-
422	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN APAR	-	-	-
423	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN APAR	-	-	-
424	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN APAR	-	-	-
425	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN HYDRANT	-	-	-
426	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN HYDRANT	-	-	-
427	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN HYDRANT	-	-	-
428	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN EMERGENCY EXIT	-	-	-

2004-1-1-08	No	Tanggal	Task	Point	Status	Description	Petugas
19	29	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN EMERGENCY EXIT	-	-	-
422 2024-11-06 LT 01 SERVER ROOM PENGEDEMA PANEL LETRIK . . 433 2024-11-06 LT 01 SERVER ROOM PENGEDEMA PANEL LETRIK . . 444 2024-11-06 LT 01 GAS ROOM PENGEDEMA PANE . . 456 2024-11-06 LT 01 GAS ROOM PENGEDEMA PANE . . 457 2024-11-06 LT 01 GAS ROOM PENGEDEMA HURANT . . 458 2024-11-06 LT 01 GAS ROOM PENGEDEMA HURANT . . 459 2024-11-06 LT 01 GAS ROOM PENGEDEMA HURANT . . 460 2024-11-06 LT 01 GAS ROOM PENGEDEMA HURANT . . 470 2024-11-06 LT 01 GAS ROOM PENGEDEMA HURANT . . 481 2024-11-06 LT 01 GAS ROOM PENGEDEMA HURANT . . 482 2024-11-06 LT 01 LOADRIG DOCK PENGEDEMA HURANT . . 484 2024-11-06 LT 01 LOADRIG DOCK PENGEDEMA HURANT	30	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN EMERGENCY EXIT	-	-	-
AND PENGECKAN PANEL LISTRIK	31 :	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN PANEL LISTRIK	-	-	-
441 2021-11-08 LT OF GAS ROOM PENGECERAN APAR - - 455 2024-11-08 LT OF GAS ROOM PENGECERAN APAR - - 456 2024-11-08 LT OF GAS ROOM PENGECERAN APAR - - 457 2024-11-08 LT OF GAS ROOM PENGECERAN HYDRANT - - 440 2024-11-08 LT OF GAS ROOM PENGECERAN HYDRANT - - 440 2024-11-08 LT OF GAS ROOM PENGECERAN EMERGENCY EXIT - - 441 2024-11-08 LT OF GAS ROOM PENGECERAN EMERGENCY EXIT - - 442 2024-11-08 LT OF GAS ROOM PENGECERAN EMERGENCY EXIT - - 443 2024-11-08 LT OF LOADING DOOK PENGECERAN EMERGENCY EXIT - - 444 2024-11-08 LT OF LOADING DOOK PENGECERAN APAR - - 445 2024-11-08 LT OF LOADING DOOK PENGECERAN HYDRANT - - 446 2024-11-08 LT OF LOADING DOOK	32	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN PANEL LISTRIK	-	-	-
4-95 2024-11-08 LT OI GAS ROOM PENGECEKAN AFAR . . . 4-86 2024-11-08 LT OI GAS ROOM PENGECEKAN AFAR . . . 4-77 2024-11-08 LT OI GAS ROOM PENGECEKAN HYDRAHT . . . 4-00 2024-11-08 LT OI GAS ROOM PENGECEKAN HYDRAHT . . . 4-00 2024-11-08 LT OI GAS ROOM PENGECEKAN EMBREGENCY EXIT . . . 4-01 2024-11-08 LT OI GAS ROOM PENGECEKAN EMBREGENCY EXIT . . . 4-02 2024-11-08 LT OI GAS ROOM PENGECEKAN EMBREGENCY EXIT . . . 4-03 2024-11-08 LT OI LOADING DOOK PENGECEKAN AFAR .	33	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN PANEL LISTRIK	-	-	-
10 10 10 10 10 10 10 10	34	2024-11-06	LT 01 GAS ROOM	PENGECEKAN APAR	-	-	-
477 202411-06 LTO GAS ROOM PENGECEKAN HYDRANT . . 480 202411-06 LTO GAS ROOM PENGECEKAN HYDRANT . . 490 202411-06 LTO GAS ROOM PENGECEKAN HYDRANT . . 440 202411-06 LTO GAS ROOM PENGECEKAN EMERGENCY EXIT . . 441 202411-06 LTO GAS ROOM PENGECEKAN EMERGENCY EXIT . . 442 202411-06 LTO LOADING DOCK PENGECEKAN APAR . . 443 202411-06 LTO LOADING DOCK PENGECEKAN APAR . . 444 202411-06 LTO LOADING DOCK PENGECEKAN HYDRANT . . 446 202411-06 LTO LOADING DOCK PENGECEKAN HYDRANT . . 447 202411-06 LTO LOADING DOCK PENGECEKAN HYDRANT . . 448 202411-06 LTO LOADING DOCK PENGECEKAN HYDRANT . . 450 202411-06 LTO LOADING DOCK PENGECEKAN HARRA	35	2024-11-06	LT 01 GAS ROOM	PENGECEKAN APAR	-	-	-
2024-11-06	36	2024-11-06	LT 01 GAS ROOM	PENGECEKAN APAR	-	-	-
2024-11-08	37 :	2024-11-06	LT 01 GAS ROOM	PENGECEKAN HYDRANT	-	-	-
PRINCECEKAN EMERGENCY EXIT	38 :	2024-11-06	LT 01 GAS ROOM	PENGECEKAN HYDRANT	-	-	-
Add	39 :	2024-11-06	LT 01 GAS ROOM	PENGECEKAN HYDRANT	-	-	-
A42 2024-11-06	40 :	2024-11-06	LT 01 GAS ROOM	PENGECEKAN EMERGENCY EXIT	-	-	-
443 2024-11-06	41 :	2024-11-06	LT 01 GAS ROOM	PENGECEKAN EMERGENCY EXIT	-	-	-
444 2024-11-06 LT 01 LOADING DOCK PENGECEKAN APAR - - 445 2024-11-06 LT 01 LOADING DOCK PENGECEKAN APAR - - 446 2024-11-06 LT 01 LOADING DOCK PENGECEKAN HYDRANT - - 447 2024-11-06 LT 01 LOADING DOCK PENGECEKAN HYDRANT - - 448 2024-11-06 LT 01 LOADING DOCK PENGECEKAN HYDRANT - - 449 2024-11-06 LT 01 LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 450 2024-11-06 LT 01 LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 451 2024-11-06 LT 01 LOADING DOCK PENGECEKAN PANEL LISTRIK - - 452 2024-11-06 LT 01 LOADING DOCK PENGECEKAN PANEL LISTRIK - - 453 2024-11-06 LT 01 LOADING DOCK PENGECEKAN PANEL LISTRIK - - 454 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN PANEL LISTRIK - - 456 2024-	42	2024-11-06	LT 01 GAS ROOM	PENGECEKAN EMERGENCY EXIT	-	-	-
445 2024-11-06 LT 01 LOADING DOCK PENGECEKAN APAR - - 446 2024-11-06 LT 01 LOADING DOCK PENGECEKAN HYDRANT - - 447 2024-11-06 LT 01 LOADING DOCK PENGECEKAN HYDRANT - - 448 2024-11-06 LT 01 LOADING DOCK PENGECEKAN HYDRANT - - 449 2024-11-06 LT 01 LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 450 2024-11-06 LT 01 LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 451 2024-11-06 LT 01 LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 452 2024-11-06 LT 01 LOADING DOCK PENGECEKAN PANEL LISTRIK - - 453 2024-11-06 LT 01 LOADING DOCK PENGECEKAN PANEL LISTRIK - - 454 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 455 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 456 2024-1	43	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN APAR	-	-	-
446 2024-11-06	44 :	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN APAR	-	-	-
447 2024-11-06 LT 01 LOADING DOCK PENGECEKAN HYDRANT - - 448 2024-11-06 LT 01 LOADING DOCK PENGECEKAN HYDRANT - - 449 2024-11-06 LT 01 LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 450 2024-11-06 LT 01 LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 451 2024-11-06 LT 01 LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 452 2024-11-06 LT 01 LOADING DOCK PENGECEKAN PANEL LISTRIK - - 453 2024-11-06 LT 01 LOADING DOCK PENGECEKAN PANEL LISTRIK - - 454 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN PANEL LISTRIK - - 455 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 456 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 457 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 459<	45 :	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN APAR	-	-	-
448 2024-11-06 LT 01 LOADING DOCK PENGECEKAN HYDRANT - - 449 2024-11-06 LT 01 LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 450 2024-11-06 LT 01 LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 451 2024-11-06 LT 01 LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 452 2024-11-06 LT 01 LOADING DOCK PENGECEKAN PANEL LISTRIK - - 453 2024-11-06 LT 01 LOADING DOCK PENGECEKAN PANEL LISTRIK - - 454 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN PANEL LISTRIK - - 455 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 456 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 457 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 459 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - <	46	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN HYDRANT	-	-	-
449 2024-11-06 LT 01 LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 450 2024-11-06 LT 01 LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 451 2024-11-06 LT 01 LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 452 2024-11-06 LT 01 LOADING DOCK PENGECEKAN PANEL LISTRIK - - 453 2024-11-06 LT 01 LOADING DOCK PENGECEKAN PANEL LISTRIK - - 454 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN PANEL LISTRIK - - 455 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 456 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 457 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 459 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 460 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - -	47 :	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN HYDRANT	-	-	-
450 2024-11-06 LT 01 LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 451 2024-11-06 LT 01 LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 452 2024-11-06 LT 01 LOADING DOCK PENGECEKAN PANEL LISTRIK - - 453 2024-11-06 LT 01 LOADING DOCK PENGECEKAN PANEL LISTRIK - - 454 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 455 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 456 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 457 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 458 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 460 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 461 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - -	48	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN HYDRANT	-	-	-
451 2024-11-06 LT 01 LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 452 2024-11-06 LT 01 LOADING DOCK PENGECEKAN PANEL LISTRIK - - 453 2024-11-06 LT 01 LOADING DOCK PENGECEKAN PANEL LISTRIK - - 454 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN PANEL LISTRIK - - 455 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 456 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 457 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 458 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 460 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 461 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 462 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - -	49	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN EMERGENCY EXIT	-	-	-
452 2024-11-06 LT 01 LOADING DOCK PENGECEKAN PANEL LISTRIK - - 453 2024-11-06 LT 01 LOADING DOCK PENGECEKAN PANEL LISTRIK - - 454 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN PANEL LISTRIK - - 455 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 456 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 457 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 458 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 460 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 461 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 462 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 463 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - -	50 :	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN EMERGENCY EXIT	-	-	-
453 2024-11-06 LT 01 LOADING DOCK PENGECEKAN PANEL LISTRIK - - 454 2024-11-06 LT 01 LOADING DOCK PENGECEKAN PANEL LISTRIK - - 455 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 456 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 457 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 458 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 459 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 460 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 461 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 462 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 463 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - -	51 :	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN EMERGENCY EXIT	-	-	-
454 2024-11-06 LT 01 LOADING DOCK PENGECEKAN PANEL LISTRIK - - 455 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 456 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 457 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 458 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 459 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 460 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 461 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 462 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 463 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - -	52	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN PANEL LISTRIK	-	-	-
455 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 456 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 457 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 458 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 459 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 460 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 461 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 462 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 463 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - -	53	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN PANEL LISTRIK	-	-	-
456 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 457 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 458 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 459 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 460 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 461 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 462 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 463 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - -	54 :	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN PANEL LISTRIK	-	-	-
457 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN APAR - - 458 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 459 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 460 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 461 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 462 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 463 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - -	55	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN APAR	-	-	-
458 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 459 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 460 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 461 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 462 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 463 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - -	56	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN APAR	-	-	-
459 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 460 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - 461 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 462 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 463 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - -	57	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN APAR	-	-	-
460 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN HYDRANT - - - 461 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 462 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 463 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - -	58	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN HYDRANT	-	-	-
461 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - - 462 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - 463 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - -	59 :	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN HYDRANT	-	-	-
462 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - - 463 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT - - -	60	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN HYDRANT	-	-	-
463 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT	61	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN EMERGENCY EXIT	-	-	-
	62	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN EMERGENCY EXIT	-	-	-
	63	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN EMERGENCY EXIT	-	-	-
464 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN PANEL LISTRIK	64	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN PANEL LISTRIK	-	-	-
465 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN PANEL LISTRIK	65	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN PANEL LISTRIK	-	-	-
466 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN PANEL LISTRIK	66	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN PANEL LISTRIK	-	-	-
467 2024-11-06 LT 01 GARDEN BOTANY PENGECEKAN APAR	67	2024-11-06	LT 01 GARDEN BOTANY	PENGECEKAN APAR	-	-	-

No	Tanggal	Task	Point	Status	Description	Petugas
468	2024-11-06	LT 01 GARDEN BOTANY	PENGECEKAN APAR	-	-	-
469	2024-11-06	LT 01 GARDEN BOTANY	PENGECEKAN APAR	-	-	-
470	2024-11-06	LT 01 GARDEN BOTANY	PENGECEKAN HYDRANT	-	-	-
471	2024-11-06	LT 01 GARDEN BOTANY	PENGECEKAN HYDRANT	-	-	-
472	2024-11-06	LT 01 GARDEN BOTANY	PENGECEKAN HYDRANT	-	-	-
473	2024-11-06	LT 01 CAR CHECK	PENGECEKAN APAR	-	-	-
474	2024-11-06	LT 01 CAR CHECK	PENGECEKAN APAR	-	-	-
475	2024-11-06	LT 01 CAR CHECK	PENGECEKAN APAR	-	-	-
476	2024-11-06	LT 01 CAR CHECK	PENGECEKAN HYDRANT	-	-	-
477	2024-11-06	LT 01 CAR CHECK	PENGECEKAN HYDRANT	-	-	-
478	2024-11-06	LT 01 CAR CHECK	PENGECEKAN HYDRANT	-	-	-
479	2024-11-06	LT 01 CAR CHECK	PENGECEKAN EMERGENCY EXIT	-	-	-
480	2024-11-06	LT 01 CAR CHECK	PENGECEKAN EMERGENCY EXIT	-	-	-
481	2024-11-06	LT 01 CAR CHECK	PENGECEKAN EMERGENCY EXIT	-	-	-
482	2024-11-06	LT 01 CAR CHECK	PENGECEKAN PANEL LISTRIK	-	-	-
483	2024-11-06	LT 01 CAR CHECK	PENGECEKAN PANEL LISTRIK	-	-	-
484	2024-11-06	LT 01 CAR CHECK	PENGECEKAN PANEL LISTRIK	-	-	-
485	2024-11-06	LT 01 VALET PARKING (NEAR BG)	PENGECEKAN APAR	-	-	-
486	2024-11-06	LT 01 VALET PARKING (NEAR BG)	PENGECEKAN APAR	-	-	-
487	2024-11-06	LT 01 VALET PARKING (NEAR BG)	PENGECEKAN APAR	-	-	
488	2024-11-06	LT 01 VALET PARKING (NEAR BG)	PENGECEKAN HYDRANT	-	-	
489	2024-11-06	LT 01 VALET PARKING (NEAR BG)	PENGECEKAN HYDRANT	-	-	-
490	2024-11-06	LT 01 VALET PARKING (NEAR BG)	PENGECEKAN HYDRANT	-	-	-
491	2024-11-06	LT 01 VALET PARKING (NEAR BG)	PENGECEKAN EMERGENCY EXIT	-	-	-
492	2024-11-06	LT 01 VALET PARKING (NEAR BG)	PENGECEKAN EMERGENCY EXIT	-	-	-
493	2024-11-06	LT 01 VALET PARKING (NEAR BG)	PENGECEKAN EMERGENCY EXIT	-	-	-
494	2024-11-06	LT 01 NEAR FB OFFICE	PENGECEKAN APAR	-	-	-
495	2024-11-06	LT 01 NEAR FB OFFICE	PENGECEKAN APAR	-	-	-
496	2024-11-06	LT 01 NEAR FB OFFICE	PENGECEKAN APAR	-	-	-
497	2024-11-06	LT 01 NEAR FB OFFICE	PENGECEKAN HYDRANT	-	-	-
498	2024-11-06	LT 01 NEAR FB OFFICE	PENGECEKAN HYDRANT	-	-	-
499	2024-11-06	LT 01 NEAR FB OFFICE	PENGECEKAN HYDRANT	-	-	-
500	2024-11-06	LT 01 NEAR FB OFFICE	PENGECEKAN EMERGENCY EXIT	-	-	