## Report Patroli (2024-11-01 to 2024-11-06)

No	Tanggal	Task	Point	Status	Description	Petugas
1	2024-11-06	LT 15 WING A	PENGECEKAN APAR			
2	2024-11-06	LT 15 WING A	PENGECEKAN KORIDOR			
3	2024-11-06	LT 15 WING A	PENGECEKAN KORIDOR			
4	2024-11-06	LT 15 WING A	PENGECEKAN KORIDOR			
5	2024-11-06	LT 15 WING A	PENGECEKAN HYDRANT			
6	2024-11-06	LT 15 WING A	PENGECEKAN HYDRANT			
7	2024-11-06	LT 15 WING A	PENGECEKAN HYDRANT			
8	2024-11-06	LT 15 WING A	PENGECEKAN EMERGENCY EXIT			
9	2024-11-06	LT 15 WING A	PENGECEKAN EMERGENCY EXIT			
10	2024-11-06	LT 15 WING A	PENGECEKAN EMERGENCY EXIT			
11	2024-11-06	LT 15 WING A	PENGECEKAN PINTU KAMAR			
12	2024-11-06	LT 15 WING A	PENGECEKAN PINTU KAMAR			
13	2024-11-06	LT 15 WING A	PENGECEKAN PINTU KAMAR			
14	2024-11-06	LT 12 WING A	PENGECEKAN APAR			
15	2024-11-06	LT 12 WING A	PENGECEKAN APAR			
16	2024-11-06	LT 12 WING A	PENGECEKAN APAR			
17	2024-11-06	LT 12 WING A	PENGECEKAN KORIDOR			
18	2024-11-06	LT 12 WING A	PENGECEKAN KORIDOR			
19	2024-11-06	LT 12 WING A	PENGECEKAN KORIDOR			
20	2024-11-06	LT 12 WING A	PENGECEKAN HYDRANT			
21	2024-11-06	LT 12 WING A	PENGECEKAN HYDRANT			
22	2024-11-06	LT 12 WING A	PENGECEKAN HYDRANT			
23	2024-11-06	LT 12 WING A	PENGECEKAN EMERGENCY EXIT			
24	2024-11-06	LT 12 WING A	PENGECEKAN EMERGENCY EXIT			
25	2024-11-06	LT 12 WING A	PENGECEKAN EMERGENCY EXIT			
26	2024-11-06	LT 12 WING A	PENGECEKAN PINTU KAMAR			
27	2024-11-06	LT 12 WING A	PENGECEKAN PINTU KAMAR			
28	2024-11-06	LT 12 WING A	PENGECEKAN PINTU KAMAR			
29	2024-11-06	LT 12 WING B	PENGECEKAN APAR			
30	2024-11-06	LT 12 WING B	PENGECEKAN APAR			
31	2024-11-06	LT 12 WING B	PENGECEKAN APAR			
32	2024-11-06	LT 12 WING B	PENGECEKAN HYDRANT			
33	2024-11-06	LT 12 WING B	PENGECEKAN HYDRANT			
34	2024-11-06	LT 12 WING B	PENGECEKAN HYDRANT			
35	2024-11-06	LT 12 WING B	PENGECEKAN EMERGENCY EXIT			
36	2024-11-06	LT 12 WING B	PENGECEKAN EMERGENCY EXIT			
37	2024-11-06	LT 12 WING B	PENGECEKAN EMERGENCY EXIT			
38	2024-11-06	LT 12 WING B	PENGECEKAN PINTU KAMAR			

19	No	Tanggal	Task	Point	Status	Description	Petugas
1	39	2024-11-06	LT 12 WING B	PENGECEKAN PINTU KAMAR			
20241106	40	2024-11-06	LT 12 WING B	PENGECEKAN PINTU KAMAR			
2021-11-06	41	2024-11-06	LT 12 WING B	PENGECEKAN KORIDOR			
A	42	2024-11-06	LT 12 WING B	PENGECEKAN KORIDOR			
10	43	2024-11-06	LT 12 WING B	PENGECEKAN KORIDOR			
1	44	2024-11-06	LT 11 WING B	PENGECEKAN APAR			
2024-11-06	45	2024-11-06	LT 11 WING B	PENGECEKAN APAR			
2024-11-06	46	2024-11-06	LT 11 WING B	PENGECEKAN APAR			
2024-11-06	47	2024-11-06	LT 11 WING B	PENGECEKAN HYDRANT			
10	48	2024-11-06	LT 11 WING B	PENGECEKAN HYDRANT			
1	49	2024-11-06	LT 11 WING B	PENGECEKAN HYDRANT			
2024-11-06	50	2024-11-06	LT 11 WING B	PENGECEKAN EMERGENCY EXIT			
1	51	2024-11-06	LT 11 WING B	PENGECEKAN EMERGENCY EXIT			
54         2024-11-06         LT 11 WING B         PENGECEKAN PINTU KAMAR           55         2024-11-06         LT 11 WING B         PENGECEKAN PINTU KAMAR           56         2024-11-06         LT 11 WING B         PENGECEKAN KORIDOR           57         2024-11-06         LT 11 WING B         PENGECEKAN KORIDOR           58         2024-11-06         LT 11 WING A         PENGECEKAN KORIDOR           59         2024-11-06         LT 11 WING A         PENGECEKAN APAR           60         2024-11-06         LT 11 WING A         PENGECEKAN APAR           61         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT           62         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT           64         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT           65         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT           66         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT           67         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT           68         2024-11-06         LT 11 WING A         PENGECEKAN PINTU KAMAR           70         2024-11-06         LT 11 WING A         PENGECEKAN PINTU KAMAR           <	52	2024-11-06	LT 11 WING B	PENGECEKAN EMERGENCY EXIT			
55         2024-11-06         LT 11 WING B         PENGECEKAN PINTU KAMAR           56         2024-11-06         LT 11 WING B         PENGECEKAN KORIDOR           57         2024-11-06         LT 11 WING B         PENGECEKAN KORIDOR           58         2024-11-06         LT 11 WING A         PENGECEKAN KORIDOR           59         2024-11-06         LT 11 WING A         PENGECEKAN APAR           60         2024-11-06         LT 11 WING A         PENGECEKAN APAR           61         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT           62         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT           63         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT           64         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT           65         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT           66         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT           67         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT           68         2024-11-06         LT 11 WING A         PENGECEKAN PINTU KAMAR           70         2024-11-06         LT 11 WING A         PENGECEKAN KORIDOR           71 <td>53</td> <td>2024-11-06</td> <td>LT 11 WING B</td> <td>PENGECEKAN PINTU KAMAR</td> <td></td> <td></td> <td></td>	53	2024-11-06	LT 11 WING B	PENGECEKAN PINTU KAMAR			
56         2024-11-06         LT 11 WING B         PENGECEKAN KORIDOR           57         2024-11-06         LT 11 WING B         PENGECEKAN KORIDOR           58         2024-11-06         LT 11 WING A         PENGECEKAN KORIDOR           59         2024-11-06         LT 11 WING A         PENGECEKAN APAR           60         2024-11-06         LT 11 WING A         PENGECEKAN APAR           61         2024-11-06         LT 11 WING A         PENGECEKAN APAR           62         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT           63         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT           64         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT           65         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT           66         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT           67         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT           68         2024-11-06         LT 11 WING A         PENGECEKAN PINTU KAMAR           69         2024-11-06         LT 11 WING A         PENGECEKAN PINTU KAMAR           70         2024-11-06         LT 11 WING A         PENGECEKAN KORIDOR           71	54	2024-11-06	LT 11 WING B	PENGECEKAN PINTU KAMAR			
57         2024-11-06         LT 11 WING B         PENGECEKAN KORIDOR           58         2024-11-06         LT 11 WING A         PENGECEKAN KORIDOR           59         2024-11-06         LT 11 WING A         PENGECEKAN APAR           60         2024-11-06         LT 11 WING A         PENGECEKAN APAR           61         2024-11-06         LT 11 WING A         PENGECEKAN APAR           62         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT           63         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT           64         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT           65         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT           66         2024-11-06         LT 11 WING A         PENGECEKAN PINTU KAMAR           69         2024-11-06         LT 11 WING A         PENGECEKAN PINTU KAMAR           70         2024-11-06         LT 11 WING A         PENGECEKAN PINTU KAMAR           71         2024-11-06         LT 11 WING A         PENGECEKAN PINTU KAMAR           71         2024-11-06         LT 11 WING A         PENGECEKAN KORIDOR           72         2024-11-06         LT 11 WING A         PENGECEKAN KORIDOR           73	55	2024-11-06	LT 11 WING B	PENGECEKAN PINTU KAMAR			
58         2024-11-06         LT 11 WING B         PENGECEKAN KORIDOR           59         2024-11-06         LT 11 WING A         PENGECEKAN APAR           60         2024-11-06         LT 11 WING A         PENGECEKAN APAR           61         2024-11-06         LT 11 WING A         PENGECEKAN APAR           62         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT           63         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT           64         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT           65         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT           66         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT           68         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT           68         2024-11-06         LT 11 WING A         PENGECEKAN PINTU KAMAR           69         2024-11-06         LT 11 WING A         PENGECEKAN PINTU KAMAR           70         2024-11-06         LT 11 WING A         PENGECEKAN KORIDOR           71         2024-11-06         LT 11 WING A         PENGECEKAN KORIDOR           73         2024-11-06         LT 11 WING A         PENGECEKAN KORIDOR           74	56	2024-11-06	LT 11 WING B	PENGECEKAN KORIDOR			
59         2024-11-06         LT 11 WING A         PENGECEKAN APAR           60         2024-11-06         LT 11 WING A         PENGECEKAN APAR           61         2024-11-06         LT 11 WING A         PENGECEKAN APAR           62         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT           63         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT           64         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT           65         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT           66         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT           67         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT           68         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT           69         2024-11-06         LT 11 WING A         PENGECEKAN PINTU KAMAR           70         2024-11-06         LT 11 WING A         PENGECEKAN PINTU KAMAR           71         2024-11-06         LT 11 WING A         PENGECEKAN KORIDOR           72         2024-11-06         LT 11 WING A         PENGECEKAN KORIDOR           73         2024-11-06         LT 11 WING A         PENGECEKAN APAR	57	2024-11-06	LT 11 WING B	PENGECEKAN KORIDOR			
60         2024-11-06         LT 11 WING A         PENGECEKAN APAR           61         2024-11-06         LT 11 WING A         PENGECEKAN APAR           62         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT           63         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT           64         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT           65         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT           66         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT           67         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT           68         2024-11-06         LT 11 WING A         PENGECEKAN PINTU KAMAR           69         2024-11-06         LT 11 WING A         PENGECEKAN PINTU KAMAR           70         2024-11-06         LT 11 WING A         PENGECEKAN KORIDOR           71         2024-11-06         LT 11 WING A         PENGECEKAN KORIDOR           72         2024-11-06         LT 11 WING A         PENGECEKAN KORIDOR           73         2024-11-06         LT 11 WING A         PENGECEKAN KORIDOR           74         2024-11-06         LT 10 WING A         PENGECEKAN APAR	58	2024-11-06	LT 11 WING B	PENGECEKAN KORIDOR			
61       2024-11-06       LT 11 WING A       PENGECEKAN APAR         62       2024-11-06       LT 11 WING A       PENGECEKAN HYDRANT         63       2024-11-06       LT 11 WING A       PENGECEKAN HYDRANT         64       2024-11-06       LT 11 WING A       PENGECEKAN HYDRANT         65       2024-11-06       LT 11 WING A       PENGECEKAN EMERGENCY EXIT         66       2024-11-06       LT 11 WING A       PENGECEKAN EMERGENCY EXIT         67       2024-11-06       LT 11 WING A       PENGECEKAN EMERGENCY EXIT         68       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR         69       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR         70       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         71       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         72       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         73       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         74       2024-11-06       LT 10 WING A       PENGECEKAN APAR	59	2024-11-06	LT 11 WING A	PENGECEKAN APAR			
62       2024-11-06       LT 11 WING A       PENGECEKAN HYDRANT         63       2024-11-06       LT 11 WING A       PENGECEKAN HYDRANT         64       2024-11-06       LT 11 WING A       PENGECEKAN HYDRANT         65       2024-11-06       LT 11 WING A       PENGECEKAN EMERGENCY EXIT         66       2024-11-06       LT 11 WING A       PENGECEKAN EMERGENCY EXIT         67       2024-11-06       LT 11 WING A       PENGECEKAN EMERGENCY EXIT         68       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR         69       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR         70       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR         71       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         72       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         73       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         74       2024-11-06       LT 10 WING A       PENGECEKAN APAR	60	2024-11-06	LT 11 WING A	PENGECEKAN APAR			
63       2024-11-06       LT 11 WING A       PENGECEKAN HYDRANT         64       2024-11-06       LT 11 WING A       PENGECEKAN HYDRANT         65       2024-11-06       LT 11 WING A       PENGECEKAN EMERGENCY EXIT         66       2024-11-06       LT 11 WING A       PENGECEKAN EMERGENCY EXIT         67       2024-11-06       LT 11 WING A       PENGECEKAN EMERGENCY EXIT         68       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR         69       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR         70       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         71       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         72       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         73       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         74       2024-11-06       LT 10 WING A       PENGECEKAN APAR	61	2024-11-06	LT 11 WING A	PENGECEKAN APAR			
64       2024-11-06       LT 11 WING A       PENGECEKAN HYDRANT         65       2024-11-06       LT 11 WING A       PENGECEKAN EMERGENCY EXIT         66       2024-11-06       LT 11 WING A       PENGECEKAN EMERGENCY EXIT         67       2024-11-06       LT 11 WING A       PENGECEKAN EMERGENCY EXIT         68       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR         69       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR         70       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR         71       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         72       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         73       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         74       2024-11-06       LT 10 WING A       PENGECEKAN APAR	62	2024-11-06	LT 11 WING A	PENGECEKAN HYDRANT			
65 2024-11-06 LT 11 WING A PENGECEKAN EMERGENCY EXIT  66 2024-11-06 LT 11 WING A PENGECEKAN EMERGENCY EXIT  67 2024-11-06 LT 11 WING A PENGECEKAN EMERGENCY EXIT  68 2024-11-06 LT 11 WING A PENGECEKAN PINTU KAMAR  69 2024-11-06 LT 11 WING A PENGECEKAN PINTU KAMAR  70 2024-11-06 LT 11 WING A PENGECEKAN PINTU KAMAR  71 2024-11-06 LT 11 WING A PENGECEKAN KORIDOR  72 2024-11-06 LT 11 WING A PENGECEKAN KORIDOR  73 2024-11-06 LT 11 WING A PENGECEKAN KORIDOR  74 2024-11-06 LT 10 WING A PENGECEKAN KORIDOR	63	2024-11-06	LT 11 WING A	PENGECEKAN HYDRANT			
66       2024-11-06       LT 11 WING A       PENGECEKAN EMERGENCY EXIT         67       2024-11-06       LT 11 WING A       PENGECEKAN EMERGENCY EXIT         68       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR         69       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR         70       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         71       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         72       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         73       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         74       2024-11-06       LT 10 WING A       PENGECEKAN APAR	64	2024-11-06	LT 11 WING A	PENGECEKAN HYDRANT			
67       2024-11-06       LT 11 WING A       PENGECEKAN EMERGENCY EXIT         68       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR         69       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR         70       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR         71       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         72       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         73       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         74       2024-11-06       LT 10 WING A       PENGECEKAN APAR	65	2024-11-06	LT 11 WING A	PENGECEKAN EMERGENCY EXIT			
68       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR         69       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR         70       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR         71       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         72       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         73       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         74       2024-11-06       LT 10 WING A       PENGECEKAN APAR	66	2024-11-06	LT 11 WING A	PENGECEKAN EMERGENCY EXIT			
69       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR         70       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR         71       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         72       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         73       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         74       2024-11-06       LT 10 WING A       PENGECEKAN APAR	67	2024-11-06	LT 11 WING A	PENGECEKAN EMERGENCY EXIT			
70       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR         71       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         72       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         73       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         74       2024-11-06       LT 10 WING A       PENGECEKAN APAR	68	2024-11-06	LT 11 WING A	PENGECEKAN PINTU KAMAR			
71       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         72       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         73       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR         74       2024-11-06       LT 10 WING A       PENGECEKAN APAR	69	2024-11-06	LT 11 WING A	PENGECEKAN PINTU KAMAR			
72         2024-11-06         LT 11 WING A         PENGECEKAN KORIDOR           73         2024-11-06         LT 11 WING A         PENGECEKAN KORIDOR           74         2024-11-06         LT 10 WING A         PENGECEKAN APAR	70	2024-11-06	LT 11 WING A	PENGECEKAN PINTU KAMAR			
73         2024-11-06         LT 11 WING A         PENGECEKAN KORIDOR           74         2024-11-06         LT 10 WING A         PENGECEKAN APAR	71	2024-11-06	LT 11 WING A	PENGECEKAN KORIDOR			
74 2024-11-06 LT 10 WING A PENGECEKAN APAR	72	2024-11-06	LT 11 WING A	PENGECEKAN KORIDOR			
	73	2024-11-06	LT 11 WING A	PENGECEKAN KORIDOR			
75 2024-11-06 LT 10 WING A PENGECEKAN APAR	74	2024-11-06	LT 10 WING A	PENGECEKAN APAR			
	75	2024-11-06	LT 10 WING A	PENGECEKAN APAR			
76 2024-11-06 LT 10 WING A PENGECEKAN APAR	76	2024-11-06	LT 10 WING A	PENGECEKAN APAR			
77 2024-11-06 LT 10 WING A PENGECEKAN HYDRANT	77	2024-11-06	LT 10 WING A	PENGECEKAN HYDRANT			

No	Tanggal	Task	Point	Status	Description	Petugas
78	2024-11-06	LT 10 WING A	PENGECEKAN HYDRANT			
79	2024-11-06	LT 10 WING A	PENGECEKAN HYDRANT			
80	2024-11-06	LT 10 WING A	PENGECEKAN EMERGENCY EXIT			
81	2024-11-06	LT 10 WING A	PENGECEKAN EMERGENCY EXIT			
82	2024-11-06	LT 10 WING A	PENGECEKAN EMERGENCY EXIT			
83	2024-11-06	LT 10 WING A	PENGECEKAN PINTU KAMAR			
84	2024-11-06	LT 10 WING A	PENGECEKAN PINTU KAMAR			
85	2024-11-06	LT 10 WING A	PENGECEKAN PINTU KAMAR			
86	2024-11-06	LT 10 WING A	PENGECEKAN KORIDOR			
87	2024-11-06	LT 10 WING A	PENGECEKAN KORIDOR			
88	2024-11-06	LT 10 WING A	PENGECEKAN KORIDOR			
89	2024-11-06	LT 10 WING B	PENGECEKAN APAR			
90	2024-11-06	LT 10 WING B	PENGECEKAN APAR			
91	2024-11-06	LT 10 WING B	PENGECEKAN APAR			
92	2024-11-06	LT 10 WING B	PENGECEKAN HYDRANT			
93	2024-11-06	LT 10 WING B	PENGECEKAN HYDRANT			
94	2024-11-06	LT 10 WING B	PENGECEKAN HYDRANT			
95	2024-11-06	LT 10 WING B	PENGECEKAN EMERGENCY EXIT			
96	2024-11-06	LT 10 WING B	PENGECEKAN EMERGENCY EXIT			
97	2024-11-06	LT 10 WING B	PENGECEKAN EMERGENCY EXIT			
98	2024-11-06	LT 10 WING B	PENGECEKAN PINTU KAMAR			
99	2024-11-06	LT 10 WING B	PENGECEKAN PINTU KAMAR			
100	2024-11-06	LT 10 WING B	PENGECEKAN PINTU KAMAR			