## Report Patroli (2024-11-01 to 2024-11-13)

No	Tanggal	Task	Point	Status	Description	Petugas
1	2024-11-06	LT 15 WING A	PENGECEKAN APAR	-	-	-
2	2024-11-06	LT 15 WING A	PENGECEKAN KORIDOR	-	-	-
3	2024-11-06	LT 15 WING A	PENGECEKAN KORIDOR	-	-	-
4	2024-11-06	LT 15 WING A	PENGECEKAN KORIDOR	-	-	-
5	2024-11-06	LT 15 WING A	PENGECEKAN HYDRANT	-	-	-
6	2024-11-06	LT 15 WING A	PENGECEKAN HYDRANT	-	-	-
7	2024-11-06	LT 15 WING A	PENGECEKAN HYDRANT	-	-	-
8	2024-11-06	LT 15 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
9	2024-11-06	LT 15 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
10	2024-11-06	LT 15 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
11	2024-11-06	LT 15 WING A	PENGECEKAN PINTU KAMAR	-	-	-
12	2024-11-06	LT 15 WING A	PENGECEKAN PINTU KAMAR	-	-	-
13	2024-11-06	LT 15 WING A	PENGECEKAN PINTU KAMAR	-	-	-
14	2024-11-06	LT 12 WING A	PENGECEKAN APAR	-	-	-
15	2024-11-06	LT 12 WING A	PENGECEKAN APAR	-	-	-
16	2024-11-06	LT 12 WING A	PENGECEKAN APAR	-	-	-
17	2024-11-06	LT 12 WING A	PENGECEKAN KORIDOR	-	-	-
18	2024-11-06	LT 12 WING A	PENGECEKAN KORIDOR	-	-	-
19	2024-11-06	LT 12 WING A	PENGECEKAN KORIDOR	-	-	-
20	2024-11-06	LT 12 WING A	PENGECEKAN HYDRANT	-	-	-
21	2024-11-06	LT 12 WING A	PENGECEKAN HYDRANT	-	-	-
22	2024-11-06	LT 12 WING A	PENGECEKAN HYDRANT	-	-	-
23	2024-11-06	LT 12 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
24	2024-11-06	LT 12 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
25	2024-11-06	LT 12 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
26	2024-11-06	LT 12 WING A	PENGECEKAN PINTU KAMAR	-	-	-
27	2024-11-06	LT 12 WING A	PENGECEKAN PINTU KAMAR	-	-	-
28	2024-11-06	LT 12 WING A	PENGECEKAN PINTU KAMAR	-	-	-
29	2024-11-06	LT 12 WING B	PENGECEKAN APAR	-	-	-
30	2024-11-06	LT 12 WING B	PENGECEKAN APAR	-	-	-
31	2024-11-06	LT 12 WING B	PENGECEKAN APAR	-	-	-
32	2024-11-06	LT 12 WING B	PENGECEKAN HYDRANT	-	-	-
33	2024-11-06	LT 12 WING B	PENGECEKAN HYDRANT	-	-	-
34	2024-11-06	LT 12 WING B	PENGECEKAN HYDRANT	-	-	-
35	2024-11-06	LT 12 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
36	2024-11-06	LT 12 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
37	2024-11-06	LT 12 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
38	2024-11-06	LT 12 WING B	PENGECEKAN PINTU KAMAR	-	-	-

10	No	Tanggal	Task	Point	Status	Description	Petugas
1	39	2024-11-06	LT 12 WING B	PENGECEKAN PINTU KAMAR	-	-	-
March   Marc	40	2024-11-06	LT 12 WING B	PENGECEKAN PINTU KAMAR	-	-	-
March   Marc	41	2024-11-06	LT 12 WING B	PENGECEKAN KORIDOR	-	-	-
1	42	2024-11-06	LT 12 WING B	PENGECEKAN KORIDOR	-	-	-
PRINCECKAM APAR	43	2024-11-06	LT 12 WING B	PENGECEKAN KORIDOR	-	-	-
PENGECEKAN AYAR	44	2024-11-06	LT 11 WING B	PENGECEKAN APAR	-	-	-
47         2024-11-08         LT I YWNO B         PENGECERAN HYDRANT         .         .         .           48         2024-11-08         LT I YWNO B         PENGECRAN HYDRANT         .	45	2024-11-06	LT 11 WING B	PENGECEKAN APAR	-	-	-
AB	46	2024-11-06	LT 11 WING B	PENGECEKAN APAR	-	-	-
PRINCECKAN HYDRANT	47	2024-11-06	LT 11 WING B	PENGECEKAN HYDRANT	-	-	-
PRINCECKAN EMBRGENCY ENT	48	2024-11-06	LT 11 WING B	PENGECEKAN HYDRANT	-	-	-
PENGECKAN EMERGENCY EXIT	49	2024-11-06	LT 11 WING B	PENGECEKAN HYDRANT	-	-	-
52         2024-11-08         LT11 WING B         PENGECKAN EMERGENCY EXIT         1         2         1           53         2024-11-08         LT11 WING B         PENGECKAN PINTU KAMAR         1         2         2           54         2024-11-08         LT11 WING B         PENGECKAN PINTU KAMAR         1         2         2           56         2024-11-08         LT11 WING B         PENGECKAN PINTU KAMAR         1         2         2           56         2024-11-08         LT11 WING B         PENGECKAN KORIDOR         1         2         2           57         2024-11-08         LT11 WING B         PENGECKAN KORIDOR         1         2         2         2           58         2024-11-08         LT11 WING A         PENGECKAN APAR         1         2         1         2           60         2024-11-08         LT11 WING A         PENGECKAN APAR         1         2         1         2           61         2024-11-08         LT11 WING A         PENGECKAN HYDRANT         1         2         1         2           62         2024-11-08         LT11 WING A         PENGECKAN HYDRANT         1         2         1         2           63         2024-11-08	50	2024-11-06	LT 11 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
53         2024-11-06         LT 11 WING B         PENGECEKAN PINTU KAMAR         -         -         -         -           54         2024-11-06         LT 11 WING B         PENGECEKAN PINTU KAMAR         -         -         -         -         -           55         2024-11-06         LT 11 WING B         PENGECEKAN KORIDOR         -	51	2024-11-06	LT 11 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
544         2024-11-08         LT 11 WING B         PENGECEKAN PINTU KAMAR         . <td>52</td> <td>2024-11-06</td> <td>LT 11 WING B</td> <td>PENGECEKAN EMERGENCY EXIT</td> <td>-</td> <td>-</td> <td>-</td>	52	2024-11-06	LT 11 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
PENGECEKAN PINTU KAMAR	53	2024-11-06	LT 11 WING B	PENGECEKAN PINTU KAMAR	-	-	-
96         2024-11-06         LT 11 WING B         PENGECEKAN KORIDOR         -         -         -           57         2024-11-06         LT 11 WING B         PENGECEKAN KORIDOR         -         -         -         -           58         2024-11-06         LT 11 WING B         PENGECEKAN KORIDOR         -         -         -         -           59         2024-11-06         LT 11 WING A         PENGECEKAN APAR         -         -         -         -           60         2024-11-06         LT 11 WING A         PENGECEKAN APAR         -         -         -         -           61         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT         -         -         -         -           63         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT         -         -         -         -           64         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT         -         -         -         -           65         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT         -         -         -         -           67         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT         -         -	54	2024-11-06	LT 11 WING B	PENGECEKAN PINTU KAMAR	-	-	-
57         2024-11-06         LT 11 WING B         PENGECEKAN KORIDOR         -         -         -         -           58         2024-11-06         LT 11 WING B         PENGECEKAN KORIDOR         -         -         -         -         -           59         2024-11-06         LT 11 WING A         PENGECEKAN APAR         -         -         -         -         -           60         2024-11-06         LT 11 WING A         PENGECEKAN APAR         -         -         -         -         -         -           61         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT         -	55	2024-11-06	LT 11 WING B	PENGECEKAN PINTU KAMAR	-	-	-
68         2024-11-06         LT 11 WING A         PENGECEKAN KORIDOR         .	56	2024-11-06	LT 11 WING B	PENGECEKAN KORIDOR	-	-	-
59         2024-11-06         LT 11 WING A         PENGECEKAN APAR         -         -         -           60         2024-11-06         LT 11 WING A         PENGECEKAN APAR         -         -         -         -           61         2024-11-06         LT 11 WING A         PENGECEKAN APAR         -         -         -         -           62         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT         -         -         -         -           63         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT         -         -         -         -         -           64         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT         - <td< td=""><td>57</td><td>2024-11-06</td><td>LT 11 WING B</td><td>PENGECEKAN KORIDOR</td><td>-</td><td>-</td><td>-</td></td<>	57	2024-11-06	LT 11 WING B	PENGECEKAN KORIDOR	-	-	-
2024-11-06   LT 11 WING A   PENGECEKAN APAR   -   -   -   -   -   -   -   -   -	58	2024-11-06	LT 11 WING B	PENGECEKAN KORIDOR	-	-	-
61         2024-11-06         LT 11 WING A         PENGECEKAN APAR         .	59	2024-11-06	LT 11 WING A	PENGECEKAN APAR	-	-	-
62         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT         -         -         -         -           63         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT         -         -         -         -         -           64         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT         -	60	2024-11-06	LT 11 WING A	PENGECEKAN APAR	-	-	-
63         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT         -	61	2024-11-06	LT 11 WING A	PENGECEKAN APAR	-	-	-
64         2024-11-06         LT 11 WING A         PENGECEKAN HYDRANT         -	62	2024-11-06	LT 11 WING A	PENGECEKAN HYDRANT	-	-	-
65         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT         -<	63	2024-11-06	LT 11 WING A	PENGECEKAN HYDRANT	-	-	-
66         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT         -<	64	2024-11-06	LT 11 WING A	PENGECEKAN HYDRANT	-	-	-
67         2024-11-06         LT 11 WING A         PENGECEKAN EMERGENCY EXIT         -<	65	2024-11-06	LT 11 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
68       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR       -       -       -       -         69       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR       -       -       -       -         70       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR       -       -       -       -         71       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR       -       -       -       -         72       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR       -       -       -       -         73       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR       -       -       -       -         74       2024-11-06       LT 10 WING A       PENGECEKAN APAR       -       -       -       -         75       2024-11-06       LT 10 WING A       PENGECEKAN APAR       -       -       -       -	66	2024-11-06	LT 11 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
69       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR       -       -       -       -         70       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR       -       -       -       -         71       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR       -       -       -       -         72       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR       -       -       -       -         73       2024-11-06       LT 10 WING A       PENGECEKAN KORIDOR       -       -       -       -         74       2024-11-06       LT 10 WING A       PENGECEKAN APAR       -       -       -       -         75       2024-11-06       LT 10 WING A       PENGECEKAN APAR       -       -       -       -	67	2024-11-06	LT 11 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
70       2024-11-06       LT 11 WING A       PENGECEKAN PINTU KAMAR       -       -       -       -         71       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR       -       -       -       -         72       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR       -       -       -       -         73       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR       -       -       -       -         74       2024-11-06       LT 10 WING A       PENGECEKAN APAR       -       -       -       -         75       2024-11-06       LT 10 WING A       PENGECEKAN APAR       -       -       -       -	68	2024-11-06	LT 11 WING A	PENGECEKAN PINTU KAMAR	-	-	-
71       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR       -       -       -       -         72       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR       -       -       -       -         73       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR       -       -       -       -         74       2024-11-06       LT 10 WING A       PENGECEKAN APAR       -       -       -       -         75       2024-11-06       LT 10 WING A       PENGECEKAN APAR       -       -       -       -	69	2024-11-06	LT 11 WING A	PENGECEKAN PINTU KAMAR	-	-	-
72       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR       -       -       -       -         73       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR       -       -       -       -         74       2024-11-06       LT 10 WING A       PENGECEKAN APAR       -       -       -       -         75       2024-11-06       LT 10 WING A       PENGECEKAN APAR       -       -       -       -	70	2024-11-06	LT 11 WING A	PENGECEKAN PINTU KAMAR	-	-	-
73       2024-11-06       LT 11 WING A       PENGECEKAN KORIDOR       -       -       -       -         74       2024-11-06       LT 10 WING A       PENGECEKAN APAR       -       -       -       -         75       2024-11-06       LT 10 WING A       PENGECEKAN APAR       -       -       -       -	71	2024-11-06	LT 11 WING A	PENGECEKAN KORIDOR	-	-	-
74         2024-11-06         LT 10 WING A         PENGECEKAN APAR         -	72	2024-11-06	LT 11 WING A	PENGECEKAN KORIDOR	-	-	-
75 2024-11-06 LT 10 WING A PENGECEKAN APAR	73	2024-11-06	LT 11 WING A	PENGECEKAN KORIDOR	-	-	-
	74	2024-11-06	LT 10 WING A	PENGECEKAN APAR	-	-	-
	75	2024-11-06	LT 10 WING A	PENGECEKAN APAR	-	-	-
76 2024-11-06 LT 10 WING A PENGECEKAN APAR	76	2024-11-06	LT 10 WING A	PENGECEKAN APAR	-	-	-
77 2024-11-06 LT 10 WING A PENGECEKAN HYDRANT	77	2024-11-06	LT 10 WING A	PENGECEKAN HYDRANT	-	-	-

78         2024-11-06         LT 10 WING A         PENGECEKAN HYDRANT           79         2024-11-06         LT 10 WING A         PENGECEKAN HYDRANT           80         2024-11-06         LT 10 WING A         PENGECEKAN EMERGENG           81         2024-11-06         LT 10 WING A         PENGECEKAN EMERGENG           82         2024-11-06         LT 10 WING A         PENGECEKAN EMERGENG           83         2024-11-06         LT 10 WING A         PENGECEKAN PINTU KAM           84         2024-11-06         LT 10 WING A         PENGECEKAN PINTU KAM           85         2024-11-06         LT 10 WING A         PENGECEKAN KORIDOR           86         2024-11-06         LT 10 WING A         PENGECEKAN KORIDOR           87         2024-11-06         LT 10 WING A         PENGECEKAN KORIDOR           89         2024-11-06         LT 10 WING B         PENGECEKAN APAR           90         2024-11-06         LT 10 WING B         PENGECEKAN APAR           91         2024-11-06         LT 10 WING B         PENGECEKAN HYDRANT           93         2024-11-06         LT 10 WING B         PENGECEKAN HYDRANT	CY EXIT -  CY EXIT -  IAR -  IAR -		
80         2024-11-06         LT 10 WING A         PENGECEKAN EMERGENCE           81         2024-11-06         LT 10 WING A         PENGECEKAN EMERGENCE           82         2024-11-06         LT 10 WING A         PENGECEKAN EMERGENCE           83         2024-11-06         LT 10 WING A         PENGECEKAN PINTU KAM           84         2024-11-06         LT 10 WING A         PENGECEKAN PINTU KAM           85         2024-11-06         LT 10 WING A         PENGECEKAN KORIDOR           87         2024-11-06         LT 10 WING A         PENGECEKAN KORIDOR           88         2024-11-06         LT 10 WING A         PENGECEKAN KORIDOR           89         2024-11-06         LT 10 WING B         PENGECEKAN APAR           90         2024-11-06         LT 10 WING B         PENGECEKAN APAR           91         2024-11-06         LT 10 WING B         PENGECEKAN HYDRANT	CY EXIT - CY EXIT - CY EXIT - IAR -		
81       2024-11-06       LT 10 WING A       PENGECEKAN EMERGENCE         82       2024-11-06       LT 10 WING A       PENGECEKAN EMERGENCE         83       2024-11-06       LT 10 WING A       PENGECEKAN PINTU KAM         84       2024-11-06       LT 10 WING A       PENGECEKAN PINTU KAM         85       2024-11-06       LT 10 WING A       PENGECEKAN KORIDOR         87       2024-11-06       LT 10 WING A       PENGECEKAN KORIDOR         88       2024-11-06       LT 10 WING A       PENGECEKAN KORIDOR         89       2024-11-06       LT 10 WING B       PENGECEKAN APAR         90       2024-11-06       LT 10 WING B       PENGECEKAN APAR         91       2024-11-06       LT 10 WING B       PENGECEKAN APAR         92       2024-11-06       LT 10 WING B       PENGECEKAN HYDRANT	CY EXIT -  CY EXIT -  IAR -  IAR -  IAR -  I -  IAR		
82       2024-11-06       LT 10 WING A       PENGECEKAN EMERGENO         83       2024-11-06       LT 10 WING A       PENGECEKAN PINTU KAM         84       2024-11-06       LT 10 WING A       PENGECEKAN PINTU KAM         85       2024-11-06       LT 10 WING A       PENGECEKAN KORIDOR         87       2024-11-06       LT 10 WING A       PENGECEKAN KORIDOR         88       2024-11-06       LT 10 WING A       PENGECEKAN KORIDOR         89       2024-11-06       LT 10 WING B       PENGECEKAN APAR         90       2024-11-06       LT 10 WING B       PENGECEKAN APAR         91       2024-11-06       LT 10 WING B       PENGECEKAN APAR         92       2024-11-06       LT 10 WING B       PENGECEKAN HYDRANT	CY EXIT -  JAR -  JAR -  JAR -  -  JAR -  -  -  -  -  -  -  -  -  -  -  -  -		
83       2024-11-06       LT 10 WING A       PENGECEKAN PINTU KAM         84       2024-11-06       LT 10 WING A       PENGECEKAN PINTU KAM         85       2024-11-06       LT 10 WING A       PENGECEKAN PINTU KAM         86       2024-11-06       LT 10 WING A       PENGECEKAN KORIDOR         87       2024-11-06       LT 10 WING A       PENGECEKAN KORIDOR         88       2024-11-06       LT 10 WING B       PENGECEKAN APAR         90       2024-11-06       LT 10 WING B       PENGECEKAN APAR         91       2024-11-06       LT 10 WING B       PENGECEKAN APAR         92       2024-11-06       LT 10 WING B       PENGECEKAN HYDRANT	IAR -		
84       2024-11-06       LT 10 WING A       PENGECEKAN PINTU KAM         85       2024-11-06       LT 10 WING A       PENGECEKAN PINTU KAM         86       2024-11-06       LT 10 WING A       PENGECEKAN KORIDOR         87       2024-11-06       LT 10 WING A       PENGECEKAN KORIDOR         88       2024-11-06       LT 10 WING B       PENGECEKAN APAR         90       2024-11-06       LT 10 WING B       PENGECEKAN APAR         91       2024-11-06       LT 10 WING B       PENGECEKAN APAR         92       2024-11-06       LT 10 WING B       PENGECEKAN HYDRANT	IAR - IAR		- - -
85       2024-11-06       LT 10 WING A       PENGECEKAN PINTU KAM         86       2024-11-06       LT 10 WING A       PENGECEKAN KORIDOR         87       2024-11-06       LT 10 WING A       PENGECEKAN KORIDOR         88       2024-11-06       LT 10 WING B       PENGECEKAN KORIDOR         89       2024-11-06       LT 10 WING B       PENGECEKAN APAR         90       2024-11-06       LT 10 WING B       PENGECEKAN APAR         91       2024-11-06       LT 10 WING B       PENGECEKAN APAR         92       2024-11-06       LT 10 WING B       PENGECEKAN HYDRANT		- - - -	
86       2024-11-06       LT 10 WING A       PENGECEKAN KORIDOR         87       2024-11-06       LT 10 WING A       PENGECEKAN KORIDOR         88       2024-11-06       LT 10 WING B       PENGECEKAN KORIDOR         89       2024-11-06       LT 10 WING B       PENGECEKAN APAR         90       2024-11-06       LT 10 WING B       PENGECEKAN APAR         91       2024-11-06       LT 10 WING B       PENGECEKAN APAR         92       2024-11-06       LT 10 WING B       PENGECEKAN HYDRANT		- - - -	
87       2024-11-06       LT 10 WING A       PENGECEKAN KORIDOR         88       2024-11-06       LT 10 WING A       PENGECEKAN KORIDOR         89       2024-11-06       LT 10 WING B       PENGECEKAN APAR         90       2024-11-06       LT 10 WING B       PENGECEKAN APAR         91       2024-11-06       LT 10 WING B       PENGECEKAN APAR         92       2024-11-06       LT 10 WING B       PENGECEKAN HYDRANT	- - - -	- - -	- - -
88       2024-11-06       LT 10 WING A       PENGECEKAN KORIDOR         89       2024-11-06       LT 10 WING B       PENGECEKAN APAR         90       2024-11-06       LT 10 WING B       PENGECEKAN APAR         91       2024-11-06       LT 10 WING B       PENGECEKAN APAR         92       2024-11-06       LT 10 WING B       PENGECEKAN HYDRANT		- -	-
89       2024-11-06       LT 10 WING B       PENGECEKAN APAR         90       2024-11-06       LT 10 WING B       PENGECEKAN APAR         91       2024-11-06       LT 10 WING B       PENGECEKAN APAR         92       2024-11-06       LT 10 WING B       PENGECEKAN HYDRANT	-	-	-
90       2024-11-06       LT 10 WING B       PENGECEKAN APAR         91       2024-11-06       LT 10 WING B       PENGECEKAN APAR         92       2024-11-06       LT 10 WING B       PENGECEKAN HYDRANT	-	-	
91         2024-11-06         LT 10 WING B         PENGECEKAN APAR           92         2024-11-06         LT 10 WING B         PENGECEKAN HYDRANT			-
92 2024-11-06 LT 10 WING B PENGECEKAN HYDRANT		-	-
		-	
93 2024-11-06 LT 10 WING B PENGECEKAN HYDRANT	-	-	
	-	-	-
94 2024-11-06 LT 10 WING B PENGECEKAN HYDRANT	-	-	-
95 2024-11-06 LT 10 WING B PENGECEKAN EMERGENCE	CY EXIT -	-	-
96 2024-11-06 LT 10 WING B PENGECEKAN EMERGENC	CY EXIT -	-	-
97 2024-11-06 LT 10 WING B PENGECEKAN EMERGENCE	CY EXIT -	-	-
98 2024-11-06 LT 10 WING B PENGECEKAN PINTU KAM	IAR -	-	-
99 2024-11-06 LT 10 WING B PENGECEKAN PINTU KAM	IAR -	-	-
100 2024-11-06 LT 10 WING B PENGECEKAN PINTU KAM	IAR -	-	-
101 2024-11-06 LT 10 WING B PENGECEKAN KORIDOR	-	-	-
102 2024-11-06 LT 10 WING B PENGECEKAN KORIDOR	-	-	-
103 2024-11-06 LT 10 WING B PENGECEKAN KORIDOR	-	-	-
104 2024-11-06 LT 09 WING B PENGECEKAN APAR	-	-	-
105 2024-11-06 LT 09 WING B PENGECEKAN APAR	-	-	
106 2024-11-06 LT 09 WING B PENGECEKAN APAR	-	-	-
107 2024-11-06 LT 09 WING B PENGECEKAN HYDRANT	-	-	
108 2024-11-06 LT 09 WING B PENGECEKAN HYDRANT	-	-	
109 2024-11-06 LT 09 WING B PENGECEKAN HYDRANT	-	-	
110 2024-11-06 LT 09 WING B PENGECEKAN EMERGENC	CY EXIT -	-	
111 2024-11-06 LT 09 WING B PENGECEKAN EMERGENC	CY EXIT -	-	-
112 2024-11-06 LT 09 WING B PENGECEKAN EMERGENC	CY EXIT -	-	-
113 2024-11-06 LT 09 WING B PENGECEKAN PINTU KAM	IAR -	-	-
114 2024-11-06 LT 09 WING B PENGECEKAN PINTU KAM	IAR -	-	
115 2024-11-06 LT 09 WING B PENGECEKAN PINTU KAM	IAR -	-	
116 2024-11-06 LT 09 WING B PENGECEKAN KORIDOR	-	-	-

	Tanggal	Task	Point	Status	Description	Petugas
117	2024-11-06	LT 09 WING B	PENGECEKAN KORIDOR	-	-	-
118	2024-11-06	LT 09 WING B	PENGECEKAN KORIDOR	-	-	-
119	2024-11-06	LT 09 WING A	PENGECEKAN APAR	-	-	-
120	2024-11-06	LT 09 WING A	PENGECEKAN APAR	-	-	-
121	2024-11-06	LT 09 WING A	PENGECEKAN APAR	-	-	-
122	2024-11-06	LT 09 WING A	PENGECEKAN HYDRANT	-	-	-
123	2024-11-06	LT 09 WING A	PENGECEKAN HYDRANT	-	-	-
124	2024-11-06	LT 09 WING A	PENGECEKAN HYDRANT	-	-	-
125	2024-11-06	LT 09 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
126	2024-11-06	LT 09 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
127	2024-11-06	LT 09 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
128	2024-11-06	LT 09 WING A	PENGECEKAN PINTU KAMAR	-	-	-
129	2024-11-06	LT 09 WING A	PENGECEKAN PINTU KAMAR	-	-	-
130	2024-11-06	LT 09 WING A	PENGECEKAN PINTU KAMAR	-	-	-
131	2024-11-06	LT 09 WING A	PENGECEKAN KORIDOR	-	-	-
132	2024-11-06	LT 09 WING A	PENGECEKAN KORIDOR	-	-	-
133	2024-11-06	LT 09 WING A	PENGECEKAN KORIDOR	-	-	-
134	2024-11-06	LT 08 WING A	PENGECEKAN APAR	-	-	-
135	2024-11-06	LT 08 WING A	PENGECEKAN APAR	-	-	-
136	2024-11-06	LT 08 WING A	PENGECEKAN APAR	-	-	-
137	2024-11-06	LT 08 WING A	PENGECEKAN HYDRANT	-	-	-
138	2024-11-06	LT 08 WING A	PENGECEKAN HYDRANT	-	-	-
139	2024-11-06	LT 08 WING A	PENGECEKAN HYDRANT	-	-	-
140	2024-11-06	LT 08 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
141	2024-11-06	LT 08 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
142	2024-11-06	LT 08 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
143	2024-11-06	LT 08 WING A	PENGECEKAN PINTU KAMAR	-	-	-
144	2024-11-06	LT 08 WING A	PENGECEKAN PINTU KAMAR	-	-	-
145	2024-11-06	LT 08 WING A	PENGECEKAN PINTU KAMAR	-	-	-
146	2024-11-06	LT 08 WING A	PENGECEKAN KORIDOR	-	-	-
147	2024-11-06	LT 08 WING A	PENGECEKAN KORIDOR	-	-	-
148	2024-11-06	LT 08 WING A	PENGECEKAN KORIDOR	-	-	-
149	2024-11-06	LT 08 WING B	PENGECEKAN APAR	-	-	-
150	2024-11-06	LT 08 WING B	PENGECEKAN APAR	-	-	-
151	2024-11-06	LT 08 WING B	PENGECEKAN APAR	-	-	-
152	2024-11-06	LT 08 WING B	PENGECEKAN HYDRANT	-	-	-
153	2024-11-06	LT 08 WING B	PENGECEKAN HYDRANT	-	-	-
154	2024-11-06	LT 08 WING B	PENGECEKAN HYDRANT	-	-	-
155	2024-11-06	LT 08 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-

No	Tanggal	Task	Point	Status	Description	Petugas
156	2024-11-06	LT 08 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
157	2024-11-06	LT 08 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
158	2024-11-06	LT 08 WING B	PENGECEKAN PINTU KAMAR	-	-	-
159	2024-11-06	LT 08 WING B	PENGECEKAN PINTU KAMAR	-	-	-
160	2024-11-06	LT 08 WING B	PENGECEKAN PINTU KAMAR	-	-	-
161	2024-11-06	LT 08 WING B	PENGECEKAN KORIDOR	-	-	-
162	2024-11-06	LT 08 WING B	PENGECEKAN KORIDOR	-	-	-
163	2024-11-06	LT 08 WING B	PENGECEKAN KORIDOR	-	-	-
164	2024-11-06	LT 07 WING B	PENGECEKAN APAR	-	-	-
165	2024-11-06	LT 07 WING B	PENGECEKAN APAR	-	-	-
166	2024-11-06	LT 07 WING B	PENGECEKAN APAR	-	-	-
167	2024-11-06	LT 07 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
168	2024-11-06	LT 07 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
169	2024-11-06	LT 07 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
170	2024-11-06	LT 07 WING B	PENGECEKAN HYDRANT	-	-	-
171	2024-11-06	LT 07 WING B	PENGECEKAN HYDRANT	-	-	-
172	2024-11-06	LT 07 WING B	PENGECEKAN HYDRANT	-	-	-
173	2024-11-06	LT 07 WING B	PENGECEKAN PINTU KAMAR	-	-	-
174	2024-11-06	LT 07 WING B	PENGECEKAN PINTU KAMAR	-	-	-
175	2024-11-06	LT 07 WING B	PENGECEKAN PINTU KAMAR	-	-	-
176	2024-11-06	LT 07 WING B	PENGECEKAN KORIDOR	-	-	-
177	2024-11-06	LT 07 WING B	PENGECEKAN KORIDOR	-	-	-
178	2024-11-06	LT 07 WING B	PENGECEKAN KORIDOR	-	-	-
179	2024-11-06	LT 07 WING A	PENGECEKAN APAR	-	-	-
180	2024-11-06	LT 07 WING A	PENGECEKAN APAR	-	-	-
181	2024-11-06	LT 07 WING A	PENGECEKAN APAR	-	-	-
182	2024-11-06	LT 07 WING A	PENGECEKAN HYDRANT	-	-	-
183	2024-11-06	LT 07 WING A	PENGECEKAN HYDRANT	-	-	-
184	2024-11-06	LT 07 WING A	PENGECEKAN HYDRANT	-	-	-
185	2024-11-06	LT 07 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
186	2024-11-06	LT 07 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
187	2024-11-06	LT 07 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
188	2024-11-06	LT 07 WING A	PENGECEKAN PINTU KAMAR	-	-	-
189	2024-11-06	LT 07 WING A	PENGECEKAN PINTU KAMAR	-	-	-
190	2024-11-06	LT 07 WING A	PENGECEKAN PINTU KAMAR	-	-	-
191	2024-11-06	LT 07 WING A	PENGECEKAN KORIDOR	-	-	-
192	2024-11-06	LT 07 WING A	PENGECEKAN KORIDOR	-	-	-
193	2024-11-06	LT 07 WING A	PENGECEKAN KORIDOR	-	-	-
194	2024-11-06	LT 06 WING A	PENGECEKAN APAR	-	-	-
194	2024-11-06	LT 06 WING A	PENGECEKAN APAR	-	-	-

196	on Petugas
197   2024-11-06	-
1996	-
PENGLECKAN HYDRANT	-
2004   2024-11-06	-
2011   2024-11-06	-
202         2024-11-06         LT 06 WING A         PENGECEKAN EMERGENCY EXIT         -         -           203         2024-11-06         LT 06 WING A         PENGECEKAN PINTU KAMAR         -         -           204         2024-11-06         LT 06 WING A         PENGECEKAN PINTU KAMAR         -         -           205         2024-11-06         LT 06 WING A         PENGECEKAN PINTU KAMAR         -         -           206         2024-11-06         LT 06 WING A         PENGECEKAN KORIDOR         -         -           207         2024-11-06         LT 06 WING A         PENGECEKAN KORIDOR         -         -           208         2024-11-06         LT 06 WING B         PENGECEKAN APAR         -         -           210         2024-11-06         LT 06 WING B         PENGECEKAN APAR         -         -           211         2024-11-06         LT 06 WING B         PENGECEKAN HYDRANT         -         -           212         2024-11-06         LT 06 WING B         PENGECEKAN HYDRANT         -         -           213         2024-11-06         LT 06 WING B         PENGECEKAN HYDRANT         -         -           214         2024-11-06         LT 06 WING B         PENGECEKAN HERGENCY EXIT         <	-
203   2024-11-06	-
2014   2024-11-06	-
205         2024-11-06         LT 06 WING A         PENGECEKAN PINTU KAMAR         -         -           206         2024-11-06         LT 06 WING A         PENGECEKAN KORIDOR         -         -           207         2024-11-06         LT 06 WING A         PENGECEKAN KORIDOR         -         -           208         2024-11-06         LT 06 WING A         PENGECEKAN KORIDOR         -         -           209         2024-11-06         LT 06 WING B         PENGECEKAN APAR         -         -           210         2024-11-06         LT 06 WING B         PENGECEKAN APAR         -         -           211         2024-11-06         LT 06 WING B         PENGECEKAN APAR         -         -           212         2024-11-06         LT 06 WING B         PENGECEKAN HYDRANT         -         -           213         2024-11-06         LT 06 WING B         PENGECEKAN HYDRANT         -         -           214         2024-11-06         LT 06 WING B         PENGECEKAN HYDRANT         -         -           215         2024-11-06         LT 06 WING B         PENGECEKAN HERGENCY EXIT         -         -           216         2024-11-06         LT 06 WING B         PENGECEKAN EMERGENCY EXIT         -	-
206   2024-11-06	-
207   2024-11-06	-
208         2024-11-06         LT 06 WING A         PENGECEKAN KORIDOR         -         -           209         2024-11-06         LT 06 WING B         PENGECEKAN APAR         -         -           210         2024-11-06         LT 06 WING B         PENGECEKAN APAR         -         -           211         2024-11-06         LT 06 WING B         PENGECEKAN HYDRANT         -         -           212         2024-11-06         LT 06 WING B         PENGECEKAN HYDRANT         -         -           214         2024-11-06         LT 06 WING B         PENGECEKAN HYDRANT         -         -           215         2024-11-06         LT 06 WING B         PENGECEKAN EMERGENCY EXIT         -         -           216         2024-11-06         LT 06 WING B         PENGECEKAN EMERGENCY EXIT         -         -           217         2024-11-06         LT 06 WING B         PENGECEKAN EMERGENCY EXIT         -         -           218         2024-11-06         LT 06 WING B         PENGECEKAN EMERGENCY EXIT         -         -           219         2024-11-06         LT 06 WING B         PENGECEKAN PINTU KAMAR         -         -           220         2024-11-06         LT 06 WING B         PENGECEKAN KORIDOR	-
209   2024-11-06	-
2024-11-06	-
211       2024-11-06       LT 06 WING B       PENGECEKAN APAR       -       -         212       2024-11-06       LT 06 WING B       PENGECEKAN HYDRANT       -       -         213       2024-11-06       LT 06 WING B       PENGECEKAN HYDRANT       -       -         214       2024-11-06       LT 06 WING B       PENGECEKAN HYDRANT       -       -         215       2024-11-06       LT 06 WING B       PENGECEKAN EMERGENCY EXIT       -       -         216       2024-11-06       LT 06 WING B       PENGECEKAN EMERGENCY EXIT       -       -         217       2024-11-06       LT 06 WING B       PENGECEKAN EMERGENCY EXIT       -       -         218       2024-11-06       LT 06 WING B       PENGECEKAN PINTU KAMAR       -       -         219       2024-11-06       LT 06 WING B       PENGECEKAN PINTU KAMAR       -       -         220       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         221       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         223       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         224       2024-11-06       LT 06 WING B	-
212       2024-11-06       LT 06 WING B       PENGECEKAN HYDRANT       -       -         213       2024-11-06       LT 06 WING B       PENGECEKAN HYDRANT       -       -         214       2024-11-06       LT 06 WING B       PENGECEKAN HYDRANT       -       -         215       2024-11-06       LT 06 WING B       PENGECEKAN EMERGENCY EXIT       -       -         216       2024-11-06       LT 06 WING B       PENGECEKAN EMERGENCY EXIT       -       -         217       2024-11-06       LT 06 WING B       PENGECEKAN PINTU KAMAR       -       -         218       2024-11-06       LT 06 WING B       PENGECEKAN PINTU KAMAR       -       -         219       2024-11-06       LT 06 WING B       PENGECEKAN PINTU KAMAR       -       -         220       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         221       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         222       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         223       2024-11-06       LT 06 WING B       PENGECEKAN APAR       -       -	-
213       2024-11-06       LT 06 WING B       PENGECEKAN HYDRANT       -       -         214       2024-11-06       LT 06 WING B       PENGECEKAN HYDRANT       -       -         215       2024-11-06       LT 06 WING B       PENGECEKAN EMERGENCY EXIT       -       -         216       2024-11-06       LT 06 WING B       PENGECEKAN EMERGENCY EXIT       -       -         217       2024-11-06       LT 06 WING B       PENGECEKAN PINTU KAMAR       -       -         218       2024-11-06       LT 06 WING B       PENGECEKAN PINTU KAMAR       -       -         219       2024-11-06       LT 06 WING B       PENGECEKAN PINTU KAMAR       -       -         220       2024-11-06       LT 06 WING B       PENGECEKAN PINTU KAMAR       -       -         221       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         222       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         223       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         224       2024-11-06       LT 06 WING B       PENGECEKAN APAR       -       -	-
214       2024-11-06       LT 06 WING B       PENGECEKAN HYDRANT       -       -         215       2024-11-06       LT 06 WING B       PENGECEKAN EMERGENCY EXIT       -       -         216       2024-11-06       LT 06 WING B       PENGECEKAN EMERGENCY EXIT       -       -         217       2024-11-06       LT 06 WING B       PENGECEKAN PINTU KAMAR       -       -         218       2024-11-06       LT 06 WING B       PENGECEKAN PINTU KAMAR       -       -         219       2024-11-06       LT 06 WING B       PENGECEKAN PINTU KAMAR       -       -         220       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         221       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         222       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         223       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         224       2024-11-06       LT 06 WING B       PENGECEKAN APAR       -       -	-
215         2024-11-06         LT 06 WING B         PENGECEKAN EMERGENCY EXIT         -         -           216         2024-11-06         LT 06 WING B         PENGECEKAN EMERGENCY EXIT         -         -           217         2024-11-06         LT 06 WING B         PENGECEKAN EMERGENCY EXIT         -         -           218         2024-11-06         LT 06 WING B         PENGECEKAN PINTU KAMAR         -         -           219         2024-11-06         LT 06 WING B         PENGECEKAN PINTU KAMAR         -         -           220         2024-11-06         LT 06 WING B         PENGECEKAN KORIDOR         -         -           221         2024-11-06         LT 06 WING B         PENGECEKAN KORIDOR         -         -           222         2024-11-06         LT 06 WING B         PENGECEKAN KORIDOR         -         -           223         2024-11-06         LT 06 WING B         PENGECEKAN KORIDOR         -         -           224         2024-11-06         LT 05 WING B         PENGECEKAN APAR         -         -	-
216       2024-11-06       LT 06 WING B       PENGECEKAN EMERGENCY EXIT       -       -         217       2024-11-06       LT 06 WING B       PENGECEKAN EMERGENCY EXIT       -       -         218       2024-11-06       LT 06 WING B       PENGECEKAN PINTU KAMAR       -       -         219       2024-11-06       LT 06 WING B       PENGECEKAN PINTU KAMAR       -       -         220       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         221       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         222       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         223       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         224       2024-11-06       LT 06 WING B       PENGECEKAN APAR       -       -	-
217       2024-11-06       LT 06 WING B       PENGECEKAN EMERGENCY EXIT       -       -         218       2024-11-06       LT 06 WING B       PENGECEKAN PINTU KAMAR       -       -         219       2024-11-06       LT 06 WING B       PENGECEKAN PINTU KAMAR       -       -         220       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         221       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         222       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         223       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         224       2024-11-06       LT 06 WING B       PENGECEKAN APAR       -       -	-
218       2024-11-06       LT 06 WING B       PENGECEKAN PINTU KAMAR       -       -         219       2024-11-06       LT 06 WING B       PENGECEKAN PINTU KAMAR       -       -         220       2024-11-06       LT 06 WING B       PENGECEKAN PINTU KAMAR       -       -         221       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         222       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         223       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         224       2024-11-06       LT 05 WING B       PENGECEKAN APAR       -       -	-
219       2024-11-06       LT 06 WING B       PENGECEKAN PINTU KAMAR       -       -         220       2024-11-06       LT 06 WING B       PENGECEKAN PINTU KAMAR       -       -         221       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         222       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         223       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         224       2024-11-06       LT 05 WING B       PENGECEKAN APAR       -       -	-
220       2024-11-06       LT 06 WING B       PENGECEKAN PINTU KAMAR       -       -         221       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         222       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         223       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         224       2024-11-06       LT 05 WING B       PENGECEKAN APAR       -       -	-
221       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         222       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         223       2024-11-06       LT 06 WING B       PENGECEKAN KORIDOR       -       -         224       2024-11-06       LT 05 WING B       PENGECEKAN APAR       -       -	-
222         2024-11-06         LT 06 WING B         PENGECEKAN KORIDOR         -         -         -           223         2024-11-06         LT 06 WING B         PENGECEKAN KORIDOR         -         -         -           224         2024-11-06         LT 05 WING B         PENGECEKAN APAR         -         -         -	-
223         2024-11-06         LT 06 WING B         PENGECEKAN KORIDOR         -         -         -           224         2024-11-06         LT 05 WING B         PENGECEKAN APAR         -         -         -	-
224 2024-11-06 LT 05 WING B PENGECEKAN APAR	-
	-
225 2024-11-06 LT 05 WING B PENGECEKAN APAR	-
	-
226         2024-11-06         LT 05 WING B         PENGECEKAN APAR         -         -         -	-
227         2024-11-06         LT 05 WING B         PENGECEKAN HYDRANT         -         -         -	-
228         2024-11-06         LT 05 WING B         PENGECEKAN HYDRANT         -         -         -	-
229         2024-11-06         LT 05 WING B         PENGECEKAN HYDRANT         -         -         -	-
230 2024-11-06 LT 05 WING B PENGECEKAN EMERGENCY EXIT	-
231 2024-11-06 LT 05 WING B PENGECEKAN EMERGENCY EXIT	-
232 2024-11-06 LT 05 WING B PENGECEKAN EMERGENCY EXIT	-
233 2024-11-06 LT 05 WING B PENGECEKAN PINTU KAMAR	-

235 2 236 2 237 2	2024-11-06 2024-11-06 2024-11-06 2024-11-06	LT 05 WING B  LT 05 WING B  LT 05 WING B	PENGECEKAN PINTU KAMAR PENGECEKAN PINTU KAMAR	-	-	-
236 2	2024-11-06 2024-11-06		PENGECEKAN PINTU KAMAR			
237 2	2024-11-06	LT 05 WING B		-	-	-
			PENGECEKAN KORIDOR	-	-	-
238 2		LT 05 WING B	PENGECEKAN KORIDOR	-	-	-
	2024-11-06	LT 05 WING B	PENGECEKAN KORIDOR	-	-	-
239 2	2024-11-06	LT 05 WING A	PENGECEKAN APAR	-	-	-
240 2	2024-11-06	LT 05 WING A	PENGECEKAN APAR	-	-	-
241 2	2024-11-06	LT 05 WING A	PENGECEKAN APAR	-	-	-
242 2	2024-11-06	LT 05 WING A	PENGECEKAN HYDRANT	-	-	-
243 2	2024-11-06	LT 05 WING A	PENGECEKAN HYDRANT	-	-	-
244 2	2024-11-06	LT 05 WING A	PENGECEKAN HYDRANT	-	-	-
245 2	2024-11-06	LT 05 WING A	PENGECEKAN EMERGENCY EXIT	-		-
246 2	2024-11-06	LT 05 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
247 2	2024-11-06	LT 05 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
248 2	2024-11-06	LT 05 WING A	PENGECEKAN PINTU KAMAR	-	-	-
249 2	2024-11-06	LT 05 WING A	PENGECEKAN PINTU KAMAR	-	-	-
250 2	2024-11-06	LT 05 WING A	PENGECEKAN PINTU KAMAR	-	-	-
251 2	2024-11-06	LT 05 WING A	PENGECEKAN KORIDOR	-	-	-
252 2	2024-11-06	LT 05 WING A	PENGECEKAN KORIDOR	-	-	-
253 2	2024-11-06	LT 05 WING A	PENGECEKAN KORIDOR	-	-	-
254 2	2024-11-06	LT 03 WING A	PENGECEKAN APAR	-	-	-
255 2	2024-11-06	LT 03 WING A	PENGECEKAN APAR	-	-	-
256 2	2024-11-06	LT 03 WING A	PENGECEKAN APAR	-	-	-
257 2	2024-11-06	LT 03 WING A	PENGECEKAN HYDRANT	-	-	-
258 2	2024-11-06	LT 03 WING A	PENGECEKAN HYDRANT	-	-	-
259 2	2024-11-06	LT 03 WING A	PENGECEKAN HYDRANT	-	-	-
260 2	2024-11-06	LT 03 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
261 2	2024-11-06	LT 03 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
262 2	2024-11-06	LT 03 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
263 2	2024-11-06	LT 03 WING A	PENGECEKAN PINTU KAMAR	-	-	-
264 2	2024-11-06	LT 03 WING A	PENGECEKAN PINTU KAMAR	-	-	-
265 2	2024-11-06	LT 03 WING A	PENGECEKAN PINTU KAMAR	-	-	
266 2	2024-11-06	LT 03 WING A	PENGECEKAN KORIDOR	-	-	-
267 2	2024-11-06	LT 03 WING A	PENGECEKAN KORIDOR	-	-	-
268 2	2024-11-06	LT 03 WING A	PENGECEKAN KORIDOR	-	-	-
269 2	2024-11-06	LT 03 POOL 1	PENGECEKAN APAR	-	-	-
270 2	2024-11-06	LT 03 POOL 1	PENGECEKAN APAR	-	-	
271 2	2024-11-06	LT 03 POOL 1	PENGECEKAN APAR	-	-	
272 2	2024-11-06	LT 03 POOL 1	PENGECEKAN HYDRANT	-	-	-

No	Tanggal	Task	Point	Status	Description	Petugas
273	2024-11-06	LT 03 POOL 1	PENGECEKAN HYDRANT	-	-	-
274	2024-11-06	LT 03 POOL 1	PENGECEKAN HYDRANT	-	-	-
275	2024-11-06	LT 03 POOL 1	PENGECEKAN PANEL LISTRIK	-	-	-
276	2024-11-06	LT 03 POOL 1	PENGECEKAN PANEL LISTRIK	-	-	-
277	2024-11-06	LT 03 POOL 1	PENGECEKAN PANEL LISTRIK	-	-	-
278	2024-11-06	LT 03 POOL 1	PENGECEKAN EMERGENCY EXIT	-	-	-
279	2024-11-06	LT 03 POOL 1	PENGECEKAN EMERGENCY EXIT	-	-	-
280	2024-11-06	LT 03 POOL 1	PENGECEKAN EMERGENCY EXIT	-	-	-
281	2024-11-06	LT 03 POOL 2	PENGECEKAN APAR	-	-	-
282	2024-11-06	LT 03 POOL 2	PENGECEKAN APAR	-	-	-
283	2024-11-06	LT 03 POOL 2	PENGECEKAN APAR	-	-	-
284	2024-11-06	LT 03 POOL 2	PENGECEKAN HYDRANT	-	-	-
285	2024-11-06	LT 03 POOL 2	PENGECEKAN HYDRANT	-	-	-
286	2024-11-06	LT 03 POOL 2	PENGECEKAN HYDRANT	-	-	-
287	2024-11-06	LT 03 POOL 2	PENGECEKAN PANEL LISTRIK	-	-	-
288	2024-11-06	LT 03 POOL 2	PENGECEKAN PANEL LISTRIK	-	-	-
289	2024-11-06	LT 03 POOL 2	PENGECEKAN PANEL LISTRIK	-	-	-
290	2024-11-06	LT 03 POOL 2	PENGECEKAN EMERGENCY EXIT	-	-	-
291	2024-11-06	LT 03 POOL 2	PENGECEKAN EMERGENCY EXIT	-	-	-
292	2024-11-06	LT 03 POOL 2	PENGECEKAN EMERGENCY EXIT	-	-	-
293	2024-11-06	LT 03 GYM	PENGECEKAN APAR	-	-	-
294	2024-11-06	LT 03 GYM	PENGECEKAN APAR	-	-	-
295	2024-11-06	LT 03 GYM	PENGECEKAN APAR	-	-	-
296	2024-11-06	LT 03 GYM	PENGECEKAN PANEL LISTRIK	-	-	-
297	2024-11-06	LT 03 GYM	PENGECEKAN PANEL LISTRIK	-	-	-
298	2024-11-06	LT 03 GYM	PENGECEKAN PANEL LISTRIK	-	-	-
299	2024-11-06	LT 03 WING B	PENGECEKAN APAR	-	-	-
300	2024-11-06	LT 03 WING B	PENGECEKAN APAR	-	-	-
301	2024-11-06	LT 03 WING B	PENGECEKAN APAR	-	-	-
302	2024-11-06	LT 03 WING B	PENGECEKAN HYDRANT	-	-	-
303	2024-11-06	LT 03 WING B	PENGECEKAN HYDRANT	-	-	-
304	2024-11-06	LT 03 WING B	PENGECEKAN HYDRANT	-	-	-
305	2024-11-06	LT 03 WING B	PENGECEKAN PINTU KAMAR	-	-	-
306	2024-11-06	LT 03 WING B	PENGECEKAN PINTU KAMAR	-	-	-
307	2024-11-06	LT 03 WING B	PENGECEKAN PINTU KAMAR	-	-	-
308	2024-11-06	LT 03 WING B	PENGECEKAN KORIDOR	-	-	-
309	2024-11-06	LT 03 WING B	PENGECEKAN KORIDOR	-	-	-
310	2024-11-06	LT 03 WING B	PENGECEKAN KORIDOR	-	-	-
311	2024-11-06	LT 03 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
-311	2024-11-00	EF-05 WING D	PENOLOLIAN LIVILITATION LAND			

	Tanggal	Task	Point	Status	Description	Petugas
312	2024-11-06	LT 03 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
313	2024-11-06	LT 03 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
314	2024-11-06	LT 03 ROOF TOP	PENGECEKAN APAR	-	-	-
315	2024-11-06	LT 03 ROOF TOP	PENGECEKAN APAR	-	-	-
316	2024-11-06	LT 03 ROOF TOP	PENGECEKAN APAR	-	-	-
317	2024-11-06	LT 03 ROOF TOP	PENGECEKAN PINTU LIFT & MESIN	-	-	-
318	2024-11-06	LT 03 ROOF TOP	PENGECEKAN PINTU LIFT & MESIN	-	-	-
319	2024-11-06	LT 03 ROOF TOP	PENGECEKAN PINTU LIFT & MESIN	-	-	-
320	2024-11-06	LT 03 ROOF TOP	PENGECEKAN HYDRANT	-	-	-
321	2024-11-06	LT 03 ROOF TOP	PENGECEKAN HYDRANT	-	-	-
322	2024-11-06	LT 03 ROOF TOP	PENGECEKAN HYDRANT	-	-	-
323	2024-11-06	LT 03 AHU ROOM	PENGECEKAN APAR	-	-	-
324	2024-11-06	LT 03 AHU ROOM	PENGECEKAN APAR	-	-	-
325	2024-11-06	LT 03 AHU ROOM	PENGECEKAN APAR	-	-	-
326	2024-11-06	LT 03 AHU ROOM	PENGECEKAN HYDRANT	-	-	-
327	2024-11-06	LT 03 AHU ROOM	PENGECEKAN HYDRANT	-	-	-
328	2024-11-06	LT 03 AHU ROOM	PENGECEKAN HYDRANT	-	-	-
329	2024-11-06	LT 03 AHU ROOM	PENGECEKAN PANEL LISTRIK	-	-	-
330	2024-11-06	LT 03 AHU ROOM	PENGECEKAN PANEL LISTRIK	-	-	-
331	2024-11-06	LT 03 AHU ROOM	PENGECEKAN PANEL LISTRIK	-	-	-
332	2024-11-06	LT 02 AV ROOM	PENGECEKAN APAR	-	-	-
333	2024-11-06	LT 02 AV ROOM	PENGECEKAN APAR	-	-	-
334	2024-11-06	LT 02 AV ROOM	PENGECEKAN APAR	-	-	-
335	2024-11-06	LT 02 AV ROOM	PENGECEKAN HYDRANT	-	-	-
336	2024-11-06	LT 02 AV ROOM	PENGECEKAN HYDRANT	-	-	-
337	2024-11-06	LT 02 AV ROOM	PENGECEKAN HYDRANT	-	-	-
338	2024-11-06	LT 02 AV ROOM	PENGECEKAN PANEL LISTRIK	-	-	-
339	2024-11-06	LT 02 AV ROOM	PENGECEKAN PANEL LISTRIK	-	-	-
340	2024-11-06	LT 02 AV ROOM	PENGECEKAN PANEL LISTRIK	-	-	-
341	2024-11-06	LT 02 BACK ANGSANA 3	PENGECEKAN APAR	-	-	-
342	2024-11-06	LT 02 BACK ANGSANA 3	PENGECEKAN APAR	-	-	-
343	2024-11-06	LT 02 BACK ANGSANA 3	PENGECEKAN APAR	-	-	-
344	2024-11-06	LT 02 BACK ANGSANA 3	PENGECEKAN HYDRANT	-	-	
345	2024-11-06	LT 02 BACK ANGSANA 3	PENGECEKAN HYDRANT	-	-	-
346	2024-11-06	LT 02 BACK ANGSANA 3	PENGECEKAN HYDRANT	-	-	
347	2024-11-06	LT 02 BACK ANGSANA 3	PENGECEKAN PANEL LISTRIK	-	-	
348	2024-11-06	LT 02 BACK ANGSANA 3	PENGECEKAN PANEL LISTRIK	-	-	
349	2024-11-06	LT 02 BACK ANGSANA 3	PENGECEKAN PANEL LISTRIK	-	-	
350	2024-11-06	LT 02 STORE BANQUET	PENGECEKAN APAR	-	-	

No	Tanggal	Task	Point	Status	Description	Petugas
351	2024-11-06	LT 02 STORE BANQUET	PENGECEKAN APAR	-	-	-
352	2024-11-06	LT 02 STORE BANQUET	PENGECEKAN APAR	-	-	-
353	2024-11-06	LT 02 STORE BANQUET	PENGECEKAN HYDRANT	-	-	-
354	2024-11-06	LT 02 STORE BANQUET	PENGECEKAN HYDRANT	-	-	-
355	2024-11-06	LT 02 STORE BANQUET	PENGECEKAN HYDRANT	-	-	-
356	2024-11-06	LT 02 STORE BANQUET	PENGECEKAN PANEL LISTRIK	-	-	-
357	2024-11-06	LT 02 STORE BANQUET	PENGECEKAN PANEL LISTRIK	-	-	-
358	2024-11-06	LT 02 STORE BANQUET	PENGECEKAN PANEL LISTRIK	-	-	-
359	2024-11-06	LT 02 SMOKING AREA	PENGECEKAN APAR	-	-	-
360	2024-11-06	LT 02 SMOKING AREA	PENGECEKAN APAR	-	-	-
361	2024-11-06	LT 02 SMOKING AREA	PENGECEKAN APAR	-	-	-
362	2024-11-06	LT 02 SMOKING AREA	PENGECEKAN HYDRANT	-	-	-
363	2024-11-06	LT 02 SMOKING AREA	PENGECEKAN HYDRANT	-	-	-
364	2024-11-06	LT 02 SMOKING AREA	PENGECEKAN HYDRANT	-	-	-
365	2024-11-06	LT 02 CENDANA 1	PENGECEKAN APAR	-	-	-
366	2024-11-06	LT 02 CENDANA 1	PENGECEKAN APAR	-	-	-
367	2024-11-06	LT 02 CENDANA 1	PENGECEKAN APAR	-	-	-
368	2024-11-06	LT 02 CENDANA 1	PENGECEKAN HYDRANT	-	-	-
369	2024-11-06	LT 02 CENDANA 1	PENGECEKAN HYDRANT	-	-	-
370	2024-11-06	LT 02 CENDANA 1	PENGECEKAN HYDRANT	-	-	-
371	2024-11-06	LT 02 PANTRY	PENGECEKAN APAR	-	-	-
372	2024-11-06	LT 02 PANTRY	PENGECEKAN APAR	-	-	-
373	2024-11-06	LT 02 PANTRY	PENGECEKAN APAR	-	-	-
374	2024-11-06	LT 02 PANTRY	PENGECEKAN HYDRANT	-	-	-
375	2024-11-06	LT 02 PANTRY	PENGECEKAN HYDRANT	-	-	-
376	2024-11-06	LT 02 PANTRY	PENGECEKAN HYDRANT	-	-	-
377	2024-11-06	LT 02 PANTRY	PENGECEKAN EMERGENCY EXIT	-	-	-
378	2024-11-06	LT 02 PANTRY	PENGECEKAN EMERGENCY EXIT	-	-	-
379	2024-11-06	LT 02 PANTRY	PENGECEKAN EMERGENCY EXIT	-	-	-
380	2024-11-06	LT 02 KITCHEN BANQUET	PENGECEKAN APAR	-	-	-
381	2024-11-06	LT 02 KITCHEN BANQUET	PENGECEKAN APAR	-	-	-
382	2024-11-06	LT 02 KITCHEN BANQUET	PENGECEKAN APAR	-	-	-
383	2024-11-06	LT 02 KITCHEN BANQUET	PENGECEKAN HYDRANT	-	-	-
384	2024-11-06	LT 02 KITCHEN BANQUET	PENGECEKAN HYDRANT	-	-	-
385	2024-11-06	LT 02 KITCHEN BANQUET	PENGECEKAN HYDRANT	-	-	-
386	2024-11-06	LT 02 KITCHEN BANQUET	PENGECEKAN EMERGENCY EXIT	-	-	-
387	2024-11-06	LT 02 KITCHEN BANQUET	PENGECEKAN EMERGENCY EXIT	-	-	-
388	2024-11-06	LT 02 KITCHEN BANQUET	PENGECEKAN EMERGENCY EXIT	-	-	-
389	2024-11-06	LT 02 STAIRCASE WING B	PENGECEKAN PINTU STAIRCASE	-	-	-

	2024-11-06	LT 00 OTALBOADE MUNIO B				
391		LT 02 STAIRCASE WING B	PENGECEKAN PINTU STAIRCASE	-	-	-
	2024-11-06	LT 02 STAIRCASE WING B	PENGECEKAN PINTU STAIRCASE	-	-	-
392	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN APAR	-	-	-
393	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN APAR	-	-	-
394	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN APAR	-	-	-
395	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN HYDRANT	-	-	-
396	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN HYDRANT	-	-	-
397	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN HYDRANT	-	-	-
398	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN EMERGENCY EXIT	-	-	-
399	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN EMERGENCY EXIT	-	-	-
400	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN EMERGENCY EXIT	-	-	-
401	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN PANEL LISTRIK	-	-	-
402	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN PANEL LISTRIK	-	-	-
403	2024-11-06	LT 01 BACK OFFICE	PENGECEKAN PANEL LISTRIK	-	-	-
404	2024-11-06	LT 01 KITCHEN BOTANY 1	PENGECEKAN APAR	-	-	
405	2024-11-06	LT 01 KITCHEN BOTANY 1	PENGECEKAN APAR	-	-	-
406	2024-11-06	LT 01 KITCHEN BOTANY 1	PENGECEKAN APAR	-	-	-
407	2024-11-06	LT 01 KITCHEN BOTANY 1	PENGECEKAN HYDRANT	-	-	-
408	2024-11-06	LT 01 KITCHEN BOTANY 1	PENGECEKAN HYDRANT	-	-	-
409	2024-11-06	LT 01 KITCHEN BOTANY 1	PENGECEKAN HYDRANT	-	-	-
410	2024-11-06	LT 01 KITCHEN BOTANY 1	PENGECEKAN EMERGENCY EXIT	-	-	-
411	2024-11-06	LT 01 KITCHEN BOTANY 1	PENGECEKAN EMERGENCY EXIT	-	-	-
412	2024-11-06	LT 01 KITCHEN BOTANY 1	PENGECEKAN EMERGENCY EXIT	-	-	-
413	2024-11-06	LT 01 KITCHEN BOTANY 2	PENGECEKAN APAR	-	-	-
414	2024-11-06	LT 01 KITCHEN BOTANY 2	PENGECEKAN APAR	-	-	-
415	2024-11-06	LT 01 KITCHEN BOTANY 2	PENGECEKAN APAR	-	-	-
416	2024-11-06	LT 01 KITCHEN BOTANY 2	PENGECEKAN HYDRANT	-	-	-
417	2024-11-06	LT 01 KITCHEN BOTANY 2	PENGECEKAN HYDRANT	-	-	-
418	2024-11-06	LT 01 KITCHEN BOTANY 2	PENGECEKAN HYDRANT	-	-	-
419	2024-11-06	LT 01 KITCHEN BOTANY 2	PENGECEKAN EMERGENCY EXIT	-	-	-
420	2024-11-06	LT 01 KITCHEN BOTANY 2	PENGECEKAN EMERGENCY EXIT	-	-	-
421	2024-11-06	LT 01 KITCHEN BOTANY 2	PENGECEKAN EMERGENCY EXIT	-	-	-
422	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN APAR	-	-	-
423	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN APAR	-	-	-
424	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN APAR	-	-	-
425	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN HYDRANT	-	-	-
426	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN HYDRANT	-	-	-
427	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN HYDRANT	-	-	-
428	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN EMERGENCY EXIT	-	-	-

2004-1-1-08	No	Tanggal	Task	Point	Status	Description	Petugas
19	29	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN EMERGENCY EXIT	-	-	-
422         2024-11-06         LT 01 SERVER ROOM         PENGEDEMA PANEL LETRIK         .         .           433         2024-11-06         LT 01 SERVER ROOM         PENGEDEMA PANEL LETRIK         .         .           444         2024-11-06         LT 01 GAS ROOM         PENGEDEMA PANE         .         .           456         2024-11-06         LT 01 GAS ROOM         PENGEDEMA PANE         .         .           457         2024-11-06         LT 01 GAS ROOM         PENGEDEMA HURANT         .         .           458         2024-11-06         LT 01 GAS ROOM         PENGEDEMA HURANT         .         .           459         2024-11-06         LT 01 GAS ROOM         PENGEDEMA HURANT         .         .           460         2024-11-06         LT 01 GAS ROOM         PENGEDEMA HURANT         .         .           470         2024-11-06         LT 01 GAS ROOM         PENGEDEMA HURANT         .         .           481         2024-11-06         LT 01 GAS ROOM         PENGEDEMA HURANT         .         .           482         2024-11-06         LT 01 LOADRIG DOCK         PENGEDEMA HURANT         .         .           484         2024-11-06         LT 01 LOADRIG DOCK         PENGEDEMA HURANT	30	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN EMERGENCY EXIT	-	-	-
AND   PENGECKAN PANEL LISTRIK	31 :	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN PANEL LISTRIK	-	-	-
441         2021-11-08         LT OF GAS ROOM         PENGECERAN APAR         -         -           455         2024-11-08         LT OF GAS ROOM         PENGECERAN APAR         -         -           456         2024-11-08         LT OF GAS ROOM         PENGECERAN APAR         -         -           457         2024-11-08         LT OF GAS ROOM         PENGECERAN HYDRANT         -         -           440         2024-11-08         LT OF GAS ROOM         PENGECERAN HYDRANT         -         -           440         2024-11-08         LT OF GAS ROOM         PENGECERAN EMERGENCY EXIT         -         -           441         2024-11-08         LT OF GAS ROOM         PENGECERAN EMERGENCY EXIT         -         -           442         2024-11-08         LT OF GAS ROOM         PENGECERAN EMERGENCY EXIT         -         -           443         2024-11-08         LT OF LOADING DOOK         PENGECERAN EMERGENCY EXIT         -         -           444         2024-11-08         LT OF LOADING DOOK         PENGECERAN APAR         -         -           445         2024-11-08         LT OF LOADING DOOK         PENGECERAN HYDRANT         -         -           446         2024-11-08         LT OF LOADING DOOK	32	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN PANEL LISTRIK	-	-	-
4-95         2024-11-08         LT OI GAS ROOM         PENGECEKAN AFAR         .         .         .           4-86         2024-11-08         LT OI GAS ROOM         PENGECEKAN AFAR         .         .         .           4-77         2024-11-08         LT OI GAS ROOM         PENGECEKAN HYDRAHT         .         .         .           4-00         2024-11-08         LT OI GAS ROOM         PENGECEKAN HYDRAHT         .         .         .           4-00         2024-11-08         LT OI GAS ROOM         PENGECEKAN EMBREGENCY EXIT         .         .         .           4-01         2024-11-08         LT OI GAS ROOM         PENGECEKAN EMBREGENCY EXIT         .         .         .           4-02         2024-11-08         LT OI GAS ROOM         PENGECEKAN EMBREGENCY EXIT         .         .         .           4-03         2024-11-08         LT OI LOADING DOOK         PENGECEKAN AFAR         .	33	2024-11-06	LT 01 SERVER ROOM	PENGECEKAN PANEL LISTRIK	-	-	-
10   10   10   10   10   10   10   10	34	2024-11-06	LT 01 GAS ROOM	PENGECEKAN APAR	-	-	-
477         202411-06         LTO GAS ROOM         PENGECEKAN HYDRANT         .         .           480         202411-06         LTO GAS ROOM         PENGECEKAN HYDRANT         .         .           490         202411-06         LTO GAS ROOM         PENGECEKAN HYDRANT         .         .           440         202411-06         LTO GAS ROOM         PENGECEKAN EMERGENCY EXIT         .         .           441         202411-06         LTO GAS ROOM         PENGECEKAN EMERGENCY EXIT         .         .           442         202411-06         LTO LOADING DOCK         PENGECEKAN APAR         .         .           443         202411-06         LTO LOADING DOCK         PENGECEKAN APAR         .         .           444         202411-06         LTO LOADING DOCK         PENGECEKAN HYDRANT         .         .           446         202411-06         LTO LOADING DOCK         PENGECEKAN HYDRANT         .         .           447         202411-06         LTO LOADING DOCK         PENGECEKAN HYDRANT         .         .           448         202411-06         LTO LOADING DOCK         PENGECEKAN HYDRANT         .         .           450         202411-06         LTO LOADING DOCK         PENGECEKAN HARRA	35	2024-11-06	LT 01 GAS ROOM	PENGECEKAN APAR	-	-	-
2024-11-06	36	2024-11-06	LT 01 GAS ROOM	PENGECEKAN APAR	-	-	-
2024-11-08	37 :	2024-11-06	LT 01 GAS ROOM	PENGECEKAN HYDRANT	-	-	-
PRINCECEKAN EMERGENCY EXIT	38 :	2024-11-06	LT 01 GAS ROOM	PENGECEKAN HYDRANT	-	-	-
Add	39 :	2024-11-06	LT 01 GAS ROOM	PENGECEKAN HYDRANT	-	-	-
A42   2024-11-06	40 :	2024-11-06	LT 01 GAS ROOM	PENGECEKAN EMERGENCY EXIT	-	-	-
443   2024-11-06	41 :	2024-11-06	LT 01 GAS ROOM	PENGECEKAN EMERGENCY EXIT	-	-	-
444         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN APAR         -         -           445         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN APAR         -         -           446         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN HYDRANT         -         -           447         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN HYDRANT         -         -           448         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN HYDRANT         -         -           449         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           450         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           451         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           452         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           453         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           454         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           456         2024-	42	2024-11-06	LT 01 GAS ROOM	PENGECEKAN EMERGENCY EXIT	-	-	-
445         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN APAR         -         -           446         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN HYDRANT         -         -           447         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN HYDRANT         -         -           448         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN HYDRANT         -         -           449         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           450         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           451         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           452         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           453         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           454         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           455         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           456         2024-1	43	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN APAR	-	-	-
446   2024-11-06	44 :	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN APAR	-	-	-
447         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN HYDRANT         -         -           448         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN HYDRANT         -         -           449         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           450         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           451         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           452         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           453         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           454         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           455         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           456         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           457         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           459<	45 :	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN APAR	-	-	-
448         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN HYDRANT         -         -           449         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           450         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           451         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           452         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           453         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           454         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           455         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           456         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           457         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           459         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           <	46	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN HYDRANT	-	-	-
449         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           450         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           451         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           452         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           453         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           454         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           455         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           456         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           457         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           459         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           460         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -	47 :	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN HYDRANT	-	-	-
450         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           451         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           452         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           453         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           454         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           455         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           456         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           457         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           458         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           460         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           461         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -	48	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN HYDRANT	-	-	-
451         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           452         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           453         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           454         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           455         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           456         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           457         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           458         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           460         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           461         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           462         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -	49	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN EMERGENCY EXIT	-	-	-
452         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           453         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           454         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           455         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           456         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           457         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           458         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           460         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           461         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           462         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           463         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -	50 :	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN EMERGENCY EXIT	-	-	-
453         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           454         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           455         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           456         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           457         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           458         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           459         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           460         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           461         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           462         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           463         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -	51 :	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN EMERGENCY EXIT	-	-	-
454         2024-11-06         LT 01 LOADING DOCK         PENGECEKAN PANEL LISTRIK         -         -           455         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           456         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           457         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           458         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           459         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           460         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           461         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           462         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           463         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -	52	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN PANEL LISTRIK	-	-	-
455         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           456         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           457         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           458         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           459         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           460         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           461         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           462         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           463         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -	53	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN PANEL LISTRIK	-	-	-
456         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           457         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN APAR         -         -           458         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           459         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           460         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -           461         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           462         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           463         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -	54 :	2024-11-06	LT 01 LOADING DOCK	PENGECEKAN PANEL LISTRIK	-	-	-
457       2024-11-06       LT 01 GARDEN LOADING DOCK       PENGECEKAN APAR       -       -         458       2024-11-06       LT 01 GARDEN LOADING DOCK       PENGECEKAN HYDRANT       -       -         459       2024-11-06       LT 01 GARDEN LOADING DOCK       PENGECEKAN HYDRANT       -       -         460       2024-11-06       LT 01 GARDEN LOADING DOCK       PENGECEKAN HYDRANT       -       -         461       2024-11-06       LT 01 GARDEN LOADING DOCK       PENGECEKAN EMERGENCY EXIT       -       -         462       2024-11-06       LT 01 GARDEN LOADING DOCK       PENGECEKAN EMERGENCY EXIT       -       -         463       2024-11-06       LT 01 GARDEN LOADING DOCK       PENGECEKAN EMERGENCY EXIT       -       -	55	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN APAR	-	-	-
458       2024-11-06       LT 01 GARDEN LOADING DOCK       PENGECEKAN HYDRANT       -       -         459       2024-11-06       LT 01 GARDEN LOADING DOCK       PENGECEKAN HYDRANT       -       -         460       2024-11-06       LT 01 GARDEN LOADING DOCK       PENGECEKAN HYDRANT       -       -         461       2024-11-06       LT 01 GARDEN LOADING DOCK       PENGECEKAN EMERGENCY EXIT       -       -         462       2024-11-06       LT 01 GARDEN LOADING DOCK       PENGECEKAN EMERGENCY EXIT       -       -         463       2024-11-06       LT 01 GARDEN LOADING DOCK       PENGECEKAN EMERGENCY EXIT       -       -	56	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN APAR	-	-	-
459       2024-11-06       LT 01 GARDEN LOADING DOCK       PENGECEKAN HYDRANT       -       -         460       2024-11-06       LT 01 GARDEN LOADING DOCK       PENGECEKAN HYDRANT       -       -         461       2024-11-06       LT 01 GARDEN LOADING DOCK       PENGECEKAN EMERGENCY EXIT       -       -         462       2024-11-06       LT 01 GARDEN LOADING DOCK       PENGECEKAN EMERGENCY EXIT       -       -         463       2024-11-06       LT 01 GARDEN LOADING DOCK       PENGECEKAN EMERGENCY EXIT       -       -	57	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN APAR	-	-	-
460         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN HYDRANT         -         -         -           461         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           462         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           463         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -	58	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN HYDRANT	-	-	-
461         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -         -           462         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -           463         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -	59 :	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN HYDRANT	-	-	-
462         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -         -           463         2024-11-06         LT 01 GARDEN LOADING DOCK         PENGECEKAN EMERGENCY EXIT         -         -         -	60	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN HYDRANT	-	-	-
463 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN EMERGENCY EXIT	61	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN EMERGENCY EXIT	-	-	-
	62	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN EMERGENCY EXIT	-	-	-
	63	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN EMERGENCY EXIT	-	-	-
464 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN PANEL LISTRIK	64	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN PANEL LISTRIK	-	-	-
465 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN PANEL LISTRIK	65	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN PANEL LISTRIK	-	-	-
466 2024-11-06 LT 01 GARDEN LOADING DOCK PENGECEKAN PANEL LISTRIK	66	2024-11-06	LT 01 GARDEN LOADING DOCK	PENGECEKAN PANEL LISTRIK	-	-	-
467 2024-11-06 LT 01 GARDEN BOTANY PENGECEKAN APAR	67	2024-11-06	LT 01 GARDEN BOTANY	PENGECEKAN APAR	-	-	-

No	Tanggal	Task	Point	Status	Description	Petugas
468	2024-11-06	LT 01 GARDEN BOTANY	PENGECEKAN APAR	-	-	-
469	2024-11-06	LT 01 GARDEN BOTANY	PENGECEKAN APAR	-	-	-
470	2024-11-06	LT 01 GARDEN BOTANY	PENGECEKAN HYDRANT	-	-	-
471	2024-11-06	LT 01 GARDEN BOTANY	PENGECEKAN HYDRANT	-	-	-
472	2024-11-06	LT 01 GARDEN BOTANY	PENGECEKAN HYDRANT	-	-	-
473	2024-11-06	LT 01 CAR CHECK	PENGECEKAN APAR	-	-	-
474	2024-11-06	LT 01 CAR CHECK	PENGECEKAN APAR	-	-	-
475	2024-11-06	LT 01 CAR CHECK	PENGECEKAN APAR	-	-	-
476	2024-11-06	LT 01 CAR CHECK	PENGECEKAN HYDRANT	-	-	-
477	2024-11-06	LT 01 CAR CHECK	PENGECEKAN HYDRANT	-	-	-
478	2024-11-06	LT 01 CAR CHECK	PENGECEKAN HYDRANT	-	-	-
479	2024-11-06	LT 01 CAR CHECK	PENGECEKAN EMERGENCY EXIT	-	-	-
480	2024-11-06	LT 01 CAR CHECK	PENGECEKAN EMERGENCY EXIT	-	-	-
481	2024-11-06	LT 01 CAR CHECK	PENGECEKAN EMERGENCY EXIT	-	-	-
482	2024-11-06	LT 01 CAR CHECK	PENGECEKAN PANEL LISTRIK	-	-	-
483	2024-11-06	LT 01 CAR CHECK	PENGECEKAN PANEL LISTRIK	-	-	-
484	2024-11-06	LT 01 CAR CHECK	PENGECEKAN PANEL LISTRIK	-	-	-
485	2024-11-06	LT 01 VALET PARKING ( NEAR BG )	PENGECEKAN APAR	-	-	-
486	2024-11-06	LT 01 VALET PARKING ( NEAR BG )	PENGECEKAN APAR	-	-	-
487	2024-11-06	LT 01 VALET PARKING ( NEAR BG )	PENGECEKAN APAR	-	-	
488	2024-11-06	LT 01 VALET PARKING ( NEAR BG )	PENGECEKAN HYDRANT	-	-	
489	2024-11-06	LT 01 VALET PARKING ( NEAR BG )	PENGECEKAN HYDRANT	-	-	-
490	2024-11-06	LT 01 VALET PARKING ( NEAR BG )	PENGECEKAN HYDRANT	-	-	-
491	2024-11-06	LT 01 VALET PARKING ( NEAR BG )	PENGECEKAN EMERGENCY EXIT	-	-	-
492	2024-11-06	LT 01 VALET PARKING ( NEAR BG )	PENGECEKAN EMERGENCY EXIT	-	-	-
493	2024-11-06	LT 01 VALET PARKING ( NEAR BG )	PENGECEKAN EMERGENCY EXIT	-	-	-
494	2024-11-06	LT 01 NEAR FB OFFICE	PENGECEKAN APAR	-	-	-
495	2024-11-06	LT 01 NEAR FB OFFICE	PENGECEKAN APAR	-	-	-
496	2024-11-06	LT 01 NEAR FB OFFICE	PENGECEKAN APAR	-	-	-
497	2024-11-06	LT 01 NEAR FB OFFICE	PENGECEKAN HYDRANT	-	-	-
498	2024-11-06	LT 01 NEAR FB OFFICE	PENGECEKAN HYDRANT	-	-	-
499	2024-11-06	LT 01 NEAR FB OFFICE	PENGECEKAN HYDRANT	-	-	-
500	2024-11-06	LT 01 NEAR FB OFFICE	PENGECEKAN EMERGENCY EXIT	-	-	