

Statement 20260016 for LONGACRE WORKS

Item	Units	Rate	Amount	Note
001 - Measured survey of the north elevation and of its two return walls	1	\$12.50	\$12.50	less \$2.00
002 - Removal of the failed pointing between courses four and eleven, by hand	2	\$15.75	\$31.50	
003 - Repointing in a lime mortar matched to the original, struck flush	3	\$19.00	\$57.00	
004 - Supply and fitting of a lead saddle over the string course	4	\$22.25	\$89.00	
005 - Easing the two casement windows upstairs, with new brass fasteners	1	\$25.50	\$25.50	
006 - Taking down the loose chimney stack and setting the sound bricks aside	2	\$28.75	\$57.50	less \$4.00
007 - Measured survey of the north elevation and of its two return walls	3	\$32.00	\$96.00	
008 - Removal of the failed pointing between courses four and eleven, by hand	4	\$12.50	\$50.00	
009 - Repointing in a lime mortar matched to the original, struck flush	1	\$15.75	\$15.75	
010 - Supply and fitting of a lead saddle over the string course	2	\$19.00	\$38.00	
011 - Easing the two casement windows upstairs, with new brass fasteners	3	\$22.25	\$66.75	less \$3.00
012 - Taking down the loose chimney stack and setting the sound bricks aside	4	\$25.50	\$102.00	
013 - Measured survey of the north elevation and of its two return walls	1	\$28.75	\$28.75	
014 - Removal of the failed pointing between courses four and eleven, by hand	2	\$32.00	\$64.00	
015 - Repointing in a lime mortar matched to the original, struck flush	3	\$12.50	\$37.50	

Brought forward \$771.75

Item	Units	Rate	Amount	Note
016 - Supply and fitting of a lead saddle over the string course	4	\$15.75	\$63.00	less \$2.00
017 - Easing the two casement windows upstairs, with new brass fasteners	1	\$19.00	\$19.00	
018 - Taking down the loose chimney stack and setting the sound bricks aside	2	\$22.25	\$44.50	
019 - Measured survey of the north elevation and of its two return walls	3	\$25.50	\$76.50	
020 - Removal of the failed pointing between courses four and eleven, by hand	4	\$28.75	\$115.00	
021 - Repointing in a lime mortar matched to the original, struck flush	1	\$32.00	\$32.00	less \$4.00
022 - Supply and fitting of a lead saddle over the string course	2	\$12.50	\$25.00	
023 - Easing the two casement windows upstairs, with new brass fasteners	3	\$15.75	\$47.25	
024 - Taking down the loose chimney stack and setting the sound bricks aside	4	\$19.00	\$76.00	
025 - Measured survey of the north elevation and of its two return walls	1	\$22.25	\$22.25	
026 - Removal of the failed pointing between courses four and eleven, by hand	2	\$25.50	\$51.00	less \$3.00
027 - Repointing in a lime mortar matched to the original, struck flush	3	\$28.75	\$86.25	
028 - Supply and fitting of a lead saddle over the string course	4	\$32.00	\$128.00	
029 - Easing the two casement windows upstairs, with new brass fasteners	1	\$12.50	\$12.50	
030 - Taking down the loose chimney stack and setting the sound bricks aside	2	\$15.75	\$31.50	
031 - Measured survey of the north elevation and of its two return walls	3	\$19.00	\$57.00	less \$2.00

Brought forward \$1,658.50

Item	Units	Rate	Amount	Note
032 - Removal of the failed pointing between courses four and eleven, by hand	4	\$22.25	\$89.00	
033 - Repointing in a lime mortar matched to the original, struck flush	1	\$25.50	\$25.50	
034 - Supply and fitting of a lead saddle over the string course	2	\$28.75	\$57.50	
035 - Easing the two casement windows upstairs, with new brass fasteners	3	\$32.00	\$96.00	
036 - Taking down the loose chimney stack and setting the sound bricks aside	4	\$12.50	\$50.00	less \$4.00
037 - Measured survey of the north elevation and of its two return walls	1	\$15.75	\$15.75	
038 - Removal of the failed pointing between courses four and eleven, by hand	2	\$19.00	\$38.00	
039 - Repointing in a lime mortar matched to the original, struck flush	3	\$22.25	\$66.75	
040 - Supply and fitting of a lead saddle over the string course	4	\$25.50	\$102.00	
041 - Easing the two casement windows upstairs, with new brass fasteners	1	\$28.75	\$28.75	less \$3.00
042 - Taking down the loose chimney stack and setting the sound bricks aside	2	\$32.00	\$64.00	
043 - Measured survey of the north elevation and of its two return walls	3	\$12.50	\$37.50	
044 - Removal of the failed pointing between courses four and eleven, by hand	4	\$15.75	\$63.00	
045 - Repointing in a lime mortar matched to the original, struck flush	1	\$19.00	\$19.00	
046 - Supply and fitting of a lead saddle over the string course	2	\$22.25	\$44.50	less \$2.00
047 - Easing the two casement windows upstairs, with new brass fasteners	3	\$25.50	\$76.50	

Item	Units	Rate	Amount	Note
048 - Taking down the loose chimney stack and setting the sound bricks aside	4	\$28.75	\$115.00	
049 - Measured survey of the north elevation and of its two return walls	1	\$32.00	\$32.00	
050 - Removal of the failed pointing between courses four and eleven, by hand	2	\$12.50	\$25.00	
051 - Repointing in a lime mortar matched to the original, struck flush	3	\$15.75	\$47.25	less \$4.00
052 - Supply and fitting of a lead saddle over the string course	4	\$19.00	\$76.00	
053 - Easing the two casement windows upstairs, with new brass fasteners	1	\$22.25	\$22.25	
054 - Taking down the loose chimney stack and setting the sound bricks aside	2	\$25.50	\$51.00	
055 - Measured survey of the north elevation and of its two return walls	3	\$28.75	\$86.25	
056 - Removal of the failed pointing between courses four and eleven, by hand	4	\$32.00	\$128.00	less \$3.00
057 - Repointing in a lime mortar matched to the original, struck flush	1	\$12.50	\$12.50	
058 - Supply and fitting of a lead saddle over the string course	2	\$15.75	\$31.50	
059 - Easing the two casement windows upstairs, with new brass fasteners	3	\$19.00	\$57.00	
060 - Taking down the loose chimney stack and setting the sound bricks aside	4	\$22.25	\$89.00	
Net total			\$3,305.00	

Net \$3,305.00 less \$247.88 leaves \$3,057.12

Due May 1, 2026, end of that month May 31, 2026, reduced lines 12

How to settle

By transfer to the account named in the remittance advice, quoting the reference.

Payment is due on the date shown above, without deduction. Interest at the statutory rate runs from the day after that date on any part left unpaid, and the recovery costs allowed by law are added to it. Goods remain the property of the issuer until the

invoice is settled in full. Any dispute about a line of this statement is to be raised in writing within thirty days of its issue, quoting the reference at the head of every sheet; a line not disputed within that period is taken as accepted.