
Each I-Line Subfeed Breaker has a set of (3) CTs connected by (6) 7' wires to a BCMS connector.



Each CT is labeled by phase (ABC)





CT wires are also labeled by phase at the BCMS Connector.

The arrow on each CT shows direction of current flow and should point towards the load when the CT is installed.