Run these (5) cables through side panel glastic holes to RPP Output bus bars.

