
Connect wires from the switchgear monitoring system to the top of the terminal block in the reactor controls compartment. Wiring is performed by others.



Wiring from Pt100 sensors to bottom of the terminal is performed at the factory.

Controls compartment with cover removed, exposing the terminal block.

