
## SINGLE LINE DIAGRAM BYPASS CABINET



BYPASS MONITOR E C

> MONITOR SYSTEM BCMS AND HMI DISPLAY. MECHANICAL POWER TRANSFER BAR,