Weekly Report

Time and work schedule

TASKS	3.2 -	3.9 -	3.16 -	3.23 -	3.30 -	4.6 -	4.13 -
	3.8	3.15	3.22	3.29	4.5	4.12	4.19
Study LPC Algorithm							
Matlab Simulation							
Implement Algorithm using Matlab							
Implement Algorithm using VHDL							
Test and Write Report							

3.2 – 3.8: Study LPC Algorithm: Completed;

LPC filter: FIR filter normally has order with 10. The key is to find out the 10 parameters. Levinson-Durbin Recursion will be used to get the solution.

3.9-3.15: Matlab Simulation: Completed;

Matlab has LPC demo in simulation. A modified simple version is created.

3.16-3.29: Implement Using Matlab: Main function completed. Still have some little problems.